



Product Change Notification - SYST-10WTGX473

Date:

11 Dec 2019

Product Category:

16-Bit - Microcontrollers and Digital Signal Controllers

Affected CPNs:**Notification subject:**

ERRATA - PIC24F16KL402 Family Silicon/Data Sheet Errata

Notification text:

SYST-10WTGX473

Microchip has released a new Product Documents for the PIC24F16KL402 Family Silicon/Data Sheet Errata of devices. If you are using one of these devices please read the document located at [PIC24F16KL402 Family Silicon/Data Sheet Errata](#).

Notification Status: Final

Description of Change:

1) Removes data sheet clarifications that were addressed in current Device Data Sheet (DS30001037D).

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 11 Dec 2019

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[PIC24F16KL402 Family Silicon/Data Sheet Errata](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

PIC24F04KL100-E/ST
PIC24F04KL100-I/P
PIC24F04KL100-I/ST
PIC24F04KL100T-I/ST
PIC24F04KL101-E/MQ
PIC24F04KL101-E/SS
PIC24F04KL101-I/MQ
PIC24F04KL101-I/P
PIC24F04KL101-I/SS
PIC24F04KL101T-I/MQ
PIC24F04KL101T-I/SS
PIC24F08KL200-E/P
PIC24F08KL200-E/ST
PIC24F08KL200-I/P
PIC24F08KL200-I/ST
PIC24F08KL201-E/MQ
PIC24F08KL201-E/SS
PIC24F08KL201-I/MQ
PIC24F08KL201-I/P
PIC24F08KL201-I/SO
PIC24F08KL201-I/SS
PIC24F08KL201T-I/MQ
PIC24F08KL201T-I/SS
PIC24F08KL301-E/MQ
PIC24F08KL301-E/P
PIC24F08KL301-I/MQ
PIC24F08KL301-I/P
PIC24F08KL301-I/SO
PIC24F08KL301-I/SS
PIC24F08KL301T-I/MQ
PIC24F08KL301T-I/MQ020
PIC24F08KL301T-I/SS
PIC24F08KL302-E/ML
PIC24F08KL302-E/SO
PIC24F08KL302-E/SS
PIC24F08KL302-I/ML
PIC24F08KL302-I/MQ
PIC24F08KL302-I/SO
PIC24F08KL302-I/SP
PIC24F08KL302-I/SS
PIC24F08KL302T-I/MQ
PIC24F08KL302T-I/SS
PIC24F08KL401-E/MQ
PIC24F08KL401-I/MQ
PIC24F08KL401-I/P
PIC24F08KL401-I/SO

PIC24F08KL401-I/SS
PIC24F08KL401T-I/SS
PIC24F08KL402-E/SS
PIC24F08KL402-I/ML
PIC24F08KL402-I/MQ
PIC24F08KL402-I/SO
PIC24F08KL402-I/SP
PIC24F08KL402-I/SS
PIC24F08KL402T-I/SS
PIC24F16KL401-E/MQ
PIC24F16KL401-E/P
PIC24F16KL401-E/SO
PIC24F16KL401-E/SS
PIC24F16KL401-I/MQ
PIC24F16KL401-I/P
PIC24F16KL401-I/SO
PIC24F16KL401-I/SS
PIC24F16KL401T-E/SS
PIC24F16KL401T-I/MQ
PIC24F16KL401T-I/SO
PIC24F16KL401T-I/SS
PIC24F16KL402-E/MQ
PIC24F16KL402-E/SO
PIC24F16KL402-E/SP
PIC24F16KL402-E/SS
PIC24F16KL402-I/ML
PIC24F16KL402-I/MQ
PIC24F16KL402-I/SO
PIC24F16KL402-I/SP
PIC24F16KL402-I/SS
PIC24F16KL402T-E/SS
PIC24F16KL402T-I/ML
PIC24F16KL402T-I/MQ
PIC24F16KL402T-I/SS

PIC24F16KL402 Family Silicon Errata and Data Sheet Clarification

The PIC24F16KL402 family devices that you have received conform functionally to the current Device Data Sheet (DS30001037D), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).

The errata described in this document will be addressed in future revisions of the PIC24F16KL402 family silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (**A2**).

Data Sheet clarifications and corrections start on [Page 4](#), following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers, and emulation tools, which are available at the Microchip corporate website (www.microchip.com).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with MPLAB ICD 2 or PICKit™ 3:

1. Using the appropriate interface, connect the device to the MPLAB ICD 2 programmer/debugger or PICKit 3.
2. From the main menu in MPLAB IDE, select *Configure>Select Device* and then select the target part number in the dialog box.
3. Select the MPLAB hardware tool (*Debugger>Select Tool*).
4. Perform a "Connect" operation to the device (*Debugger>Connect*). Depending on the development tool used, the part number *and* Device Revision ID value appear in the **Output** window.

Note: If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC24F16KL402 family silicon revisions are shown in [Table 1](#).

TABLE 1: SILICON DEVREV VALUES

Part Number	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽²⁾			Part Number	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽²⁾		
		A0	A1	A2			A0	A1	A2
PIC24F04KL100	4B01h	0000h	0001h	0002h	PIC24F08KL302	4B00h	0000h	0001h	0002h
PIC24F04KL101	4B02h				PIC24F08KL401	4B0Eh			
PIC24F08KL200	4B05h				PIC24F08KL402	4B04h			
PIC24F08KL201	4B06h				PIC24F16KL401	4B1Eh			
PIC24F08KL301	4B0Ah				PIC24F16KL402	4B14h			

Note 1: The Device IDs (DEVID and DEVREV) are located at the last two implemented addresses of configuration memory space. They are shown in hexadecimal in the format "DEVID DEVREV".

2: Refer to the "PIC24FXXKMXXX/KLXXX Flash Programming Specifications" (DS30000625) for detailed information on Device and Revision IDs for your specific device.

PIC24F16KL402 FAMILY

TABLE 2: SILICON ISSUE SUMMARY

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾		
				A0	A1	A2
UART (Transmit)	Transmit	1.	UTXBF flag may not indicate correctly.	X		
Oscillator (REFO)	REFO	2.	REFO output unavailable at higher frequencies.	X	X	X
HLVD (Band Gap Reference)	Band Gap Reference	3.	BGVST and IRVST bits may not become set at extremely low temperatures.	X	X	X

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

PIC24F16KL402 FAMILY

Silicon Errata Issues

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (**A2**).

1. Module: UART (Transmit)

The Transmit Buffer Full Flag, UTXBF (UxSTA[9]), may become cleared before the data start moving out of the full buffer. If the flag is used to determine when data can be written to the buffer, new data may not be accepted and data may not be transmitted.

Work around

Poll the Transmit Buffer Empty Flag, TRMT (UxSTA[8]), to determine when the transmit buffer is empty and can be written to.

Alternatively, configure the UART to set the Transmit Interrupt Flag (UxTXIF) whenever a character is shifted into the Transmit Shift Register (UTXISEL[1:0] = 00). When a transmit interrupt occurs, this indicates that at least one buffer position is open and that the buffer can be written to.

Affected Silicon Revisions

A0	A1	A2						
X								

2. Module: Oscillator (REFO)

When output frequencies above 16 MHz are selected for the Reference Clock Output (REFO), the peak output voltage on the REFO pin may be too low to be properly detected by external devices.

Work around

None.

Affected Silicon Revisions

A0	A1	A2						
X	X	X						

3. Module: HLVD (Band Gap Reference)

At the extreme low end of the operating temperature range (near -40°C), the BGVST and IRVST flag bits (HLVDCON[6,5]) may not become set when the voltage references are stable and ready to use.

Work around

For applications that run at extremely cold temperatures, do not use the BGVST and IRVST bits as the sole indicator of band gap readiness. Include a time-out of 750 µs between enabling and using a reference.

Affected Silicon Revisions

A0	A1	A2						
X	X	X						

PIC24F16KL402 FAMILY

Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS30001037D):

<p>Note: Corrections and additions are shown in bold. Where possible, the original bold text formatting has been removed for clarity.</p>

None.

APPENDIX A: DOCUMENT REVISION HISTORY

Rev A Document (11/2011)

Initial release of this document; issued for revision A0. Includes silicon issues 1 (UART, Transmit) and 2 (Oscillator, REFO).

Rev B Document (4/2012)

Adds silicon issue 3 (HLVD, Band Gap Reference) to revision A0.

Adds data sheet clarifications 1 (Front Matter, Device Features), 2 (Pin Diagrams), 3 (Overview), 4 (I/O Ports), 5 (Master Synchronous Serial Port – MSSP) and 6 (Comparator).

Rev C Document (4/2013)

Adds silicon revision A1.

Rev D Document (3/2014)

Removes data sheet clarifications that were addressed in current Device Data Sheet (DS30001037C).

Adds data sheet clarifications 2 (Special Features) and 3 (Pin Diagrams).

Rev E Document (1/2016)

Adds silicon revision A2.

Rev F Document (12/2019)

Removes data sheet clarifications that were addressed in current Device Data Sheet (DS30001037D).

PIC24F16KL402 FAMILY

NOTES:

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLoo, JukeBlox, KeeLoq, Klear, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackeTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TempTrackr, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, Vite, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KlearNet, KlearNet logo, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2011-2019, Microchip Technology Incorporated, All Rights Reserved.

ISBN: 978-1-5224-5374-1

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.



MICROCHIP

Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta

Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Austin, TX

Tel: 512-257-3370

Boston

Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago

Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas

Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit

Novi, MI
Tel: 248-848-4000

Houston, TX

Tel: 281-894-5983

Indianapolis

Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453
Tel: 317-536-2380

Los Angeles

Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608
Tel: 951-273-7800

Raleigh, NC

Tel: 919-844-7510

New York, NY

Tel: 631-435-6000

San Jose, CA

Tel: 408-735-9110
Tel: 408-436-4270

Canada - Toronto

Tel: 905-695-1980
Fax: 905-695-2078

ASIA/PACIFIC

Australia - Sydney
Tel: 61-2-9868-6733

China - Beijing
Tel: 86-10-8569-7000

China - Chengdu
Tel: 86-28-8665-5511

China - Chongqing
Tel: 86-23-8980-9588

China - Dongguan
Tel: 86-769-8702-9880

China - Guangzhou
Tel: 86-20-8755-8029

China - Hangzhou
Tel: 86-571-8792-8115

China - Hong Kong SAR
Tel: 852-2943-5100

China - Nanjing
Tel: 86-25-8473-2460

China - Qingdao
Tel: 86-532-8502-7355

China - Shanghai
Tel: 86-21-3326-8000

China - Shenyang
Tel: 86-24-2334-2829

China - Shenzhen
Tel: 86-755-8864-2200

China - Suzhou
Tel: 86-186-6233-1526

China - Wuhan
Tel: 86-27-5980-5300

China - Xian
Tel: 86-29-8833-7252

China - Xiamen
Tel: 86-592-2388138

China - Zhuhai
Tel: 86-756-3210040

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444

India - New Delhi
Tel: 91-11-4160-8631

India - Pune
Tel: 91-20-4121-0141

Japan - Osaka
Tel: 81-6-6152-7160

Japan - Tokyo
Tel: 81-3-6880-3770

Korea - Daegu
Tel: 82-53-744-4301

Korea - Seoul
Tel: 82-2-554-7200

Malaysia - Kuala Lumpur
Tel: 60-3-7651-7906

Malaysia - Penang
Tel: 60-4-227-8870

Philippines - Manila
Tel: 63-2-634-9065

Singapore
Tel: 65-6334-8870

Taiwan - Hsin Chu
Tel: 886-3-577-8366

Taiwan - Kaohsiung
Tel: 886-7-213-7830

Taiwan - Taipei
Tel: 886-2-2508-8600

Thailand - Bangkok
Tel: 66-2-694-1351

Vietnam - Ho Chi Minh
Tel: 84-28-5448-2100

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

Finland - Espoo
Tel: 358-9-4520-820

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Garching
Tel: 49-8931-9700

Germany - Haan
Tel: 49-2129-3766400

Germany - Heilbronn
Tel: 49-7131-72400

Germany - Karlsruhe
Tel: 49-721-625370

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Germany - Rosenheim
Tel: 49-8031-354-560

Israel - Ra'anana
Tel: 972-9-744-7705

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Italy - Padova
Tel: 39-049-7625286

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Norway - Trondheim
Tel: 47-7288-4388

Poland - Warsaw
Tel: 48-22-3325737

Romania - Bucharest
Tel: 40-21-407-87-50

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

Sweden - Gothenberg
Tel: 46-31-704-60-40

Sweden - Stockholm
Tel: 46-8-5090-4654

UK - Wokingham
Tel: 44-118-921-5800
Fax: 44-118-921-5820