

Product Change Notification - SYST-08YWFH854

Date:

11 May 2020

Product Category:

8-bit Microcontrollers

Affected CPNs:



Notification subject:

ERRATA - ATxmega128/64/32/16A4U Silicon Errata and Data Sheet Clarification

Notification text:

SYST-08YWFH854

Microchip has released a new Product Documents for the ATxmega128/64/32/16A4U Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at ATxmega128/64/32/16A4U Silicon Errata and Data Sheet Clarification.

Notification Status: Final

Description of Change:

This revision includes the following updates to Data Sheet Clarifications:

- 1) Initial release of this document.
- 2) Content moved from the data sheet and restructured to the new document template
- 3) Updated the die revision list to reflect die revisions in production
- 4) Added silicon issue Hi-Res Extension Does Not Work for TCO/1 CCB and CCD

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 11 May 2020

NOTE: Please be advised that this is a change to the document only the product has not been

changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

ATxmega128/64/32/16A4U Silicon Errata and Data Sheet Clarification

Please contact your local <u>Microchip sales office</u> with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to <u>receive Microchip PCNs via email</u> please register for our PCN email service at our <u>PCN home page</u> select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the <u>PCN FAQ</u> section.

If you wish to <u>change your PCN profile</u>, <u>including opt out</u>, please go to the <u>PCN home page</u> select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

ATXMEGA128A4U-AU

ATXMEGA128A4U-AUR

ATXMEGA128A4U-CU

ATXMEGA128A4U-CUR

ATXMEGA128A4U-MH

ATXMEGA128A4U-MHR

ATXMEGA16A4U-AN

ATXMEGA16A4U-ANR

ATXMEGA16A4U-AU

ATXMEGA16A4U-AUR

ATXMEGA16A4U-CU

ATXMEGA16A4U-CUR

ATXMEGA16A4U-MH

ATXMEGA16A4U-MHR

ATXMEGA32A4U-AN

ATXMEGA32A4U-ANR

ATXMEGA32A4U-AU

ATXMEGA32A4U-AUR

ATXMEGA32A4U-CU

ATXMEGA32A4U-CUA0

ATXMEGA32A4U-CUR

ATXMEGA32A4U-MH

ATXMEGA32A4U-MHR

ATXMEGA32A4U-MHR893

ATXMEGA64A4U-AU

ATXMEGA64A4U-AUR

ATXMEGA64A4U-CU

ATXMEGA64A4U-CUR

ATXMEGA64A4U-MH

ATXMEGA64A4U-MHR

Date: Sunday, May 10, 2020



ATxmega128/64/32/16A4U

ATxmega128/64/32/16A4U Silicon Errata and Data Sheet Clarification

Introduction

The ATxmega128/64/32/16A4U devices you have received conform functionally to the current device data sheet (http://www.microchip.com/DS40002166), except for the anomalies described in this document. The errata described in this document will likely be addressed in future revisions of the ATxmega128/64/32/16A4U devices.

Note

· This document summarizes all the silicon errata issues from all revisions of silicon, previous as well as current.

Table of Contents

Intr	oductio	on	1			
1.	Silico	n Issue Summary	3			
2.	Silico	n Errata Issues	. 4			
	2.1.	Errata Details	4			
	2.2.	ADC - Analog to Digital Converter	4			
	2.3.	CRC - Cyclic Redundancy Check	. 4			
	2.4.	AWeX - Advanced Waveform eXtension	5			
	2.5.	Hi-Res - High-Resolution Extension				
3.	Data	Sheet Clarifications	7			
	3.1.	None	7			
4.	Docui	ment Revision History	8			
	4.1.	Revision History	. 8			
The	e Micro	chip Website	9			
Pro	duct C	hange Notification Service	9			
Cu	stomer	Support	. 9			
Mic	rochip	Devices Code Protection Feature	9			
Leç	gal Noti	ce	. 9			
Tra	ademarks10					
Qu	ality Ma	anagement System	10			
Wo	rldwide	Sales and Service	11			

1. Silicon Issue Summary

Legend

- Erratum is not applicable.
- **X** Erratum is applicable.
- * This silicon revision was never released to production.

				,	Valid for	Silicon	Revisio	n	
Peripheral	Short Description	ATxmega16A4U		ATxmega32A4U		ATxmega64A4U			ATxmega128A4U
		Rev. A-D	Rev. E	Rev. A-D	Rev. E	Rev. A-B	Rev. C	Rev. D	Rev. A
ADC	ADC May Have Missing Codes in Single Ended Unsigned Mode at Low Temp and Low V _{CC}	*	Х	*	Х	*	Х	Х	Х
CRC	CRC Fails for Range CRC When End Address is the Last Word Address of a Flash Section	*	Х	*	X	*	Х	Х	-
AWeX	AWeX Fault Protection Restore is Not Done Correctly in Pattern Generation Mode	*	Х	*	Х	*	Х	-	-
Hi-Res	Hi-Res Extension Does Not Work for TC0/1 CCB and CCD	*	Х	X	Х	*	X	X	Х

2. Silicon Errata Issues

2.1 Errata Details

- Erratum is not applicable.
- X Erratum is applicable.
- * This silicon revision was never released to production.

2.2 ADC - Analog to Digital Converter

2.2.1 ADC May Have Missing Codes in Single Ended (SE) Unsigned Mode at Low Temp. and Low V_{CC}

The ADC may have missing codes in SE unsigned mode below 0°C when V_{CC} is below 1.8V.

Workaround

Use the ADC in SE signed mode.

Affected Silicon Revisions

ATxmega16A4U			
Rev. A - D	Rev. E		
*	X		

ATxmega32A4U		
Rev. A - D	Rev. E	
*	X	

ATxmega64A4U					
Rev. A-B	Rev. C	Rev. D			
*	X	X			

	ATxmega128A4U	
Rev. A		
	X	

2.3 CRC - Cyclic Redundancy Check

2.3.1 CRC Fails for Range CRC When End Address is the Last Word Address of a Flash Section

If the boot read lock is enabled, the range CRC cannot end on the last address of the application section. If the application table read lock is enabled, the range CRC cannot end on the last address before the application table.

Workaround

Ensure that the end address used in Range CRC does not end at the last address before a section with read lock is enabled. Instead, use the dedicated CRC commands for complete application sections.

Affected Silicon Revisions ATxmega16A4U Rev. E Rev. A - D Χ ATxmega32A4U Rev. A - D Rev. E Χ ATxmega64A4U Rev. A-B Rev. C Rev. D Χ Χ ATxmega128A4U Rev. A

2.4 AWeX - Advanced Waveform eXtension

2.4.1 AWEX Fault Protection Restore is Not Done Correctly in Pattern Generation Mode

When a fault is detected, the OUTOVEN register is cleared, and when the fault condition is cleared, OUTOVEN is restored according to the corresponding enabled DTI channels. For Common Waveform Channel Mode (CWCM), this has no effect as the OUTOVEN is correct after restoring from fault. For Pattern Generation Mode (PGM), OUTOVEN should instead have been restored according to the DTLSBUF register.

Workaround

For CWCM, no workaround is required.

For PGM in latched mode, disable the DTI channels before returning from the fault condition. Then, set the correct OUTOVEN value and enable the DTI channels, before the direction (DIR) register is written to enable the correct outputs again.

Affected Silicon Revisions

Allected Silicon Revisions					
ATxmega16A4U					
Rev. A - D		Rev. E			
*			X		
	ATxmega32A4U				
Rev. A - D		Rev. E			
*			X		
ATxmega64A4U					
Rev. A-B	Rev. C		Rev. D		
*	>	<	-		

Χ

	ATxmega128A4U
Rev. A	
	-

2.5 Hi-Res - High-Resolution Extension

2.5.1 Hi-Res Extension Does Not Work for TC0/1 CCB and CCD

Enabling TC0/1 CCB or CCD with the Hi-res extension will cause incorrect values on belonging channel output in any of the waveform generation modes.

Workaround

None.

Affected Silicon Revisions

	ATxmega16A4U				
Rev. A - D		Rev. E			
*	•		X		
	ATxmeg	a32A4U			
Rev A - D		Rev F			

ATxmega64A4U					
Rev. A-B	Rev. C	Rev. D			
*	Х	X			

	ATxmega128A4U	
Rev. A		
	X	

ATxmega128/64/32/16A4U

Data Sheet Clarifications

3. Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (http://microchip.com/DS40002166).

Note: Corrections are shown in bold. Where possible, the original bold text formatting has been removed for clarity.

3.1 None

There are no known data sheet clarifications as of this publication date.

4. Document Revision History

Note: The data sheet clarification document revision is independent of the die revision and the device variant (last letter of the ordering number).

4.1 Revision History

Doc. Rev.	Date	Comments
A	04/2020	 Initial release of this document. Content moved from the data sheet and restructured to the new document template Updated the die revision list to reflect die revisions in production Added silicon issue <i>Hi-Res Extension Does Not Work for TC0/1 CCB and CCD</i>

The Microchip Website

Microchip provides online support via our website at http://www.microchip.com/. This website is used to make files and information easily available to customers. Some of the content available includes:

- Product Support Data sheets and errata, application notes and sample programs, design resources, user's
 guides and hardware support documents, latest software releases and archived software
- General Technical Support Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- Business of Microchip Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to http://www.microchip.com/pcn and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- · Distributor or Representative
- · Local Sales Office
- Embedded Solutions Engineer (ESE)
- · Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: http://www.microchip.com/support

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these
 methods, to our knowledge, require using the Microchip products in a manner outside the operating
 specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of
 intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Legal Notice

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with

your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackeTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TempTrackr, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, Vite, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KleerNet, KleerNet logo, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2020, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-5224-5406-9

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit http://www.microchip.com/quality.



Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
Corporate Office	Australia - Sydney	India - Bangalore	Austria - Wels
2355 West Chandler Blvd.	Tel: 61-2-9868-6733	Tel: 91-80-3090-4444	Tel: 43-7242-2244-39
Chandler, AZ 85224-6199	China - Beijing	India - New Delhi	Fax: 43-7242-2244-393
Tel: 480-792-7200	Tel: 86-10-8569-7000	Tel: 91-11-4160-8631	Denmark - Copenhagen
Fax: 480-792-7277	China - Chengdu	India - Pune	Tel: 45-4485-5910
Technical Support:	Tel: 86-28-8665-5511	Tel: 91-20-4121-0141	Fax: 45-4485-2829
http://www.microchip.com/support	China - Chongqing	Japan - Osaka	Finland - Espoo
Web Address:	Tel: 86-23-8980-9588	Tel: 81-6-6152-7160	Tel: 358-9-4520-820
http://www.microchip.com	China - Dongguan	Japan - Tokyo	France - Paris
Atlanta	Tel: 86-769-8702-9880	Tel: 81-3-6880- 3770	Tel: 33-1-69-53-63-20
Duluth, GA	China - Guangzhou	Korea - Daegu	Fax: 33-1-69-30-90-79
Tel: 678-957-9614	Tel: 86-20-8755-8029	Tel: 82-53-744-4301	Germany - Garching
Fax: 678-957-1455	China - Hangzhou	Korea - Seoul	Tel: 49-8931-9700
Austin, TX	Tel: 86-571-8792-8115	Tel: 82-2-554-7200	Germany - Haan
Tel: 512-257-3370	China - Hong Kong SAR	Malaysia - Kuala Lumpur	Tel: 49-2129-3766400
Boston	Tel: 852-2943-5100	Tel: 60-3-7651-7906	Germany - Heilbronn
Westborough, MA	China - Nanjing	Malaysia - Penang	Tel: 49-7131-72400
Tel: 774-760-0087	Tel: 86-25-8473-2460	Tel: 60-4-227-8870	Germany - Karlsruhe
Fax: 774-760-0088	China - Qingdao	Philippines - Manila	Tel: 49-721-625370
Chicago	Tel: 86-532-8502-7355	Tel: 63-2-634-9065	Germany - Munich
Itasca, IL	China - Shanghai	Singapore	Tel: 49-89-627-144-0
Tel: 630-285-0071	Tel: 86-21-3326-8000	Tel: 65-6334-8870	Fax: 49-89-627-144-44
Fax: 630-285-0075	China - Shenyang	Taiwan - Hsin Chu	Germany - Rosenheim
Dallas	Tel: 86-24-2334-2829	Tel: 886-3-577-8366	Tel: 49-8031-354-560
Addison, TX	China - Shenzhen	Taiwan - Kaohsiung	Israel - Ra'anana
Tel: 972-818-7423	Tel: 86-755-8864-2200	Tel: 886-7-213-7830	Tel: 972-9-744-7705
Fax: 972-818-2924	China - Suzhou	Taiwan - Taipei	Italy - Milan
Detroit	Tel: 86-186-6233-1526	Tel: 886-2-2508-8600	Tel: 39-0331-742611
Novi, MI	China - Wuhan	Thailand - Bangkok	Fax: 39-0331-466781
Tel: 248-848-4000	Tel: 86-27-5980-5300	Tel: 66-2-694-1351	Italy - Padova
Houston, TX	China - Xian	Vietnam - Ho Chi Minh	Tel: 39-049-7625286
Tel: 281-894-5983	Tel: 86-29-8833-7252	Tel: 84-28-5448-2100	Netherlands - Drunen
Indianapolis	China - Xiamen		Tel: 31-416-690399
Noblesville, IN	Tel: 86-592-2388138		Fax: 31-416-690340
Tel: 317-773-8323	China - Zhuhai		Norway - Trondheim
Fax: 317-773-5453	Tel: 86-756-3210040		Tel: 47-72884388
Tel: 317-536-2380			Poland - Warsaw
Los Angeles			Tel: 48-22-3325737
Mission Viejo, CA			Romania - Bucharest
Tel: 949-462-9523			Tel: 40-21-407-87-50
Fax: 949-462-9608			Spain - Madrid
Tel: 951-273-7800			Tel: 34-91-708-08-90
Raleigh, NC			Fax: 34-91-708-08-91
Tel: 919-844-7510			Sweden - Gothenberg
New York, NY			Tel: 46-31-704-60-40
Tel: 631-435-6000			Sweden - Stockholm
San Jose, CA			Tel: 46-8-5090-4654
Tel: 408-735-9110			UK - Wokingham
Tel: 408-436-4270			Tel: 44-118-921-5800
Canada - Toronto			Fax: 44-118-921-5820
Tel: 905-695-1980			
Fax: 905-695-2078			