

English ▼


Search Microchip

Search Data Sheets

[PRODUCTS](#) [APPLICATIONS](#) [DESIGN SUPPORT](#) [TRAINING](#) [SAMPLE & BUY](#) [ABOUT US](#) [Contact Us](#) [myMicrochip Login](#)

Product Change Notification - SYST-27AWEP266 [\(Printer Friendly\)](#)

Date: 07 May 2015

Affected CPNs: 

Notification subject: ERRATA - USB334x Family Silicon Errata and Data Sheet Clarification Errata Document Revision

Notification text: SYST-27AWEP266

Microchip has released a new DeviceDoc for the USB334x Family Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [USB334x Family Silicon Errata and Data Sheet Clarification](#).

Notification Status: Final

Description of Change: Initial release

Pre Change: Anomaly 1 Solution 1 The host SoC should command the USB334x to enable Full Speed Transceivers and enter Low Power Mode with a single command (TX CMD = 0x05h). Do not split these two steps into separate TX CMDs. The downstream USB device will always enter USB suspend when this work around is used.

Post Change: Anomaly 1 Solution 1 The host SoC should command the USB334x to enable Full Speed Transceivers and enter Low Power Mode with a single command (TX CMD = 0x05h). Do not split these two steps into separate TX CMDs. The downstream USB device will always enter USB suspend when this work around is used. If the Function Control Register (04h-06h) is written immediately after the Port Suspend bit is set and the XcvrSelect bits are set back to 00, the noise will be eliminated. Note: The squelch threshold may need to be adjusted through the Varisense bits in the HS Compensation Register (31h) to ensure that the correct status update still occurs.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 07 May 2015

NOTE: Please be advised that this is a change to the document only the product has not been changed..

Markings to Distinguish Revised from Unrevised Devices:N/A

Attachment(s): [USB334x Family Silicon Errata and Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."



[Products](#) [Applications](#) [Design Support](#) [Training](#) [Sample & Buy](#) [About Us](#) [Contact Us](#)
[Legal](#) [Investors](#) [Careers](#)

©Copyright 1998-2014 Microchip Technology Inc. All rights reserved.
Shanghai ICP Recordal No.09049794