



## Product Change Notification / SYST-06ELYK439

---

**Date:**

14-Nov-2020

**Product Category:**

8-bit Microcontrollers

**PCN Type:**

Document Change

**Notification Subject:**

ERRATA - PIC18F26/45/46Q10 Family Silicon Errata and Data Sheet Clarifications

**Affected CPNs:**

[SYST-06ELYK439\\_Affected\\_CPN\\_11142020.pdf](#)

[SYST-06ELYK439\\_Affected\\_CPN\\_11142020.csv](#)

**Notification Text:**

SYST-06ELYK439

Microchip has released a new Product Documents for the PIC18F26/45/46Q10 Family Silicon Errata and Data Sheet Clarifications of devices. If you are using one of these devices please read the document located at [PIC18F26/45/46Q10 Family Silicon Errata and Data Sheet Clarifications](#).

**Notification Status:** Final

**Description of Change:** Updated the Revision ID for silicon Rev B0.

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Productivity

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 14 Nov 2020

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

## **Attachments:**

[PIC18F26/45/46Q10 Family Silicon Errata and Data Sheet Clarifications](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

## **Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

PIC18F26Q10-E/ML  
PIC18F26Q10-E/SO  
PIC18F26Q10-E/SP  
PIC18F26Q10-E/SS  
PIC18F26Q10-E/SSVAO  
PIC18F26Q10-E/STX  
PIC18F26Q10-I/ML  
PIC18F26Q10-I/SO  
PIC18F26Q10-I/SP  
PIC18F26Q10-I/SS  
PIC18F26Q10-I/SSC01  
PIC18F26Q10-I/SSVAO  
PIC18F26Q10-I/STX  
PIC18F26Q10T-I/ML  
PIC18F26Q10T-I/SO  
PIC18F26Q10T-I/SS  
PIC18F26Q10T-I/SS020  
PIC18F26Q10T-I/SSC01  
PIC18F26Q10T-I/SSVAO  
PIC18F26Q10T-I/STX  
PIC18F45Q10-E/MP  
PIC18F45Q10-E/P  
PIC18F45Q10-E/PT  
PIC18F45Q10-E/PTVAO  
PIC18F45Q10-I/MP  
PIC18F45Q10-I/P  
PIC18F45Q10-I/PT  
PIC18F45Q10T-I/MP  
PIC18F45Q10T-I/PT  
PIC18F46Q10-E/MP  
PIC18F46Q10-E/P  
PIC18F46Q10-E/PT  
PIC18F46Q10-I/MP  
PIC18F46Q10-I/P  
PIC18F46Q10-I/PT  
PIC18F46Q10T-I/MP  
PIC18F46Q10T-I/PT

## PIC18F26/45/46Q10 Silicon Errata and Data Sheet Clarifications

The PIC18F26/45/46Q10 devices that you have received conform functionally to the current device data sheet (DS40001996D), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in the table below.

The errata described in this document will be addressed in future revisions of the PIC18F26/45/46Q10 silicon.

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current.

**Table 1. Silicon Device Identification**

Part Number	Device ID	Revision ID		
		A5	B0	B2
PIC18F26Q10	0x7180	0xA045	0xA0C0	0xA0C2
PIC18F45Q10	0x7140	0xA045	0xA0C0	0xA0C2
PIC18F46Q10	0x7120	0xA045	0xA0C0	0xA0C2



**Important:** Refer to the **Device/Revision ID** section in the current “**PIC18F2X/4XQ10 Memory Programming Specification**” (DS40001874) for more detailed information on Device Identification and Revision IDs for your specific device.

Table 2. Silicon Issue Summary

Module	Feature	Item No.	Issue Summary	Affected Revisions		
				A5	B0	B2
Electrical Specifications	Sleep current	1.1.1	Higher current after DFM write	X		
Resets	$\overline{\text{RMCLR}}$ flag	1.2.1	POR may clear the $\overline{\text{RMCLR}}$ bit by mistake	X	X	X
Resets	LPBOR	1.2.2	Trip point rises with temperature		X	
CWG	Auto-shutdown sources	1.3.1	CLC2 and CLC6 not available	X		
ADCC	FVR reference	1.4.1	Missing codes when FVR used as reference	X	X	X
ADCC	Burst average	1.4.2	ADCNT may not increment	X		
ADCC	ADCRC (FRC) oscillator	1.4.3	Oscillator continues to run in Sleep after conversion	X		
ADCC	Input slew rate	1.4.4	Unreliable conversion results with fast falling slew rate	X	X	X
Windowed Watchdog Timer	Window operation	1.5.1	Window feature of the WWDT does not operate correctly in Doze mode	X		
NVM	NVMERR	1.6.1	The NVMERR bit is set by device Reset after being cleared by software	X		
NVM	Self-writes	1.6.2	Do not write above 85°C	X		
MSSP	SPI	1.7.1	SSPBUF may be corrupted by writes to other GPR/SFRs	X		
Oscillator	HFINTOSC	1.8.1	5% variation over temperature range	X		
Oscillator	XT mode	1.8.2	Maximum clock frequency limited to 2 MHz for XT mode	X	X	

**Note:** Only those issues indicated in the last column apply to the current silicon revision.

# 1. Silicon Errata Issues



**Notice:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the bold font in the following tables apply to the current silicon revision.

## 1.1 Module: Electrical Specifications

### 1.1.1 Sleep Current - Higher Sleep Current after DFM Write Operation

When performing a DFM write operation during Sleep mode, once the write operation has completed, the system clock will stay active. This means that while the device remains in this state, a higher Sleep current will be experienced.

**Work around**

Once the DFM write operation is completed, wake the device up from Sleep mode and re-execute a new Sleep command.

**Affected Silicon Revisions**

A5	B0	B2
X		

## 1.2 Module: Resets

### 1.2.1 The $\overline{\text{RMCLR}}$ Flag in the PCON0 Register Cleared by Mistake

On an initial power-up of the device, or when executing a software Reset, the  $\overline{\text{RMCLR}}$  flag in the PCON0 register may be improperly cleared by a Power-On Reset (POR) or software Reset ( $\overline{\text{RI}}$ ), thereby indicating a false MCLR event.

**Work around**

None.

**Affected Silicon Revisions**

A5	B0	B2
X	X	X

### 1.2.2 Low-Power Brown-out Reset (LPBOR) Mode

The Brown-out Reset trip level increases proportionally with temperature to a level where BOR is never released. LPBOR cannot be used reliably because the trip level relative to temperature is indeterminate.

**Work around**

Use the normal power BOR mode.

**Affected Silicon Revisions**

A5	B0	B2
	X	

**1.3 Module: Complementary Waveform Generator (CWG)****1.3.1 CWG Auto-Shutdown Sources**

Shutdown sources AS6E (CLC2\_out) and AS7E (CLC6\_out) are not available.

**Work around**

Route the CLC output through PPS to an output pin, and use the AS0E source selection (pin selected by CWGxPPS) and PPS controls to select the same pin as the shutdown source.

**Affected Silicon Revisions**

A5	B0	B2
X		

**1.4 Module: Analog-to-Digital Converter with Computation (ADCC)****1.4.1 Missing Codes with FVR Reference**

Using the FVR as the positive voltage reference for the ADC can cause an increase in missing codes.

**Work around****Method 1:**

Increase the bit conversion time, known as  $T_{AD}$ , to 8  $\mu$ s or higher.

**Method 2:**

Use  $V_{DD}$  as the positive voltage reference to the ADC.

**Affected Silicon Revisions**

A5	B0	B2
X	X	X

**1.4.2 ADCC Burst Average Mode**

When the ADCC is operated in Burst Average mode (ADMD = 0b011 in the ADCON2 register) while enabling non-continuous operation and double-sampling (ADCONT = 0 in the ADCON0 register and ADDSEN = 1 in the ADCON1 register), the value in the ADCNT register does not increment beyond '0b1' toward the value in the ADRPT register.

**Work around**

When operating the ADCC in Burst Average mode with double-sampling, enable continuous operation of the module (ADCONT = 1 in the ADCON0 register) and set the Stop-on-Interrupt bit (the ADSOI bit in the ADCON3 register). After the interrupt occurs, perform appropriate threshold calculations in the software and retrigger ADCC as necessary.

Alternatively, if the CPU is in Low-Power Sleep mode, the ADCC in non-continuous Burst-Average mode can be operated with a single ADC conversion (ADDSEN = 0 in the ADCON1 register). Doing so compromises noise immunity for lower power consumption by preventing the device from waking up to perform threshold calculations in the software.

**Affected Silicon Revisions**

A5	B0	B2
X		

**1.4.3 ADCRC (FRC) Oscillator Operation in Sleep**

If the part is in Sleep and the ADCRC (FRC) oscillator is used as clock source to the ADC, the oscillator continues to run after the conversion is complete. This will increase the current consumption in Sleep mode. The oscillator will stop after the device exits Sleep mode and resumes normal code execution.

**Work around**

None.

**Affected Silicon Revisions**

A5	B0	B2
X		

**1.4.4 Unreliable Conversion Results with Fast Falling Slew Rate**

When the ADC input falls by greater than 3.2V, with a slew rate faster than  $-11 \text{ V}/\mu\text{s}$ , the next ADC conversion will have the Most Significant bit (MSb) improperly set. This is likely to happen when the ADC input channel is switched from one with a high input level to another with a low input level.

**Work around**

When switching between input channels, discard the first conversion result after the switch. Subsequent conversions will not be affected.

**Affected Silicon Revisions**

A4	B0	B2
X	X	X

**1.5 Module: Windowed Watchdog Timer (WWDT)****1.5.1 Window Operation in Doze Mode**

When the windowed mode of operation is enabled in Doze mode, a window violation error is issued even though the window is open and has been armed. This condition occurs only when the window size is set to a value other than 100% open.

**Work around****Method 1:**

Use the windowed mode of operation in any other than Doze mode. If disabling the Doze mode is not an option, use the WWDT module without the window being enabled.

**Method 2:**

If the device is in Doze mode, perform the arming process for the window in Normal mode and return to the Doze mode.

**Method 3:**

If there is an Interrupt Service Routine (ISR) in the application code, the arming within the window can be done inside the ISR with the ROI bit of the CPUDOZE register being set.



**Affected Silicon Revisions**

A5	B0	B2
X		

**1.6 Module: Nonvolatile Memory (NVM)**

**1.6.1 NVMERR**

When a Reset is issued while an NVM high-voltage operation is in progress, the NVMERR bit in the NVMCON0 register is set as expected. After clearing the NVMERR bit, if a Reset reoccurs, the NVMERR bit is set again regardless of whether an NVM operation is in progress or not. A successful write operation will clear the NVMERR condition.

**Work around**

None.

**Affected Silicon Revisions**

A5	B0	B2
X		

**1.6.2 PFM Writes Above 85° Celsius**

Do not perform write operations on the Program Flash Memory (PFM) when the temperature is above 85 degrees Celsius.

**Work around**

Perform PFM writes below 85 degrees Celsius.

**Affected Silicon Revisions**

A5	B0	B2
X		

**1.7 Module: Master Synchronous Serial Port (MSSP)**

**1.7.1 MSSP SPI Slave Mode**

When operating in SPI Slave mode, if the incoming SCK clock signal arrives during any of the conditions below, the SSPBUF Transmit Shift Register (TSR) may become corrupted. The transmitted slave byte cannot be ensured to be correct, and the state of the WCOL bit may or may not indicate a write collision.

These conditions include:

- A write to an SFR
- A write to RAM following an SFR read
- A write to RAM prior to an SFR read

**Work around**

**Method 1 (Interrupt based using  $\overline{SS}$ ):**

1. Connect the  $\overline{SS}$  line to both the  $\overline{SS}$  input and either an INT or IOC input pin.
2. Enable INT or IOC interrupts (interrupt on falling edge if available, otherwise check that  $\overline{SS} == 0$  when the interrupt occurs).

3. Load SSPBUF with the data to be transmitted.
4. Continue program execution.
5. When the Interrupt Service Routine (ISR) is invoked, do either of the following:
  - 5.1. Add a delay that ensures the first SCK clock will be complete, or
  - 5.2. Poll SSPSTAT.BF (while(BF == 0)) and wait for the transmission/reception to complete.

**Method 2 (Bit polling based using  $\overline{SS}$ ):**

1. Load SSPBUF with the data to be transmitted.
2. Poll the  $\overline{SS}$  line and wait for the  $\overline{SS}$  to go active (while(!PORTx. $\overline{SS}$  == 0)).
3. When  $\overline{SS}$  is active ( $\overline{SS}$  == 0), do either of the following:
  - 3.1. Add a delay that ensures the first SCK clock will be complete, or
  - 3.2. Poll SSPSTAT.BF (while(BF == 0)), and wait for the transmission/reception to complete.

Once one of these two methods are complete, it is safe to return to program execution.

**Method 3 ( $\overline{SS}$  not available):**

1. Load SSPBUF with the data to be transmitted.
2. Poll SSPSTAT.BF (while(BF == 0)), and wait for the transmission/reception to complete.

**Affected Silicon Revisions**

A5	B0	B2
X		

## 1.8 Module: Oscillator

### 1.8.1 Internal HFINTOSC Oscillator Varies up to 5%

The internal HFINTOSC oscillator varies in frequency up to 5% over the voltage and temperature range.

**Work around**

For systems requiring more precision, use an external crystal or ceramic resonator in one of the external oscillator modes.

**Affected Silicon Revisions**

A5	B0	B2
X		

### 1.8.2 Maximum Clock Frequency Limited to 2 MHz for XT Mode

The maximum clock frequency for the intermediate gain setting that supports quartz crystal and ceramic resonator operation (XT mode) is being reduced from 4 MHz to 2 MHz.

**Work around**

For crystal or resonator frequencies above 2 MHz, use HS mode.

**Affected Silicon Revisions**

A5	B0	B2
X	X	

## **2. Data Sheet Clarifications**

### **2.1 None**

There are no known data sheet clarifications as of this publication date.

**3. Appendix A: Revision History**

Doc Rev.	Date	Comments
E	11/2020	Updated the Revision ID for silicon Rev B0.
D	09/2020	Added new silicon Rev B2.
C	05/2020	Added new silicon Rev B0. Added issue 1.2.2 and 1.8.2.
B	05/2019	Added oscillator drift erratum. Removed data sheet clarifications.
A	03/2019	Initial document release.

---

## The Microchip Website

---

Microchip provides online support via our website at [www.microchip.com/](http://www.microchip.com/). This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

---

## Product Change Notification Service

---

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to [www.microchip.com/pcn](http://www.microchip.com/pcn) and follow the registration instructions.

---

## Customer Support

---

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: [www.microchip.com/support](http://www.microchip.com/support)

---

## Microchip Devices Code Protection Feature

---

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods being used in attempts to breach the code protection features of the Microchip devices. We believe that these methods require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Attempts to breach these code protection features, most likely, cannot be accomplished without violating Microchip's intellectual property rights.
- Microchip is willing to work with any customer who is concerned about the integrity of its code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable." Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

## Legal Notice

---

Information contained in this publication is provided for the sole purpose of designing with and using Microchip products. Information regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL OR CONSEQUENTIAL LOSS, DAMAGE, COST OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

---

## Trademarks

---

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Klear, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackeTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, Inter-Chip Connectivity, JitterBlocker, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICKit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SMART-I.S., storClad, SQL, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2020, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-5224-7096-0

## Quality Management System

---

For information regarding Microchip's Quality Management Systems, please visit [www.microchip.com/quality](http://www.microchip.com/quality).

## Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
<p><b>Corporate Office</b> 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Tel: 480-792-7277 Technical Support: <a href="http://www.microchip.com/support">www.microchip.com/support</a> Web Address: <a href="http://www.microchip.com">www.microchip.com</a></p> <p><b>Atlanta</b> Duluth, GA Tel: 678-957-9614 Fax: 678-957-1455</p> <p><b>Austin, TX</b> Tel: 512-257-3370</p> <p><b>Boston</b> Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088</p> <p><b>Chicago</b> Itasca, IL Tel: 630-285-0071 Fax: 630-285-0075</p> <p><b>Dallas</b> Addison, TX Tel: 972-818-7423 Fax: 972-818-2924</p> <p><b>Detroit</b> Novi, MI Tel: 248-848-4000</p> <p><b>Houston, TX</b> Tel: 281-894-5983</p> <p><b>Indianapolis</b> Noblesville, IN Tel: 317-773-8323 Fax: 317-773-5453 Tel: 317-536-2380</p> <p><b>Los Angeles</b> Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800</p> <p><b>Raleigh, NC</b> Tel: 919-844-7510</p> <p><b>New York, NY</b> Tel: 631-435-6000</p> <p><b>San Jose, CA</b> Tel: 408-735-9110 Tel: 408-436-4270</p> <p><b>Canada - Toronto</b> Tel: 905-695-1980 Fax: 905-695-2078</p>	<p><b>Australia - Sydney</b> Tel: 61-2-9868-6733</p> <p><b>China - Beijing</b> Tel: 86-10-8569-7000</p> <p><b>China - Chengdu</b> Tel: 86-28-8665-5511</p> <p><b>China - Chongqing</b> Tel: 86-23-8980-9588</p> <p><b>China - Dongguan</b> Tel: 86-769-8702-9880</p> <p><b>China - Guangzhou</b> Tel: 86-20-8755-8029</p> <p><b>China - Hangzhou</b> Tel: 86-571-8792-8115</p> <p><b>China - Hong Kong SAR</b> Tel: 852-2943-5100</p> <p><b>China - Nanjing</b> Tel: 86-25-8473-2460</p> <p><b>China - Qingdao</b> Tel: 86-532-8502-7355</p> <p><b>China - Shanghai</b> Tel: 86-21-3326-8000</p> <p><b>China - Shenyang</b> Tel: 86-24-2334-2829</p> <p><b>China - Shenzhen</b> Tel: 86-755-8864-2200</p> <p><b>China - Suzhou</b> Tel: 86-186-6233-1526</p> <p><b>China - Wuhan</b> Tel: 86-27-5980-5300</p> <p><b>China - Xian</b> Tel: 86-29-8833-7252</p> <p><b>China - Xiamen</b> Tel: 86-592-2388138</p> <p><b>China - Zhuhai</b> Tel: 86-756-3210040</p>	<p><b>India - Bangalore</b> Tel: 91-80-3090-4444</p> <p><b>India - New Delhi</b> Tel: 91-11-4160-8631</p> <p><b>India - Pune</b> Tel: 91-20-4121-0141</p> <p><b>Japan - Osaka</b> Tel: 81-6-6152-7160</p> <p><b>Japan - Tokyo</b> Tel: 81-3-6880-3770</p> <p><b>Korea - Daegu</b> Tel: 82-53-744-4301</p> <p><b>Korea - Seoul</b> Tel: 82-2-554-7200</p> <p><b>Malaysia - Kuala Lumpur</b> Tel: 60-3-7651-7906</p> <p><b>Malaysia - Penang</b> Tel: 60-4-227-8870</p> <p><b>Philippines - Manila</b> Tel: 63-2-634-9065</p> <p><b>Singapore</b> Tel: 65-6334-8870</p> <p><b>Taiwan - Hsin Chu</b> Tel: 886-3-577-8366</p> <p><b>Taiwan - Kaohsiung</b> Tel: 886-7-213-7830</p> <p><b>Taiwan - Taipei</b> Tel: 886-2-2508-8600</p> <p><b>Thailand - Bangkok</b> Tel: 66-2-694-1351</p> <p><b>Vietnam - Ho Chi Minh</b> Tel: 84-28-5448-2100</p>	<p><b>Austria - Wels</b> Tel: 43-7242-2244-39 Fax: 43-7242-2244-393</p> <p><b>Denmark - Copenhagen</b> Tel: 45-4485-5910 Fax: 45-4485-2829</p> <p><b>Finland - Espoo</b> Tel: 358-9-4520-820</p> <p><b>France - Paris</b> Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79</p> <p><b>Germany - Garching</b> Tel: 49-8931-9700</p> <p><b>Germany - Haan</b> Tel: 49-2129-3766400</p> <p><b>Germany - Heilbronn</b> Tel: 49-7131-72400</p> <p><b>Germany - Karlsruhe</b> Tel: 49-721-625370</p> <p><b>Germany - Munich</b> Tel: 49-89-627-144-0 Fax: 49-89-627-144-44</p> <p><b>Germany - Rosenheim</b> Tel: 49-8031-354-560</p> <p><b>Israel - Ra'anana</b> Tel: 972-9-744-7705</p> <p><b>Italy - Milan</b> Tel: 39-0331-742611 Fax: 39-0331-466781</p> <p><b>Italy - Padova</b> Tel: 39-049-7625286</p> <p><b>Netherlands - Drunen</b> Tel: 31-416-690399 Fax: 31-416-690340</p> <p><b>Norway - Trondheim</b> Tel: 47-72884388</p> <p><b>Poland - Warsaw</b> Tel: 48-22-3325737</p> <p><b>Romania - Bucharest</b> Tel: 40-21-407-87-50</p> <p><b>Spain - Madrid</b> Tel: 34-91-708-08-90 Fax: 34-91-708-08-91</p> <p><b>Sweden - Gothenberg</b> Tel: 46-31-704-60-40</p> <p><b>Sweden - Stockholm</b> Tel: 46-8-5090-4654</p> <p><b>UK - Wokingham</b> Tel: 44-118-921-5800 Fax: 44-118-921-5820</p>