



| | | | |
|-----------------|-------------------|------------------|----------------|
| NL17SV00XV5T2G | NSBC113EDXV6T1G | NSBC144EDXV6T5G | NZQA6V2XV5T1G |
| NL17SV02XV5T2G | NSBC113EPDXV6T1G | NSBC144EPDXV6T1G | NZQA6V8AXV5T1G |
| NL17SV04XV5T2G | NSBC114EDXV6T1G | NSBC144EPDXV6T5G | NZQA6V8AXV5T2G |
| NL17SV08XV5T2G | NSBC114EDXV6T5G | NSBC144WDXV6T1G | NZQA6V8AXV5T3G |
| NL17SV16XV5T2G | NSBC114EPDXV6T5G | NSDEMP11XV6T1G | NZQA6V8XV5T1G |
| NL17SV32XV5T2G | NSBC114TDXV6T1G | NSDEMP11XV6T5G | SNUF2042XV6T1G |
| NL17SZ00XV5T2G | NSBC114TDXV6T5G | NSR0320XV6T1G | STZD3155CT1G |
| NL17SZ02XV5T2G | NSBC114TPDXV6T1G | NSR0320XV6T5G | STZD5110NT1G |
| NL17SZ06XV5T2G | NSBC114YDXV6T1G | NSS12100XV6T1G | |
| NL17SZ07XV5T2G | NSBC114YDXV6T5G | NST30010MXV6T1G | |
| NL17SZ08XV5T2GH | NSBC114YPDXXV6T1G | NST3904DXV6T1G | |
| NL17SZ126XV5T2G | NSBC114YPDXXV6T5G | NST3904DXV6T5G | |
| NL17SZ14XV5T2G | NSBC115EDXV6T1G | NST3906DXV6T1G | |

List of Affected Customer Specific Parts:

NOTE: Please be informed that parts impacted by this PDN/PCN are Special/Customer specific parts, thus MPN & CPN info will be available to affected customers only by clicking the "Custom PCN for Selected Company Button" in the Document Analysis page of PCMS/PCN Alert.