3^{1/2} Digital Multimeter





Features

- 3½ digital multiple with 7 sections LCD display
- Press the BACKLIGHT button to turn on the backlights
- · Function and range switch
- · Data hold button
- · Direct current voltage measurement
- · Alternating voltage measurement
- · Diode, resistor, temperature and circuit on-off measurement
- · 1999 maximum display value
- · Low voltage indication
- 9V battery, NEDA 1604 or 6F22 powered

Specifications

Fuse : F1 250mA/250V F2 10A/250V Power : 9V battery, NEDA 1604 or 6F22

Maximum display value 1999 Over-range Indication : "1"

Polarity Display : " - " for negative polarity

Operating Temperature : 0°C to +40°C

Storage Temperature : -10°C to +50°C

Low Voltage Indication : "========"">
Low Voltage Indication : 138mm×69mm×31mm

Weight : 170g

Max. Voltage between Input

and the ground : CATII 600V

Contents : Multimeter, One pair of probes, Instruction manual,

One 9V battery NEDA 1604 6F22.

Direct Current Voltage Measurement

Range	Resolution	Accuracy
200mV	100μV	±0.5% of reading, ±3 digits
2V	1mV	±0.5% of reading, ±3 digits
20V	10mV	±0.5% of reading, ±3 digits
200V	100mV	±0.5% of reading, ±3 digits
600V	1V	±0.8% of reading, ±5 digits

Overload protection: 200mV range: 250V DC or RMS;

The rest ranges: 600V DC or RMS.

Newark.com/exclusive-brands Farnell.com/exclusive-brands Element14.com/exclusive-brands



3^{1/2} Digital Multimeter



Direct Current Measurement

Range	Resolution	Accuracy
20μΑ	0.01μΑ	±1% of reading, ±3 digits
200μΑ	0.1µA	±1% of reading, ±3 digits
2mA	1μΑ	±1% of reading, ±3 digits
20mA	10μA	±1% of reading, ±5 digits
200mA	100μΑ	±1.5% of reading, ±5 digits
10A	10mA	±3% of reading, ±10 digits

Overload protection: F1 200mA/250V Fuse F2 10A/250V

Alternating Voltage Measurement

Range	Resolution	Accuracy
200V	100mV	±1.2% of reading, ±10 digits
600V	1V	±1.2% of reading, ±10 digits

Overload protection: 600V DC or RMS Frequency range: 40Hz to 400Hz

Display: Average (effective value of sinusoid)

Resistor

Range	Resolution	Accuracy
200Ω	0.1Ω	±0.8% of reading, ±5 digits
2kΩ	1Ω	±0.8% of reading, ±2 digits
20kΩ	10Ω	±0.8% of reading, ±2 digits
200kΩ	100Ω	±0.8% of reading, ±2 digits
2ΜΩ	1kΩ	±1.0% of reading, ±5 digits

Maximum open circuit voltage: 3.2V Overload protection: 250V DC or RMS

Diode and Circuit On-Off Measurement

Range	Description	
01))	When the on-resistance is smaller than $(70\pm30)\Omega$, the built-in buzzer will sound.	
→	Displays the approximate diode positive voltage.	

Overload protection: 250V DC or RMS. AC.

Temperature Measurement

Range	Resolution	Measurement	Accuracy
		-20°C to 0°C	±10% Range, ±2 digits
°C	1°C	-0°C to 400°C	±1.0% Range, ±3 digits
		400°C to 1000°C	±2.0% Range

Newark.com/exclusive-brands Farnell.com/exclusive-brands Element14.com/exclusive-brands



3^{1/2} Digital Multimeter



Operation

- Plug the instrument in and check the 9V battery. If it is low the "\(\mathbb{E}\)" symbol will display, meaning the battery needs replacing.
- The \triangle besides the probe jack indicates that the input voltage or current should not exceed the specified limits, in order to protect the internal circuit.
- Before measurement, turn the function/range switch to the desired range.

Direct Voltage Measurement

- Insert the red probe into the " $V\Omega mA$ " jack and the black one into the COM jack.
- Turn the function/range switch to the range of V=== and connect the probe to the power supply or load to be measured. The polarity touched by the red probe will be on the display.
- Overload protection: 250V DC or AC (RMS)

Part Number Table

Description	Part Number
3½ Digital Multimeter	D03125

Important Notice: This data sheet and its contents (the "Information") belong to the members of the AVNET group of companies (the "Group") or are licensed to it. No licence is granted for the use of it other than for information purposes in connection with the products to which it relates. No licence of any intellectual property rights is granted. The Information is subject to change without notice and replaces all data sheets previously supplied. The Information supplied is believed to be accurate but the Group assumes no responsibility for its accuracy or completeness, any error in or omission from it or for any use made of it. Users of this data sheet should check for themselves the Information and the suitability of the products for their purpose and not make any assumptions based on information included or omitted. Liability for loss or damage resulting from any reliance on the Information or use of it (including liability resulting from negligence or where the Group was aware of the possibility of such loss or damage arising) is excluded. This will not operate to limit or restrict the Group's liability for death or personal injury resulting from its negligence. DURATOOL is the registered trademark of Premier Farnell Limited 2019.

Newark.com/exclusive-brands Farnell.com/exclusive-brands Element14.com/exclusive-brands



Page <3> 14/11/23 V1.1