



28-May-2021

PCN #:P-21-020967

Subject:FPC and FFC Connector

Description of Change: Add an alternative resin that can be used in the short term to bridge the supply gap of the normally used resin.

Reason: Product improvement. Dear, Valued customer. As you know the world is currently experiencing a global resin shortage. The shortage will impact the products in this PCN. In an effort to mitigate disruptions to your supply chain we have identified and evaluated an alternative resin that can be used in the short term to bridge the supply gap of the normally used resin. There should be no performance differences between the current resin and the short term alternative. When supply returns to normal we will change back over to the current resin. Due to the extreme shortage the last shipment date using the current resin will be 6/01/2021. The last order date using the new resin will be 5/28/2021. The uninterrupted delivery of product will be based on how fast we can receive approval of the new resin from you all. Keep in mind identical parts made with the new resin will continued to be shipped after approval. There is no technical or dimensional change.

Key Dates:

Contact By Date:01-Jun-2021

Implementation Date:01-Jun-2021

| Product Affected | Alias Part Number |
|-------------------------|--------------------------|
| 487545-9 | "010-7174-00" |
| 88859-1 | |
| 1-487545-0 | |
| 1-485893-6 | |
| 3-88859-0 | |
| 487769-9 | |
| 487545-1 | |

| Product Affected | Alias Part Number |
|-------------------------|--------------------------|
| 487526-5 | |
| 485893-7 | |
| 487378-4 | |
| 2-487526-4 | |
| 1-487769-3 | |
| 1-88859-1 | |
| 1-487769-8 | |
| 1-487378-7 | |
| 487526-6 | |
| 3-88859-3 | |
| 487769-8 | |
| 1-487378-8 | |
| 4-487545-7 | |
| 487526-4 | |
| 487545-4 | |
| 485893-4 | |
| 1-485893-1 | |
| 487769-1 | |
| 487223-7 | |
| 1-487223-2 | |
| 2-487378-3 | |
| 88859-2 | |
| 1-487545-2 | |
| 4-487545-2 | |
| 2-487545-2 | |
| 2-487526-1 | |
| 1-485893-4 | |
| 1-487545-4 | |
| 88859-8 | |
| 1-88859-4 | |
| 88859-6 | |
| 485893-8 | |
| 1-88859-0 | |
| 1-487223-0 | |
| 487223-5 | |
| 487769-2 | |
| 88859-7 | |
| 1-88859-3 | |
| 1-485893-3 | |
| 487526-7 | |

| Product Affected | Alias Part Number |
|-------------------------|--------------------------|
| 1-487526-4 | |
| 2-487769-0 | |
| 2-487769-2 | |
| 487223-6 | |
| 1-485893-2 | |
| 1-88859-2 | |
| 88859-4 | |
| 487223-8 | |
| 2-88859-7 | |
| 1-487526-9 | |
| 487378-1 | |
| 487545-3 | "010-7175-00" |
| 487545-7 | |
| 487769-6 | |
| 2-487545-7 | |
| 1-485893-0 | |
| 1-487378-1 | |
| 487223-3 | |
| 487526-2 | |
| 1-487526-6 | |
| 2-487378-5 | |
| 485893-3 | |
| 487223-9 | |
| 1-487526-0 | |
| 487526-9 | |
| 1-487526-5 | |
| 1-487378-3 | |
| 1-487378-6 | |
| 1-485893-8 | |
| 487769-7 | |
| 487769-3 | |
| 485893-2 | |
| 88859-9 | |
| 88859-5 | |
| 1-487769-2 | |
| 487526-1 | |
| 1-487769-4 | |
| 487769-4 | |
| 2-487378-0 | |
| 88859-3 | |

| Product Affected | Alias Part Number |
|-------------------------|--------------------------|
| 487378-9 | |
| 487378-7 | |
| 1-487545-7 | |
| 485893-5 | |
| 487378-2 | |
| 487545-5 | |
| 1-487526-2 | |
| 1-487526-1 | |
| 1-487378-4 | |
| 1-88859-5 | |
| 1-487526-7 | |
| 1-487769-0 | |
| 1-487378-2 | |
| 1-487378-9 | |
| 487769-5 | |
| 1-487769-1 | |
| 487526-8 | |
| 1-487378-0 | |
| 1-487526-8 | |
| 485893-6 | |
| 487378-5 | |
| 3-487545-3 | |
| 487378-8 | |
| 1-487378-5 | |
| 487378-6 | |
| 3-487545-7 | |
| 487526-3 | |
| 2-487378-1 | |
| 1-487526-3 | |
| 1-487545-9 | |
| 487223-2 | |
| 2-487526-3 | |
| 485893-9 | |
| 487378-3 | |
| 487545-2 | |

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.