

Product Change Notification - SYST-24YDSF264

Date:

25 Jun 2020

Product Category:

8-bit Microcontrollers

Affected CPNs:



Notification subject:

ERRATA - AVR32DA28/32/48 Silicon Errata and Data Sheet Clarification

Notification text:

SYST-24YDSF264

Microchip has released a new Product Documents for the AVR32DA28/32/48 Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at AVR32DA28/32/48 Silicon Errata and Data Sheet Clarification.

Notification Status: Final

Description of Change: Initial document release

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 25 Jun 2020

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A Attachment(s):

AVR32DA28/32/48 Silicon Errata and Data Sheet Clarification

Please contact your local <u>Microchip sales office</u> with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to <u>receive Microchip PCNs via email</u> please register for our PCN email service at our <u>PCN home page</u> select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the <u>PCN FAQ</u> section.

If you wish to <u>change your PCN profile</u>, <u>including opt out</u>, please go to the <u>PCN home page</u> select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

SYST-24YDSF264 - ERRATA - AVR32DA28/32/48 Silicon Errata and Data Sheet Clarification

Affected Catalog Part Numbers (CPN)

AVR32DA28-I/SO

AVR32DA28-I/SP

AVR32DA28-I/SS

AVR32DA28T-I/SO

AVR32DA28T-I/SS

AVR32DA32-I/PT

AVR32DA32-I/RXB

AVR32DA32T-I/PT

AVR32DA32T-I/RXB

AVR32DA48-I/6LX

AVR32DA48-I/PT

AVR32DA48T-I/6LX

AVR32DA48T-I/PT

Date: Wednesday, June 24, 2020

SYST-24YDSF264 - ERRATA - AVR32DA28/32/48 Silicon Errata and Data Sheet Clarification

Affected Catalog Part Numbers(CPN)

AVR32DA28-I/SO

AVR32DA28-I/SP

AVR32DA28-I/SS

AVR32DA28T-I/SO

AVR32DA28T-I/SS

AVR32DA32-I/PT

AVR32DA32-I/RXB

AVR32DA32T-I/PT

AVR32DA32T-I/RXB

AVR32DA48-I/6LX

AVR32DA48-I/PT

AVR32DA48T-I/6LX

AVR32DA48T-I/PT



AVR32DA28/32/48

Silicon Errata and Data Sheet Clarification

The AVR32DA28/32/48 devices you have received conform functionally to the current device data sheet (microchip.com/DS40002228), except for the anomalies described in this document. The erratas described in this document will likely be addressed in future revisions of the AVR32DA28/32/48 devices.

Notes:

- · This document summarizes all the silicon errata issues from all revisions of silicon, previous as well as current.
- Refer to the Device/Revision ID section in the current device data sheet (microchip.com/DS40002228) for more
 detailed information on Device Identification and Revision IDs for your specific device, or contact your local
 Microchip sales office for assistance.

1. Silicon Issue Summary

Legend

- Erratum is not applicable.
- **X** Erratum is applicable.

Peripheral	Short Description	Valid for Silicon Revision
		Rev. A3 <u>(*)</u>
PORT	2.2.1 Digital Input on Pin Automatically Disabled When Pin Selected for Analog Input	Х
TWI	2.3.1 The Output Pin Override Does Not Function as Expected	X
USART	2.4.1 Open-Drain Mode Does Not Work When TXD is Configured as Output	Х
ZCD	2.5.1 ZCD Output Selection Bits Should Be Individual Bits	X

Note:

(*) This revision is the initial release of the silicon.

2. Silicon Errata Issues

2.1 Errata Details

- Erratum is not applicable.
- **X** Erratum is applicable.

2.2 PORT - I/O Pin Configuration

2.2.1 Digital Input on Pin Automatically Disabled When Pin Selected for Analog Input

If an input pin is selected to be analog input, the digital input function for those pins is automatically disabled.

Work around

None.

Affected Silicon Revisions

Rev. A3
Х

2.3 TWI - Two-Wire Interface

2.3.1 The Output Pin Override Does Not Function as Expected

When TWI is enabled it overrides the output pin driver, but not the output value. So when the value in the PORT Out (PORTx.OUT) register is '1', for the pins corresponding to the SDA or SCL, the output on the line will always be high.

Work around

Ensure that the value in the PORTx.OUT register corresponding to the SCL and SDA pins are '0' before enabling the TWI.

Affected Silicon Revisions

Rev. A3
Х

2.4 USART - Universal Synchronous and Asynchronous Receiver and Transmitter

2.4.1 Open-Drain Mode Does Not Work When TXD is Configured as Output

When the USART TXD pin is configured as an output, it can drive the pin high regardless of whether the Open-Drain mode is enabled or not.

Work around

Configure the TXD pin as an input by writing the corresponding bit in PORTx.DIR to '0' when using Open-Drain mode.

Affected Silicon Revisions

Rev. A3
X

2.5 ZCD - Zero-Cross Detector

2.5.1 ZCD Output Selection Bits Should Be Individual Bits

The ZCD1 and ZCD2 output selection bits in the ZCDROUTEA register are tied to the ZCD0 bit. When writing a value to the ZCD0 bit, all three ZCD outputs are switched from the default pin setting to the alternative pin setting. When writing to either ZCD1 or ZCD2 bits, nothing happens.

Work around

None.

Affected Silicon Revisions

Rev. A3	
X	

3.	Data	Sheet	Clarit	fications
v.	Dutu	Olioci	VIGIT	HOULIOHIS

None.

4. Document Revision History

Note: The data sheet clarification document revision is independent of the die revision and the device variant (last letter of the ordering number).

4.1 Revision History

Doc. Rev.	Date	Comments
Α	06/2020	Initial document release

The Microchip Website

Microchip provides online support via our website at www.microchip.com/. This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- General Technical Support Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- Business of Microchip Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to www.microchip.com/pcn and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- · Distributor or Representative
- · Local Sales Office
- Embedded Solutions Engineer (ESE)
- · Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: www.microchip.com/support

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip devices:

- · Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these
 methods, to our knowledge, require using the Microchip products in a manner outside the operating
 specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of
 intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Legal Notice

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with

your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackeTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TempTrackr, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, Vite, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KleerNet, KleerNet logo, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2020, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-5224-6181-4

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.



Worldwide Sales and Service

AMERICAS ASJAR/ACIFIC ASJAR/ACIFIC EUROPE 2355 West Chandler Blud Tel: 61-2-9868-6733 India - Bangalore Tel: 43-7242-2244-39 Chandler, AZ 55/24-6199 China - Beijing India - New Delhi Fex: 43-7242-2244-39 Fax: 480-792-7200 Tel: 86-10-8669-7000 Tel: 91-11-1160-8331 Dommark - Copenhagen Fax: 480-732-7272 China - Chengdu India - Pune Tel: 91-12-0141-11 Fex: 48-4485-5910 Fax: 480-732-7272 China - Chengdu India - Pune Tel: 91-20-412-10141 Fex: 45-4485-229 Fax: 680-980-780 China - Chongqing Japan - Osake Fill efile-16-20-900-78 Fill efile-20-20-20 Austin TX Tel: 68-67-89-60-5980 Tel: 68-87-870-9890 China - Guangthou Korea - Daegu Fex: 67-89-54-50-02 Fex: 68-85-14-300 Germany - Germany - Germany - Germany - Fex: 31-69-30-90-79 Tel: 68-87-88-71-45-50 Tel: 68-87-88-71-400 Tel: 68-87-88-71-700 Tel: 69-27-88-71-700 Tel: 69-27-88-71-700 Tel: 69-27-88-71-700 Tel: 69-27-88-71-700 Te				
2355 West Chandler Blvd. Chandler, AZ 82224-199 China - Beigling Tel: 480-792-7270 Tel: 480-792-7270 Tel: 86-10-8568-7000 Tel: 86-10-85	AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
Chandler, AZ 85224-8199 Tell: 480-792-7277 Tell: 480-898-9809 Tell: 882-88696-8511 Tell: 91-20-4121-0141 Tell: 454-485-5910 Tell: 454-485-5920	Corporate Office	Australia - Sydney	India - Bangalore	Austria - Wels
Tel: 48-07-92-7200	2355 West Chandler Blvd.	Tel: 61-2-9868-6733	Tel: 91-80-3090-4444	Tel: 43-7242-2244-39
Fax: 480-792-7277	Chandler, AZ 85224-6199	China - Beijing	India - New Delhi	Fax: 43-7242-2244-393
Technical Support	Tel: 480-792-7200	Tel: 86-10-8569-7000	Tel: 91-11-4160-8631	Denmark - Copenhagen
New Microchip cond Sepo	Fax: 480-792-7277	China - Chengdu	India - Pune	Tel: 45-4485-5910
Web Address:	Technical Support:	Tel: 86-28-8665-5511	Tel: 91-20-4121-0141	Fax: 45-4485-2829
Atlanta	www.microchip.com/support	China - Chongqing	Japan - Osaka	Finland - Espoo
Atlanta	Web Address:	Tel: 86-23-8980-9588	Tel: 81-6-6152-7160	Tel: 358-9-4520-820
Duluth, CA	www.microchip.com	China - Dongguan	Japan - Tokyo	France - Paris
Tel: 68-08-79-614	Atlanta	Tel: 86-769-8702-9880	Tel: 81-3-6880- 3770	Tel: 33-1-69-53-63-20
Fax: 678-957-1455	Duluth, GA	China - Guangzhou	Korea - Daegu	Fax: 33-1-69-30-90-79
Austin, TX Tel: 86-571-8792-8115 Tel: 82-2554-7200 Germany - Haam Boston Tel: 852-2943-5100 Tel: 682-2551-7906 Tel: 682-2948-5100 Tel: 60-3-7651-7906 Tel: 49-2129-3766400 Tel: 49-2129-3766400 Tel: 49-2129-3766400 Tel: 49-2129-3766400 Tel: 49-2129-3766400 Tel: 49-721-66400 Tel: 60-3-7651-7906 Malaysia - Kuala Lumpur Tel: 49-721-67200 Tel: 49-721-67200 Tel: 49-721-67200 Tel: 49-721-672400 Tel: 49-721-672400 Tel: 49-721-672400 Tel: 49-721-672570 Tel: 49-721-172400 Tel: 49-721-672570 Tel: 49-721-172400 Tel: 49-721-172400 Tel: 49-721-172400 Tel: 49-721-1725270 Tel: 49-721-1725271 Tel: 49-721-17252	Tel: 678-957-9614	Tel: 86-20-8755-8029	Tel: 82-53-744-4301	Germany - Garching
Tel: 512-257-3370	Fax: 678-957-1455	China - Hangzhou	Korea - Seoul	Tel: 49-8931-9700
Boston	Austin, TX	Tel: 86-571-8792-8115	Tel: 82-2-554-7200	Germany - Haan
Westborough, MA	Tel: 512-257-3370	China - Hong Kong SAR	Malaysia - Kuala Lumpur	Tel: 49-2129-3766400
Tel: 774-760-0087	Boston	Tel: 852-2943-5100	Tel: 60-3-7651-7906	Germany - Heilbronn
Tel: 774-76-0087	Westborough, MA	China - Nanjing	Malaysia - Penang	Tel: 49-7131-72400
Tel: 86-532-8502-7355	-	Tel: 86-25-8473-2460	Tel: 60-4-227-8870	Germany - Karlsruhe
Itasca, IL	Fax: 774-760-0088	China - Qingdao	Philippines - Manila	Tel: 49-721-625370
Itasca, IL	Chicago	Tel: 86-532-8502-7355	Tel: 63-2-634-9065	Germany - Munich
Tel: 630-285-0071 Fax: 630-285-0075 China - Shenyang Dallas Tel: 86-24-233-28-29 Addison, TX China - Shenyang Taiwan - Hsin Chu Tel: 86-24-233-4-2829 Addison, TX China - Shenyang Tel: 86-27-78-3666 Tel: 86-24-233-4-2829 Addison, TX China - Shenyang Tel: 886-3-77-83866 Tel: 89-28-13-354-560 Israel - Ra'anana Tel: 972-818-7423 Tel: 86-75-8864-2200 Tel: 886-7-213-7830 Tel: 972-9-744-7705 Tel: 98-72-818-2924 China - Suzhou Taiwan - Taipei Italy - Milan Tel: 97-9-744-7705 Tel: 886-8-7213-7830 Tel: 972-9-744-7705 Tel: 886-8-7213-7830 Tel: 98-29-803-1526 Novi, MI China - Wuhan Thailand - Bangkok Taix: 39-0331-466781 Tel: 98-29-883-3-7522 Tel: 86-29-833-7522 Tel: 86-29-833-7522 Tel: 86-29-833-7522 Tel: 86-29-833-7522 Tel: 86-29-833-7522 Tel: 86-29-833-7522 Tel: 31-47-73-8323 China - Zhuhai Tel: 86-59-2388138 Tel: 31-773-8323 Tel: 31-73-8323 Tel: 31-73-802 Tel: 919-844-7510 Norway - Trondheim Tel: 49-29-608 Tel: 919-844-7510 New York, NY Tel: 919-844-7510 New York, NY Tel: 63-1-3000 San Jose, CA Tel: 408-735-9110 Tel: 408-735-9110 Tel: 408-735-9110 Tel: 408-735-9110 Tel: 408-735-9110 Tel: 408-735-9110 Tel: 44-118-921-5820 Tel: 919-69-51980	_	China - Shanghai	Singapore	-
Dallas	Tel: 630-285-0071	Tel: 86-21-3326-8000		Fax: 49-89-627-144-44
Dallas	Fax: 630-285-0075	China - Shenyang	Taiwan - Hsin Chu	Germany - Rosenheim
Tel: 972-818-7423 Tel: 86-755-8864-2200 China - Suzhou Tel: 86-86-2-2508-8600 Tel: 86-86-2-2508-8600 Tel: 39-0331-742611 Tel: 39-0331-742611 Tel: 248-848-4000 Tel: 86-27-5980-5300 Tel: 66-2-694-1351 Tel: 86-28-2-8833-7252 Tel: 86-29-8833-7252 Tel: 86-39-2388138 Tel: 317-773-8323 China - Zhuhai Tel: 317-773-8323 Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 99-844-7510 New York, NY Tel: 918-844-7510 New York, NY Tel: 68-2-694-1351 Tel: 84-28-5448-2100 Netherlands - Drunen Tel: 317-778-800 Tel: 408-735-9110 Tel: 86-756-3210040 Tel: 86	Dallas		Tel: 886-3-577-8366	-
Tel: 972-818-7423 Tel: 972-818-7423 Tel: 86-755-8864-2200 China - Suzhou Tel: 86-86-32-31-526 Tel: 86-86-32-31-526 Tel: 86-86-2-2508-8600 Tel: 39-0331-742611 Tel: 39-0331-742611 Tel: 248-848-4000 Tel: 36-27-5980-5300 Tel: 36-2-598-330 Tel: 86-2-598-3500 Tel: 66-2-694-1351 Tel: 89-39-331-466781 Tel: 39-0331-466781 Tel: 39-0331-466781 Tel: 281-894-5983 Tel: 86-29-8833-7252 Tel: 86-29-8833-7252 Tel: 86-2-694-1351 Tel: 84-28-5448-2100 Netherlands - Drunen Indianapolis Noblesville, IN Tel: 86-592-2388138 Tel: 317-773-8323 China - Zhuhai Tel: 317-773-8323 China - Zhuhai Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 99-844-7580 Tel: 99-844-7510 New York, NY Tel: 66-2-694-1351 Tel: 84-28-5448-2100 Netherlands - Drunen Tel: 31-46-690340 Norway - Trondheim Tel: 31-47-7284388 Poland - Warsaw Tel: 48-22-3325737 Romania - Bucharest Tel: 49-24-407-87-50 Spain - Madrid Tel: 349-1708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg New York, NY Tel: 68-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 40-8-4270 Canada - Toronto Tel: 905-695-1980	Addison, TX	China - Shenzhen	Taiwan - Kaohsiung	Israel - Ra'anana
Detroit	Tel: 972-818-7423	Tel: 86-755-8864-2200		Tel: 972-9-744-7705
Detroit	Fax: 972-818-2924	China - Suzhou	Taiwan - Taipei	Italy - Milan
Tel: 248-848-4000 Houston, TX China - Xian Tel: 281-894-5983 Tel: 86-29-8833-7252 Tel: 86-29-8833-7252 Tel: 84-28-5448-2100 Netherlands - Drunen Tel: 31-416-690399 Noblesville, IN Tel: 86-592-2388138 Tel: 86-592-2388138 Tel: 86-592-2388138 Tel: 86-756-3210040 Tel: 317-773-8453 Tel: 86-756-3210040 Tel: 317-536-2380 Los Angeles Mission Viejo, CA Tel: 949-462-9523 Tel: 949-462-9608 Tel: 941-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-336-4270 Canada - Toronto Tel: 905-695-1980 Tel: 905-695-1980 Tel: 905-695-1980 Tel: 905-695-1980 Tel: 66-2-694-1351 Tel: 39-049-7625286 Tel: 39-049-7625286 Tel: 34-0-6090399 Notherlands - Drunen Tel: 31-416-690399 Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-69039	Detroit	Tel: 86-186-6233-1526	Tel: 886-2-2508-8600	Tel: 39-0331-742611
Houston, TX	Novi, MI	China - Wuhan		Fax: 39-0331-466781
Houston, TX	Tel: 248-848-4000	Tel: 86-27-5980-5300	Tel: 66-2-694-1351	Italy - Padova
Indianapolis	Houston, TX	China - Xian	Vietnam - Ho Chi Minh	Tel: 39-049-7625286
Noblesville, IN Tel: 86-592-2388138 China - Zhuhai Tel: 317-773-8323 Tel: 317-773-5453 Tel: 86-756-3210040 Tel: 47-72884388 Tel: 47-72884388 Tel: 48-22-3325737 Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Tel: 905-695-1980 Tel: 86-756-3210040 Tel: 46-31-704-60-40 Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5820	Tel: 281-894-5983	Tel: 86-29-8833-7252	Tel: 84-28-5448-2100	Netherlands - Drunen
Tel: 317-773-8323	Indianapolis	China - Xiamen		Tel: 31-416-690399
Fax: 317-773-5453 Tel: 86-756-3210040 Tel: 47-72884388 Poland - Warsaw Tel: 48-22-3325737 Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 40-8-735-9110 Tel: 40-8-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Tel: 86-756-3210040 Tel: 47-72884388 Poland - Warsaw Tel: 48-22-3325737 Romania - Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 408-735-9110 Tel: 408-436-4270 Fax: 44-118-921-5800 Fax: 44-118-921-5820	Noblesville, IN	Tel: 86-592-2388138		Fax: 31-416-690340
Fax: 317-773-5453 Tel: 86-756-3210040 Tel: 47-72884388 Tel: 317-536-2380 Poland - Warsaw Los Angeles Tel: 48-22-3325737 Mission Viejo, CA Romania - Bucharest Tel: 949-462-9523 Tel: 40-21-407-87-50 Fax: 949-462-9608 Spain - Madrid Tel: 951-273-7800 Tel: 34-91-708-08-90 Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 44-118-921-5800 Tel: 905-695-1980 Fax: 44-118-921-5820	Tel: 317-773-8323	China - Zhuhai		Norway - Trondheim
Los Angeles Tel: 48-22-3325737 Mission Viejo, CA Romania - Bucharest Tel: 949-462-9523 Tel: 40-21-407-87-50 Fax: 949-462-9608 Spain - Madrid Tel: 951-273-7800 Tel: 34-91-708-08-90 Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 UK - Wokingham Tel: 408-436-4270 Fax: 44-118-921-5800 Canada - Toronto Fax: 44-118-921-5820	Fax: 317-773-5453	Tel: 86-756-3210040		
Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980	Tel: 317-536-2380			Poland - Warsaw
Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	Los Angeles			Tel: 48-22-3325737
Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	Mission Viejo, CA			Romania - Bucharest
Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Tel: 951-273-7800 Fax: 34-91-708-08-90 Fax: 34-91-708-08-90 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	=			Tel: 40-21-407-87-50
Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 46-8-5090-4654 Tel: 408-735-9110 UK - Wokingham Tel: 408-436-4270 Tel: 44-118-921-5800 Canada - Toronto Fax: 44-118-921-5820 Tel: 905-695-1980 Tel: 44-118-921-5820	Fax: 949-462-9608			Spain - Madrid
Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Seeden - Stockholm Sweden - Stockholm San Jose, CA Tel: 46-8-5090-4654 Tel: 408-735-9110 UK - Wokingham Tel: 408-436-4270 Tel: 44-118-921-5800 Canada - Toronto Fax: 44-118-921-5820 Tel: 905-695-1980 Tel: 44-118-921-5820	Tel: 951-273-7800			Tel: 34-91-708-08-90
New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 46-8-5090-4654 Tel: 408-735-9110 UK - Wokingham Tel: 408-436-4270 Tel: 44-118-921-5800 Canada - Toronto Fax: 44-118-921-5820 Tel: 905-695-1980 Fax: 44-118-921-5820				Fax: 34-91-708-08-91
Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	Tel: 919-844-7510			Sweden - Gothenberg
Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	New York, NY			_
Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	·			Sweden - Stockholm
Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	San Jose, CA			Tel: 46-8-5090-4654
Tel: 408-436-4270 Tel: 44-118-921-5800 Canada - Toronto Tel: 905-695-1980 Tel: 905-695-1980				UK - Wokingham
Canada - Toronto Fax: 44-118-921-5820 Tel: 905-695-1980 Fax: 44-118-921-5820				_
Tel: 905-695-1980				
Fax. 900-090-2010	Fax: 905-695-2078			