



08-Dec-2022

**PCN #:** PCN-22-156443

**Subject :** SGI2.0 plug housing

**Description of Change :** Please be aware of an upcoming feature change to the listed part numbers.

Before: No ribs on plug housing.

After: To improve reliability, add ribs to reduce the gap between plug assembly and header assembly.

Adjust TPA tooth length to reduce the gap between terminal and TPA

Reference performance test data: Passed verification test. please see attached file for the details.

**Reason :** Update plug housing to make products more reliable.

**Key Dates :**

**Contact By Date:**28-Feb-2023

**Implementation Date:**28-Feb-2023

<b>Product Affected</b>	<b>Alias Part Number</b>	<b>Substitute Part Number</b>	<b>AliasSub Part Number</b>
1-2350224-7			
2-2350224-5			
2-2350224-8			
3-2350224-0			
1-2350224-9			
2-2350224-9			
2-2350224-4			
2-2350224-6			
2-2350224-2			
1-2350224-3			
1-2350224-5			
2-2350224-7			
2-2350224-0			
1-2350224-8			
2-2350224-3			

1-2350224-2			
1-2350224-6			
1-2350224-4			

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.