







STRAIGHT JACK FLANGE, SOLDER CABLE .141

PAGE 1/3 ISSUE 28-06-17B SERIES NEX10 PART NUMBER R180252007









All dimensions are in mm. Tolerances according ISO 2768 m-H



COMPONENTS	MATERIALS	PLATING (μm)
Body Center contact	BRASS. BERYLLIUM COPPER	BBR SILVER
Outer contact	BERTELION COLLEK	SIEVER
Insulator	PTFE	
Gasket Others parts		
-	-	-
-	-	-



Technical Data Sheet

STRAIGHT JACK FLANGE, SOLDER CABLE .141

PAGE 2/3	ISSUE 28-06-17B	SERIES NEX10	PART NUMBER R180252007
-----------------	------------------------	---------------------	-------------------------------

PACKAGING

50	Contact us	Contact us
Standard	Unit	Other

ELECTRICAL CHARACTERISTICS

Impedance			50	Ω
Frequency			0-20	GHz
VSWR	1.02*	+	0.0200	x F(GHz) Maxi
Insertion loss			0.05	√F(GHz) dB Maxi
RF leakage	- (NA	- F(GHz)) dB Maxi
Voltage rating			500	Veff Maxi
Dielectric withstanding voltage	ge		1500	Veff mini
Insulation resistance			5000	$M\Omega$ mini

MECHANICAL CHARACTERISTICS

Center contact retention Axial force - Mating End NA N mini Axial force - Opposite end NA N mini N.cm mini NA Torque

Recommended torque

NA Mating N.cm Panel nut NA N.cm Clamp nut N.cm NA A/F clamp nut 0.0000 mm

Mating life 100 Cycles mini 9.8000

Weight

g

ENVIRONMENTAL

Operating temperature -55/+125 °C Hermetic seal NA Atm.cm3/s Panel leakage NA

SPECIFICATION

CABLE ASSEMBLY

Stripping	а	b	С	d	е	f
mm	3.2	0	0	0	0.85	0

Assembly instruction:

Recommended cable(s)

RG 402

Characteristics indicated on this data sheet are those that can be achieved with the highest performance cable. Intrinsic limitations of the cable may diminish the performance of the assembly

Cable retention

- pull off 200 N mini - torque NA N.cm

TOOLING

Part Number	Description	Hexagon

OTHER CHARACTERISTICS

PIM3<=-123 dBm, 2 carriers of +43dBm




Technical Data Sheet

STRAIGHT JACK FLANGE, SOLDER CABLE .141


PAGE 3/3 ISSUE 28-06-17B SERIES NEX10 PART NUMBER R180252007

COMPONENTS

BODY







- 1
 - -Strip the cable with the cable stripping tool.
 - -Clean the cable

- 3
 - -Introduce the cable into the body until stop.
 - -Place the sub-assembly on assembly jig
 - -Solder body on the cable.
 - -Let assembly cool down before removing it from the jig.

2

- -Insert center contact until the cable
- -Solder center contact

