



15-Sep-2022

PCN #: P-22-023378

Subject : D-099-WASHER-SN63, -SN96, BI58, -PB36, -CD18

Description of Change : The current fabrication of non-precious Indalloy solders, Tape & Reel, and Flux Coated Preforms resides at the Indium Corporation, Business Park Drive location in Utica, NY (BPD). Operations will move the current equipment set, operations staff, and support services for non-precious Indalloy solder Preforms, Tape & Reel, and Flux Coated Preforms to the Indium Corporation, Success Drive, Rome, NY location (RMD).

Reason : Product improvement. Solder WASHER suppliers (Indium) expanding into the Rome, NY facility will allow for immediate capacity growth, accommodate space for additional expansion, and improve supply chain redundancy to ensure customer satisfaction.

Key Dates :

Contact By Date: 15-Sep-2022

Implementation Date: 15-Sep-2022

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
D02886-000	"7-1202000-6", "B-155-9005"		
D42180-001	"B-155-05-RSU"		
A70754-000	"8-1201998-9", "B-155-03"		
A77528-000	"5-1202057-1", "B-155-2003"		
C37054-000	"5-1202057-4", "B-155-2003-B"		
700621N001	"9-1195499-0", "D-146-60-2CS1370"		

C97376-000	"9-1201998-8", "B-155-3813"		
F45323-000	"1-1201999-5", "B-155-23"		
695696-000	"6-1195457-7", "B-044-14"		
E11880-000	"1201999-6", "B-155-17"		
754797N001	"7-1195883-6", "D-146-70-0CS1370"		
F26778-000	"3-1202083-6", "ST58-5-00"		
C91365-001	"B-155-1502-RSU"		
617671N001	"2-1194881-1", "D-146-50-3CS1370"		
695301-000	"6-1195454-1", "B-801-18"		
CA6205-000	"SGRS-2-58"		
552779-000	"8-1194368-7", "RBD-50-S-01"		
E96667-000	"6-1202046-5", "B-155-3806-W1"		
F33741-000	"8-1202000-5", "B-155-11-100-18-9"		
695130-000	"1195453-4", "W-040-18"		
EM1221-000	"SGRS-3-96"		
E99092-000	"2-1202030-4", "B-155-05-35-22-5"		
644529-000	"3-1195091-1", "CWT-4174-W122-5/9"		
CF1177-000	"ST58-3-55-22-90", "1899345-8"		

821474-000	"8-1202065-1", "D-584-1201-24-X9"		
502982-000	"1-1202054-5", "B-155-4174-22-09-01"		
696474-000	"6-1195463-4", "B-801-19"		
CB0137-000	"B-155-3811-RSU", "8-1899222-0"		
D18089-000	"B-155-9003-5000"		
C20235-000	"9-1201998-2", "B-155-09"		
D34796-000	"1201999-2", "B-155-3801"		
CB7569-000	"B-155-008-11"		
C78009-001	"B-155-3805-RSU"		
627567N001	"2-1194969-2", "D-146-50-4CS1370"		
A88975-001	"B-155-07-RSU"		
A88975-000	"9-1201998-0", "B-155-07"		
115204-000	"6-1190839-4", "D-146-0206"		
719303-000	"1-1195626-0", "RTD-75-S-01"		
F09513-000	"1-1202037-7", "B-155-11-S"		
F33138-000	"2-1202037-5", "B-155-07-S"		
918455-000	"2-1197128-7", "RBD-75-S-00"		
C78009-000	"9-1201998-7", "B-155-3805"		

F75166-000	"4-1202054-0", "B-155-3807-W2-T"		
E78945-000	"2-1202030-3", "B-155-03-35-22-5"		
728269-000	"7-1195690-8", "RTD-50-L-04"		
680864-000	"9-1195354-8", "B-801-08"		
572303N001	"8-1194542-3", "D-146-50-1CS1370"		
624513-000	"8-1194941-0", "D-146-0208"		
CF6147-000	"B-044-24-N-LF"		
E77815-000	"2-1202048-9", "B-155-1503"		
D62910-000	"8-1202000-0", "B-155-05-100-18-9"		
E39668-001	"B-155-13-RSU"		
C17488-000	"9-1201998-1", "B-155-3807"		
C21881-000	"7-1202000-4", "B-155-9004"		
132195-000	"7-1190960-3", "RBD-50-L-00"		
C47348-000	"9-1201998-5", "B-155-33"		
919975N001	"9-1197138-1", "D-146-60-4CS1370"		
D03269-000	"1-1202030-7", "B-155-07-35-22-5"		

C39701-000	"9-1201998-4", "B-155-3810"		
E39668-000	"1-1201999-0", "B-155-13"		
C26089-000	"B-155-9002-NV"		
438635N001	"5-1193296-6", "D-146-0270-0CS1370"		
524635-000	"1194121-1", "RTD-50-L-02"		
857483-000	"6-1196682-8", "RBD-75-L-00"		
F78598-000	"3-1202048-2", "B-155-1504"		
CB7571-000	"B-155-008-14"		
E02712-000	"B-155-9001-NV"		
063567N001	"1-1190480-5", "D-146-60-0CS1370"		
250449N001	"9-1191835-9", "D-146-50-5CS1370"		
881889-000	"1-1196865-9", "RBD-50-L-02"		
A70754-001	"B-155-03-RSU"		
536389-000	"6-1194210-2", "RBD-50-L-03"		
A13251-000	"6-1202061-8", "D-584-1224-90/9"		
CB0141-000	"2-1899215-9", "B-155-4174-35-22-5/9-10-RSU"		
690802-000	"1-1195424-3", "B-028-00"		
D26022-000	"1201999-1", "B-155-3802"		

223723-000	"1191648-6", "RTD-50-L-01"		
D18609-000	"6-1202036-3", "B-155-07-F"		
449255-000	"1193375-8", "RBD-50-S-02"		
E74832-000	"8-1202000-3", "B-155-9003"		
157323N001	"8-1191136-7", "D-146-50-7CS1370"		
695463-000	"9-1195455-8", "B-801-36"		
690921-000	"1-1195425-5", "W-040-04"		
F40876-000	"8-1202000-7", "B-155-9002"		
F48562-000	"3-1202054-6", "B-155-4059-22-09-01"		
842399-000	"4-1196571-8", "RBD-75-S-01"		
591691-000	"1-1194680-9", "RBD-75-S-04"		
CB6796-000	"B-155-008-13-NV"		
912481N001	"6-1201210-7", "RBD-50-S-00CS2834"		
C17488-001	"B-155-3807-RSU"		
E38778-000	"1201999-9", "B-155-3803"		
859081-000	"1-1196694-6", "PBD-75-L-00"		
572829-000	"9-1194547-9", "RBD-50-L-04"		
695124-000	"1195453-1", "B-801-16"		

F78985-000	"8-1202000-9", "B-155-07-100-18-9"		
EM1222-000	"SGRS-4-96"		
C67976-000	"7-1202000-5", "B-155-9001"		
816155-000	"4-1196360-6", "D-146-60-0CS670"		
EM1220-000	"SGRS-2-96"		
502971-000	"9-1193785-1", "CWT-4058-W122-5/9"		
310412-000	"1202083-2", "ST58-4-00"		
CA9682-000	"B-155-03-20K"		
CB7572-000	"B-155-008-15"		
E31307-000	"9-1202036-9", "B-155-01-01"		
A42002-000	"1-1202036-0", "B-155-00-01"		
312537-000	"4-1192364-4", "RBD-50-L-01"		
A83240-000	"8-1202065-7", "D-584-1202-24-90"		
CA8389-000	"D-210-0172-LT"		
F30339-000	"3-1202083-8", "ST58-1-00"		
196799-000	"8-1191426-9", "RTD-75-S-00"		
883641-000	"3-1196877-8", "RTD-50-S-01"		
EM1219-000	"SGRS-1-96"		
D61414-000	"2-1202048-4", "B-155-1501"		

D26022-001	"B-155-3802-RSU"		
D42180-000	"1201999-3", "B-155-05"		
CB6800-000	"B-155-008-15-NV"		
263641-000	"4-1191940-4", "CWT-4059-W122-5/9"		
F86517-000	"3-1202030-2", "B-155-09-35-22-5"		
680881-000	"1-1195355-8", "B-801-06"		
E38778-001	"B-155-3803-RSU"		
CB0138-000	"B-155-3813-RSU", "8-1899222-1"		
F60401-000	"2-1202030-8", "B-155-06-35-22-5"		
CB7570-000	"B-155-008-13"		
F53782-000	"3-1202037-0", "B-155-05-F"		
696245-000	"7-1195461-0", "B-804-10"		
905497-000	"9-1197035-9", "RTD-50-S-00"		
C63448-000	"1-1202083-7", "ST58-2-00"		
912481-000	"1-1197086-2", "RBD-50-S-00"		
323783-000	"6-1192450-3", "RTD-50-L-00"		
622025-000	"2-1194916-0", "D-144-25"		
C19970-000	"B-155-9002-5000"		

696059-000	"2-1195460-1", "B-801-15-01"		
F80290-000	"B-155-4174-35-22-5/9-10"		
A39093-000	"8-1201998-5", "B-155-11"		
C58264-000	"B-600-07"		
A65775-000	"1-1202030-1", "B-155-11-35-22-5"		
485251-000	"5-1193631-5", "RBD-75-L-01"		
CB0145-000	"B-155-MIXT-01-RSU", "8-1899222-4"		
A49199-000	"8-1201998-6", "B-155-3809"		
F10286-000	"6-1202046-6", "B-155-3809-W1"		
C91365-000	"2-1202048-2", "B-155-1502"		
A60679-000	"1-1202054-8", "B-155-3805-W2-T"		
F43936-000	"1-1201999-4", "B-155-3811"		
E22982-000	"5-1202046-9", "B-155-3807-W1"		
453315N001	"5-1193403-5", "D-146-0260-0CS1370"		
624512-000	"7-1194941-8", "D-146-0207"		
D17733-000	"7-1202000-8", "B-155-17-100-18-9"		

C13653-000	"1-1202083-4", "ST58-3-00"		
F27848-000	"2-1202030-5", "B-155-13-35-22-5"		
F52554-000	"2-1202045-6", "B-155-07-55-20-9"		
728269N001	"6-1201210-1", "RTD-50-L-04CS2834"		
C63309-000	"9-1201998-6", "B-155-3806"		
E21385-000	"1201999-7", "B-155-06"		
A39093-001	"B-155-11-RSU"		
842531-000	"3-1196572-7", "RTD-50-S-04"		
765475-000	"1-1195959-1", "RTD-50-S-02"		
CB6798-000	"B-155-008-14-NV"		
A74711-000	"1-1202054-9", "B-155-4174-35-22-5/9"		
A11769-000	"9-1200570-5", "D-150-0321"		
696599-000	"1195465-5", "B-801-48"		
905341-000	"8-1197034-3", "RTD-75-S-04"		
D74720-000	"8-1202036-3", "B-155-05-S"		
702377-000	"3-1195511-3", "RTD-50-L-03"		
E79815-000	"8-1202000-4", "B-155-13-100-18-9"		

CA4618-000	"ST58-7-00"		
F08112-000	"6-1202057-6", "B-155-2003-A"		
255167N001	"1-1191868-6", "D-146-60-3CS1370"		
D61414-001	"B-155-1501-RSU"		
519641-000	"3-1194077-6", "RTD-75-L-02"		
F00831-000	"1-1202037-5", "B-155-02-01"		
918911-000	"2-1197131-0", "RBD-75-S-03"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.