PCN Information March 2019

Affected Products – RAC15-SK and RAC20-SK AC/DC Converters

Dear customers and distributors, we herewith inform you about a product change in the following products:

Art #	Recom Products	Art #	Recom Products
20001181	RAC15-3.3SK	**20001167**	RAC20-05SK
20001182	RAC15-05SK	**20001168**	RAC20-12SK
20001183	RAC15-12SK	**20001169**	RAC20-15SK
20001184	RAC15-15SK	**20001170**	RAC20-24SK
20001185	RAC15-24SK	**20001171**	RAC20-48SK
20001192	RAC15-05SK/W	**20001172**	RAC20-12DK
20001193	RAC15-12SK/W	**20001173**	RAC20-15DK
20001194	RAC15-15SK/W	**20001195**	RAC20-05SK/W
		20001196	RAC20-12SK/W
		20001197	RAC20-15SK/W
		20001198	RAC20-24SK/W
		20001199	RAC20-48SK/W

Please note that due to an error, the isolation withstand voltage was given as 4kVAC instead of 3kVAC in the original datasheets. This error has now been corrected. Please ensure that any local or cached copies of the original datasheet have been replaced with the corrected version. There has been no change to the converter itself.

Issue Date: 20 March 2019

Steve Roberts
Technical Director
RECOM Engineering, Gmunden, Austria

For further information, please contact our sales teams:

Europe: Tel: +49 (0) 6102-88381-0 or info@recom-electronic.com
Asia: Tel: +65 62768795 or enquiry@recom-power.com
North-America: Tel: +1-720-386-0400 or admin@recom-power.com