Dimensions

Technical data

General specifications

Inside diameter	18 mm

Mechanical specifications

Material	Clamping cylinder: Diecast zinc Support bracket: Steel

Installation instructions

① Fasten the two parts of the mounting clamp (a) loosely by means of the screw (b) and the nut (c) supplied.

② Attach the mounting bracket (d) and then tighten the screw (b) in such a way that the bracket can still be turned.

③ Tighten the screw fully after the sensor has been mounted and aligned.

## Model Number

MH 01-M18

Mounting brackets for sensors

Features

- Suitable for M18 sensors
- Simple and fast mounting

Refer to "General Notes Relating to Pepperl+Fuchs Product Information".

Pepperl+Fuchs Group	USA: +1 330 486 0001	Germany: +49 621 776 4411	Singapore: +65 6779 9091
www.pepperl-fuchs.com	fa-info@us.pepperl-fuchs.com	fa-info@de.pepperl-fuchs.com	fa-info@sg.pepperl-fuchs.com

PEPPERL+FUCHS
SENSING YOUR NEEDS

1