# 12.02.1119

USB Type C 4-Port Docking Station

User Manual

How to Connect

- Connect the docking station directly to your computer, no extra driver required.

- Connect your USB devices to any of the USB ports; HDMI to a HDTV or monitor, USB-C for extra power charging and data transfer.

Diagram

Specification

- 2x USB 3.2 Gen1 port--(Transfer Speed up to 5Gbps)
- 1x HDMI--(max. 4K/30Hz)
- 1x USB-C-- (20V/5A 100W, Data Transfer Speed up to 5Gbps)
- Material: Aluminum + ABS
- Overall Length: 23cm
- Weight: 40±5g

Features

- HDMI output max resolution up to 4K30Hz.

- USB3.2 Gen1 A/F *2 support max data up to 5Gbps

- USB-C Receptacle: PD charge 20V/5A and Data Transfer up to 5Gbps