




Measuring tip




A = Width mm
B = Thickness mm
C = Length mm





Model	A	B	C	PU	Order No.
Measuring tip 			40	1	T005 44 722 99

Sloped




A = Width mm
B = Thickness mm
C = Length mm


Model	A	B	C	PU	Order No.
Measuring tip 				1	T005 44 731 99
XT Soldering head 10 x 4 mm, spare 				1	T005 44 731 90
Measuring tip 	4		20	1	T005 44 732 99

Model	A	B	C	PU	Order No.
Measuring tip 			20	1	T005 44 732 90
Measuring tip 	4		33	1	T005 44 733 99
Measuring tip 	4		33	1	T005 44 733 90
Measuring tip 			40	1	T005 44 734 99

Einschraubspitze

A = Width mm
B = Thickness mm
C = Length mm

Model	A	B	C	PU	Order No.
XT Einschraubspitze M4 veredelt 	M4		36	1	T005 44 719 99

Model	A	B	C	PU	Order No.
XT Einschraubspitze M5 veredelt 	M5		36	1	T005 44 720 99