

1 Products affected

Product hierarchy no. * Part no. SBU	Type / Description
SBU PG PUG Type	
01 001 023 0000000351 See list below Circuit Prote	ection UMF 250

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected				
3405.0176.11	3405.0176.24			

^{*}SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

Change of Approval Change of Label Change of Marking

3 Detailed description of change

The 10A version got newly approved by VDE on the IEC 60127-7. Since this part 7 doesn't allow to use some reserved characters, we change the product marking and labels accordingly.



4 Reason of change

The 10A version was originally not approved by VDE. To meet new customer demand, we approved this fuse according to IEC 60127-7.

5 Release date

The change is available from ww 25/2020 (production date code 2025 or higher).

6 Impact of change and recommended action

Form	No	No action recommended
Fit	No	No action recommended
Function	No	No action recommended
Manufacturing	No	No action recommended

Product Change Notification			UMF 250 10A marking				
owner	creation date	release date	released by	change order no	rev	page	D40 040 040
schmidre	22.06.2020	24.06.2020	haeckima	2020169	Α	1 of 2	D10-046-613



Label Yes No action recommended since the fuse itself hasn't changed

Packaging No No action recommended

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	

Product Change Notification			UMF 250 10A marking				
owner	creation date	release date	released by	change order no	rev	page	D10-046-613
schmidre	22.06.2020	24.06.2020	haeckima	2020169	Α	2 of 2	