



Product Change Notification



Product Group: Vishay Dale/July 30, 2013/PCN-DI-184-2013 Rev 0

IHLP-8787MZ-5A data change

DESCRIPTION OF CHANGE: The IHLP-8787MZ-5A series has been re-designed and all electrical data has changed to reflect these design changes.

CLASSIFICATION OF CHANGE: Assembly Process/Structure

REASON FOR CHANGE: To correct errors on the data sheet.

EXPECTED INFLUENCE ON QUALITY/RELIABILITY/PERFORMANCE: None.

PRODUCT CATEGORY: Inductors

PART NUMBERS/SERIES/FAMILIES AFFECTED: IHLP8787MZERR22M5A IHLP8787MZERR47M5A
IHLP8787MZERR1R0M5A IHLP8787MZERR3R3M5A IHLP8787MZERR4R7M5A
IHLP8787MZERR6R8M5A IHLP8787MZERR100M5A IHLP8787MZERR150M5A
IHLP8787MZERR750M5A IHLP8787MZERR820M5A IHLP8787MZERR101M5A

VISHAY BRAND(s): Vishay Dale

TIME SCHEDULE: July 30, 2013

SAMPLE AVAILABILITY: N/A

PRODUCT IDENTIFICATION: N/A

QUALIFICATION DATA: N/A

ISSUED BY: Doug Lillie, Product Marketing Manager

For further information, please contact your regional Vishay office.

CONTACT INFORMATION:

The Americas

Vishay Intertechnology, Inc
1505 East Highway 50
P. O. Box 180
Yankton, South Dakota 57078
Ph: 1 605-665-9301
Fax: 1 605-665-1627
doug.lillie@vishay.com

Europe

Vishay Electronic GmbH
Dr.-Felix-Zandman-Platz 1
95100 Selb
Germany
Ph: 49-9287-71-2282
Fax: 49-9287-71-2496
jens.walther@vishay.com

Asia

Vishay Asia Pte Ltd.
25 Tampines Street 92
Keppel Building #02-00
Singapore 528877
Ph: +65-788-6668
Fax: +65-788-3383
victor.goh@vishay.com