

## Product Advisory

Issue Date: 24-August-2023

**Change Description:**







Change bundling material for TUBE and TRAY from using rubber band to ESD Conductive Grid Tape.

**Parts Affected:**

AFBR-1521CZ	AFBR-395075RZ	HFBR-1402Z	HFBR-1533Z	HFBR-2533Z	QFBR-5813TQZ-SI
AFBR-1528CZ	AFBR-57B4APZ	HFBR-1404Z	HFBR-1537Z	HFBR-2541ETZ	QFBR-5813TZ-SI
AFBR-1529Z	AFBR-57B4APZC	HFBR-1412PTZ	HFBR-1541ETZ	HFBR-2541Z	QFBR-5813Z-SI
AFBR-1531CZ	AFBR-57E6APZ	HFBR-1412PZ	HFBR-1542ETZ	HFBR-2542ETZ	QFBR-5823QZ-SI
AFBR-1539Z	AFBR-57E6APZC	HFBR-1412TMZ	HFBR-1602Z	HFBR-2555AFZ	QFBR-5823TQZ-SI
AFBR-1541CZ	AFBR-57E6APZ-EN1	HFBR-1412TZ	HFBR-1604Z	HFBR-2602Z	QFBR-5969ALZ
AFBR-1549SZ	AFBR-57E6APZ-EX1	HFBR-1412Z	HFBR-2316TZ	HFBR-57E0ALZ	QFBR-5975TZ
AFBR-1555ARZ	AFBR-57E6APZ-HT	HFBR-1414MZ	HFBR-2402Z	HFBR-57E0APZ	QFBR-5978AZ
AFBR-1624Z	AFBR-5803AQZ	HFBR-1414PMZ	HFBR-2406Z	HFBR-57E0APZ-CS7	QFBR-5978AZ-2
AFBR-1629Z	AFBR-5803ATQZ	HFBR-1414PTZ	HFBR-2412MZ	HFBR-57E0APZ-EM1	QFBR-5978AZ-SI1
AFBR-1634Z	AFBR-5803ATZ	HFBR-1414PZ	HFBR-2412TCZ	HFBR-57E0LZ	QFBR-590CZ
AFBR-1639Z	AFBR-5803AZ	HFBR-1414TZ	HFBR-2412TZ	HFBR-57E0PZ	QFBR-POL212001N
AFBR-1644Z	AFBR-5803TZ	HFBR-1414Z	HFBR-2412Z	HFBR-57E5APZ	QFBR-R300CZ
AFBR-1715TZ	AFBR-5803Z	HFBR-1415PMZ	HFBR-2414TZ	HFBR-5961AGZ	QFBR-R463CZ
AFBR-2408Z	AFBR-5805ATZ	HFBR-1415PZ	HFBR-2414Z	HFBR-5961ALZ	QFBR-R518Z
AFBR-2409Z	AFBR-5805AZ	HFBR-1415TZ	HFBR-2416MZ	HFBR-5961LZ	QFBR-R521Z
AFBR-2413MZ	AFBR-5805TZ	HFBR-1415Z	HFBR-2416TCZ	HFBR-5963ALZ	QFBR-R531Z
AFBR-2418MZ	AFBR-5805Z	HFBR-1424Z	HFBR-2416TZ	HFBR-5963LZ	QFBR-R629Z
AFBR-2418TZ	AFBR-5813QZ	HFBR-1454Z	HFBR-2416Z	HFBR-5984LZ	QFBR-R90537VRZ
AFBR-2418Z	AFBR-5813TQZ	HFBR-14E4Z	HFBR-2422Z	QFBR-1478CZ	QFBR-RB5Z
AFBR-2419MZ	AFBR-5823QZ	HFBR-1505AFZ	HFBR-2452Z	QFBR-1547ETZ	QFBR-RB5ZSL
AFBR-2419TZ	AFBR-5903AZ	HFBR-1505AZ	HFBR-24E2Z	QFBR-1548Z	QFBR-RH21Z
AFBR-2419Z	AFBR-5903EZ	HFBR-1505CFZ	HFBR-24E6Z	QFBR-1549Z	QFBR-T081Z
AFBR-2521CZ	AFBR-5903Z	HFBR-1505CZ	HFBR-2505AFZ	QFBR-1551Z	QFBR-T261Z
AFBR-2528CZ	AFBR-5905AZ	HFBR-1506AFZ	HFBR-2505AZ	QFBR-1570Z	QFBR-T478Z
AFBR-2529RZ	AFBR-5972BZ	HFBR-1515BFZ	HFBR-2505CFZ	QFBR-1573Z	QFBR-T518Z
AFBR-2529SIZ	AFBR-5972EZ	HFBR-1515BZ	HFBR-2505CZ	QFBR-2478Z	QFBR-T521Z
AFBR-2529Z	AFBR-5972Z	HFBR-1517Z	HFBR-2506AFZ	QFBR-24T2Z	QFBR-T531Z
AFBR-2531CZ	AFBR-5978Z	HFBR-1520Z	HFBR-2515BFZ	QFBR-2542ETZ	QFBR-T629Z
AFBR-2539Z	AFBR-59E4APZ	HFBR-1521ETZ	HFBR-2515BZ	QFBR-2548Z	QFBR-T631Z
AFBR-2541CZ	AFBR-59E4APZC	HFBR-1521Z	HFBR-2521ETZ	QFBR-2549Z	QFBR-T90537VRZ
AFBR-2555ARZ	AFBR-59E4APZ-HT	HFBR-1522ETZ	HFBR-2521Z	QFBR-2551Z	QFBR-TB5Z
AFBR-2624Z	AFBR-59E4APZ-LH	HFBR-1522Z	HFBR-2522ETZ	QFBR-2555AFZ	QFBR-TB5ZSL
AFBR-2634Z	AFBR-59E4APZ-SI1	HFBR-1523Z	HFBR-2522Z	QFBR-2573Z	QFBR-TH21Z
AFBR-2644Z	AFBR-59F2Z	HFBR-1524Z	HFBR-2523Z	QFBR-2P44Z	QFBR-TR01BZ
AFBR-390500RZ	AFBR-POC204L	HFBR-1525EZ	HFBR-2524Z	QFBR-5591Z	QFBR-TR04Z
AFBR-390525RZ	AFBR-POC206L	HFBR-1527ETZ	HFBR-2525EZ	QFBR-5592Z	QFBR-TR11Z
AFBR-390550ROZ	AFBR-POC404L	HFBR-1527Z	HFBR-2526ETZ	QFBR-5751APZ	QFBR-TR15AZ
AFBR-390550RZ	AFBR-POC406L	HFBR-1528Z	HFBR-2526Z	QFBR-5751APZ-SI1	QFBR-TRF2ABZ
AFBR-390575RZ	AFBR-S10RX021Z	HFBR-1531ETZ	HFBR-2531ETZ	QFBR-5751APZ-SI2	QFBR-TT02Z
AFBR-395000RZ	AFBR-S10RX031Z	HFBR-1531Z	HFBR-2531Z	QFBR-5751APZ-SI3	QFBR-TT03Z
AFBR-395025RZ	AFBR-S10TRO01Z	HFBR-1532ETZ	HFBR-2532ETZ	QFBR-5751APZ-SIA	QFBR-TT12Z
AFBR-395050RZ	HFBR-1312TZ	HFBR-1532Z	HFBR-2532Z	QFBR-5813QZ-SI	QFBR-TT14AZ

**Description and Extent of Change:**

Change bundling material for TUBE and TRAY from using rubber band to ESD Conductive Grid Tape as below photo example.

Packaging	Current Packaging: Rubber Band	New Packaging: ESD Conductive Grid Tape
TUBE with vacuum seal		
TUBE		
TRAY		

**Reasons for Change:**

To reduce the risk of TUBE and TRAY deformation.

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

No change in Fit, Form and Function on the product.

**Effective Date of Change:**

Product shipments using this change will begin after 09/11/2023. Timing of shipment of the changed part will vary by part number depending on customer demand, and inventory levels.

---

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.