



# Product Change Notification

Current Date: 27-Jul-2022

## TE Connectivity

Product Change Notification: P-22-023023

PCN Date: 08-JUL-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

Zero Halogen Sheath Material

### Description of Changes

Updating TE WCD2015 specification from version 5 to version 6. 1.Updating the format and title to Zero Halogen Sheath Material 2.Adding additional continuous operating temperature rating for 120 deg. C 3.Accelerated ageing test regime updated to be aligned with Def Stan 61-12 Part 31 4.Water uptake test was amended, 3% of NaCl was added.

### Reason for Changes:

Document clarification.Document Update

### Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

18-JUL-2022

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1054663001</a>	NO		5-1199016-8, 7522A1811-0(4M)			
<a href="#">1221413001</a>	NO		9-1190888-1, 44M9996-26-0/2L-0			
<a href="#">1264313001</a>	NO		9-1190918-3, 99T1121-18-0/9-0			
<a href="#">1284473001</a>	NO		3-1190933-8, 44M9997-22-2/4/6-0			
<a href="#">1290913001</a>	NO		5-1190937-9, 44M9997-20-0/6/9-0(M)			
<a href="#">1330073001</a>	NO		1190966-1, 5020A1811-0(M)			
<a href="#">1340613001</a>	NO		4-1190974-2, 44M9997-16-2/4/6-0			
<a href="#">1364233001</a>	NO		1190989-9, 5020A3811-0			
<a href="#">1472513001</a>	NO		2-1191064-3, 44M9996-16-0/2-0(CO)			
<a href="#">1490543001</a>	NO		8-1199484-2, 5020A1811-0(12M)			
<a href="#">1565053001</a>	NO		9-1191130-3, 99T1121-16(S106)			
<a href="#">1593473001</a>	NO		3-1191151-6, 7524A1811-0(CO)			
<a href="#">1716253001</a>	NO		5-1191248-2, 44M9995-18-9-0			
<a href="#">1735213001</a>	NO		1-1191262-7, 44M9997-16-0/2/7-0			
<a href="#">1781473001</a>	NO		5-1191295-3, 44M9997-20-2/6/9-0			
<a href="#">1849113001</a>	NO		9-1191342-5, 44M9996-22-2L/9-0(CO)			
<a href="#">1850013001</a>	NO		5-1191343-9, 44M9997-20-0/2/7-0			
<a href="#">1864333001</a>	NO		8-1191353-2, 44M9996-22-1/9-0			
<a href="#">1930173001</a>	NO		1-1191400-2, 44M9997-22-2L/2L/2L-0			
<a href="#">1982513001</a>	NO		3-1191436-5, 99T7112-24-0/9-0			
<a href="#">1991013001</a>	NO		3-1191442-2, 44M9996-18-0/2L-0			
<a href="#">2004773001</a>	NO		7-1191452-1, 99T1131-16(S106)			
<a href="#">2026093001</a>	NO		8-1191468-9, 44M9997-24-2L/2L/2L-0			
<a href="#">2105953001</a>	NO		8-1191525-3, 44M9996-16-0/7-0(CO)			
<a href="#">2115513001</a>	NO		5-1191532-7, 44M9995-22-2-0(CO)			
<a href="#">2115953001</a>	NO		8-1191532-6, 7518A1811-0(CO)			
<a href="#">2229553001</a>	NO		7-1191642-3, 44M9995-16-2-0			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">2247533001</a>	NO		5-1191655-8, <b>99T1121-20-2/6-0</b>			
<a href="#">2485113001</a>	NO		6-1191822-6, <b>7522A1811-0</b>			
<a href="#">2590013001</a>	NO		9-1191894-2, <b>44M9996-20-2/2L-0</b>			
<a href="#">2599613001</a>	NO		9-1191901-4, <b>EPD51573A</b>			
<a href="#">2666913001</a>	NO		7-1191968-6, <b>44M9997-22-0/9/2L-0</b>			
<a href="#">2792563001</a>	NO		9-1192066-1, <b>44M9995-20-2L</b>			
<a href="#">2814313001</a>	NO		1-1192085-9, <b>5012A3811-0(CO)</b>			
<a href="#">2947573001</a>	NO		2-1192233-3, <b>44M9996-20-0/2L-0</b>			
<a href="#">2949713001</a>	NO		7-1192234-7, <b>5024A1811-0(CO)</b>			
<a href="#">3102453001</a>	NO		8-1192348-9, <b>44M9995-16-0-0(CO)</b>			
<a href="#">3120153001</a>	NO		1-1192361-0, <b>44M9995-16-0-0</b>			
<a href="#">3171853001</a>	NO		2-1192403-3, <b>5012A3811-0</b>			
<a href="#">3204833001</a>	NO		6-1192429-9, <b>99T1121-14-0/9-0(S106)</b>			
<a href="#">3450593001</a>	NO		1192598-6, <b>44M9996-22-2/6-9</b>			
<a href="#">3590233001</a>	NO		8-1192693-6, <b>44M9996-24-0/6-0(CO)</b>			
<a href="#">3782133001</a>	NO		1192832-6, <b>5024A1811-0</b>			
<a href="#">3942233001</a>	NO		4-1192957-9, <b>44M9995-26-2L-0</b>			
<a href="#">3979193001</a>	NO		2-1192984-4, <b>44M9996-24-0/2-0(CO)</b>			
<a href="#">3995793001</a>	NO		5-1192998-8, <b>44M9996-24-0/9-0</b>			
<a href="#">4041503001</a>	NO		8-1193050-4, <b>44M9996-22-2/6-0</b>			
<a href="#">4087693001</a>	NO		3-1193083-7, <b>44M9996-20-0/7-0</b>			
<a href="#">4113353001</a>	NO		3-1193102-2, <b>44M9997-22-0/2/7-0(CO)</b>			
<a href="#">4121193001</a>	NO		3-1193108-3, <b>44M9997-22-2/4/6-0(CO)</b>			
<a href="#">4275653001</a>	NO		1193217-5, <b>44M9995-24-2L-0(CO)</b>			
<a href="#">4276993001</a>	NO		1193218-7, <b>7520A1311-0(M)</b>			
<a href="#">4342713001</a>	NO		9-1193265-9, <b>99T1121-20-0/9-0(CO)</b>			
<a href="#">4365413001</a>	NO		4-1193281-7, <b>44M9996-20-2/6-0</b>			
<a href="#">4414673001</a>	NO		5-1193319-8, <b>5024A1811-0(M)</b>			
<a href="#">4538213001</a>	NO		7-1193406-8, <b>44M9995-24-2L-0</b>			
<a href="#">4619753001</a>	NO		1193465-9, <b>99T1121-18-4/9-0</b>			
<a href="#">4644273001</a>	NO		4-1193482-8, <b>7520A1811-0(M)</b>			
<a href="#">4673273001</a>	NO		8-1193502-2, <b>44M9995-22-9-0(M)</b>			
<a href="#">4708693001</a>	NO		2-1193528-5, <b>44M9997-16-2/4/6-0(CO)</b>			
<a href="#">4750893001</a>	NO		<b>8-1193558-1</b>			
<a href="#">4815313001</a>	NO		5-1193604-1, <b>99T1121-20-0/9-0(M)</b>			
<a href="#">4821173001</a>	NO		9-1193608-6, <b>44M9996-24-0/2L-0</b>			
<a href="#">4885483001</a>	NO		4-1193655-6, <b>7526A1811-0</b>			
<a href="#">4922153001</a>	NO		7-1899255-0, <b>7820D0831-0</b>			
<a href="#">4946093001</a>	NO		1193699-3, <b>99T7112-22-0/6-0(CO)</b>			
<a href="#">5062133001</a>	NO		6-1193927-6, <b>44M9995-22-9-0</b>			
<a href="#">5088053001</a>	NO		1-1194000-1, <b>44M9996-22-0/2-0(CO)</b>			
<a href="#">5089893001</a>	NO		3-1194001-6, <b>7524A1811-0(M)</b>			
<a href="#">5138033001</a>	NO		8-1194036-6, <b>44M9996-22-0/6-0(CO)</b>			
<a href="#">5309393001</a>	NO		9-1194169-7, <b>CLFH178</b>			
<a href="#">5322373001</a>	NO		3-1194179-1, <b>44M9996-16-0/7-0</b>			
<a href="#">5446613001</a>	NO		4-1194272-4, <b>99T7113-22-0/8/9-02(CO)</b>			
<a href="#">5552813001</a>	NO		1-1194381-8, <b>44M9995-20-2-0(CO)</b>			
<a href="#">5565033001</a>	NO		1194390-4, <b>99T1131-20-0/4/9-0</b>			
<a href="#">5666293001</a>	NO		5-1194474-9, <b>CLFH179(S50)</b>			
<a href="#">5669593001</a>	NO		8-1194476-0, <b>44M9995-16-2L-0</b>			
<a href="#">5754993001</a>	NO		2-1194567-0, <b>99T7113-22-0/8/9-05(CO)</b>			
<a href="#">5757493001</a>	NO		8-1194568-6, <b>44M9996-20-0/7-0(CO)</b>			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5774563001</a>	NO		4-1198981-6, CLFH400			
<a href="#">5788873001</a>	NO		4-1194588-3, 44M9997-20-0/2/7-0(CO)			
<a href="#">5812693001</a>	NO		"2020E0811-0"			
<a href="#">5819033001</a>	NO		8-1194609-5, 44M9995-26-9-0			
<a href="#">5888353001</a>	NO		6-1194659-4, 44M9997-20-2/4/6-0(CO)			
<a href="#">5932033001</a>	NO		6-1194690-8, 44M9996-22-0/6-0			
<a href="#">5973693001</a>	NO		9-1194723-7, 99T7112-22-0/8-0(CO)			
<a href="#">5982693001</a>	NO		4-1194730-8, 0024E0811-0(M)			
<a href="#">6002163001</a>	NO		5-1199425-1, 44M9997-20-2/5/6-0(CO)			
<a href="#">6042073001</a>	NO		1194781-7, 7520A1811-0			
<a href="#">6076173001</a>	NO		5-1194806-6, 7522A1811-0(CO)			
<a href="#">6129293001</a>	NO		6-1194845-6, 44M9997-22-0/2/7-0			
<a href="#">6326573001</a>	NO		2-1195005-3, 44M9997-24-2/6/9-0(CO)			
<a href="#">6330733001</a>	NO		1-1195008-9, 5020A3811-0(CO)			
<a href="#">6369613001</a>	NO		4-1195036-7, 44M9996-14-0/2L-0			
<a href="#">6402493001</a>	NO		5-1195060-4, 44M9996-20-0/2L-0(CO)			
<a href="#">6418473001</a>	NO		7-1195072-4, 44M9997-22-2/6/9-0(M)			
<a href="#">6474833001</a>	NO		3-1195112-0, 44M9995-22-2L-0(CO)			
<a href="#">6553073001</a>	NO		3-1195169-7, 44M9996-24-2/6-0			
<a href="#">6647563001</a>	NO		4-1199422-1, 7524A1811-0(3M)			
<a href="#">6651093001</a>	NO		8-1195240-9, 44M9995-16-2-0(CO)			
<a href="#">6921913001</a>	NO		1-1195434-8, 44M9996-24-0/9-0(CO)			
<a href="#">6943913001</a>	NO		1-1195448-4, 5026A1811-0(CO)			
<a href="#">6969513001</a>	NO		6-1195469-6, 44M9996-24-2/6-0(CO)			
<a href="#">7167633001</a>	NO		4-1195607-4, 99T1161-16(S106)			
<a href="#">7187613001</a>	NO		2-1195622-3, 99T1121-16-0/9-0(M)			
<a href="#">7204453001</a>	NO		7-1195633-5, 44M9996-16-0/2-0			
<a href="#">7333113001</a>	NO		8-1195727-0, 99T1131-20-0/2/9-0			
<a href="#">7340033001</a>	NO		7-1195732-5, 44M9996-22-2L/9-0			
<a href="#">7475593001</a>	NO		8-1195831-1, 44M9995-22-0-0(CO)			
<a href="#">7710653001</a>	NO		1196007-2, 44M9995-20-2-0			
<a href="#">7763153001</a>	NO		2-1196044-3, 7522A1811-0(M)			
<a href="#">7786813001</a>	NO		6-1196060-5, 44M9997-22-0/2L/9-0(CO)			
<a href="#">7792293001</a>	NO		4-1196064-5, 99T7113-22-0/8/9-0(CO)			
<a href="#">7900653001</a>	NO		1-1196120-2, 44M9996-22-0/2L-0(CO)			
<a href="#">7981813001</a>	NO		9-1196174-7, 44M9996-18-0/9-0			
<a href="#">8151373001</a>	NO		3-1196352-1, 7524A1811-0			
<a href="#">8279833001</a>	NO		2-1196466-9, 7526A1811-0(CO)			
<a href="#">8328413001</a>	NO		3-1196502-8, 99T1121-20(S106)			
<a href="#">8365493001</a>	NO		1196530-9, 44M9996-24-2L/7-0			
<a href="#">8477913001</a>	NO		1-1196612-5, 44M9996-20-0/9-0(M)			
<a href="#">8594383001</a>	NO		7-1201024-4, SL105-3X1.0-SU			
<a href="#">8647553001</a>	NO		8-1196734-7, 44M9995-18-2L-0			
<a href="#">8671733001</a>	NO		8-1196751-0, 44M9996-18-0/2-0			
<a href="#">8672113001</a>	NO		1196752-2, 99T7112-17-0/9-0			
<a href="#">8712693001</a>	NO		9-1196780-1, 0024E0811-0			
<a href="#">8719113001</a>	NO		2-1196785-4, CLFH316(S50)			
<a href="#">8766733001</a>	NO		1-1196819-3, 44M9995-22-0-0			
<a href="#">8948983001</a>	NO		4-1199424-1, 44M9996-20-2/6-0(CO)			
<a href="#">9133253001</a>	NO		7-1197091-8, 44M9997-20-2/4/6-0			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">9173093001</a>	NO		2-1197120-2, 99T1131-22-0/2/9-0(CO)			
<a href="#">9253893001</a>	NO		7-1197177-8, 0024E0811-0(CO)			
<a href="#">9257133001</a>	NO		8-1197179-4, 44M9995-24-9-0			
<a href="#">9257433001</a>	NO		1197180-3, 44M9996-24-0/2-0			
<a href="#">9257613001</a>	NO		1-1197180-4, 99T1121-22-0/9-0(CO)			
<a href="#">9268273001</a>	NO		7-1197187-9, CLFH178(S50)			
<a href="#">9336833001</a>	NO		6-1197235-5, 44M9996-22-0/9-0-M			
<a href="#">9361553001</a>	NO		1197253-4, 44M9997-16-0/2/7-0(CO)			
<a href="#">9394483001</a>	NO		2-1197275-0, 44M9996-26-2/6-0(27)-OBS1			
<a href="#">9560673001</a>	NO		1197402-8, 7518A1811-0			
<a href="#">9587553001</a>	NO		8-1197421-9, 44M9995-22-2-0			
<a href="#">9590573001</a>	NO		1-1197424-6, 44M9997-22-0/2/6-0			
<a href="#">9626493001</a>	NO		6-1197446-8, 44M9997-26-0/2/9-0			
<a href="#">9663653001</a>	NO		7-1197472-1, 44M9996-20-0/2-0(CO)			
<a href="#">9888653001</a>	NO		4-1197641-6, 44M9996-22-0/2L-0			
<a href="#">9926933001</a>	NO		6-1197678-1, CLFH400(S50)			
<a href="#">A201023001</a>	NO		1-1200160-4, 5026A1811-0(8M)			
<a href="#">A284773001</a>	NO		3-1201408-0, 7524A1811-0(5M)			
<a href="#">A487383001</a>	NO		8-1201286-0, CLFH179-0(M)			
<a href="#">A635943001</a>	NO		4-1201452-2, CLFH-179-0(8M)			
<a href="#">A801863001</a>	NO		3-1199703-7, 99T1111-18-9-0(4M)			
<a href="#">A816013001</a>	NO		6-1201726-7, 7530A1814-0			
<a href="#">A928393001</a>	NO		4-1201211-3, 44M9997-22-2/6/9-0(8M)			
<a href="#">C152393001</a>	NO		2-1201287-0, CLFH316-0(CO)			
<a href="#">C512703001</a>	NO		2-1200425-8, 99T1121-18-0/9-0(2M)			
<a href="#">C628353001</a>	NO		4-1201287-9, CLFH316-0(2M)			
<a href="#">C806053001</a>	NO		2-1201423-8, 7520A1811-0(CO)			
<a href="#">C857253001</a>	NO		6-1201287-2, CLFH-316CK0135			
<a href="#">C951483001</a>	NO		2-1200866-3, CLFH178(CO)			
<a href="#">CC4376-000</a>	NO		"100G1141-0.40--0-OBS"			
<a href="#">CC6877-000</a>	NO		"100G1131-2.50-F978CK0226"			
<a href="#">CD03333001</a>	NO		5-1899107-5, CL105-2X2X0.75-PO			
<a href="#">CD04593001</a>	NO		5-1899114-0, CLFH179CK1001			
<a href="#">CD18383001</a>	NO		1899172-4, 7520A1811-0(3M)			
<a href="#">CD20413001</a>	NO		1-1899185-6, CL105-5X2X0.5-PIOCK0456			
<a href="#">CD31333001</a>	NO		1899236-2, CLFH179			
<a href="#">CD37363001</a>	NO		6-1899264-4, CLFH-179-0(3M)			
<a href="#">CD46603001</a>	NO		6-1899315-7, 5026C3814-0			
<a href="#">CD54463001</a>	NO		4-1899355-8, 0024K1811-0(2M)			
<a href="#">CD56713001</a>	NO		3-1899364-6, 0024K1811-0			
<a href="#">CD57673001</a>	NO		2-1899369-3, 0024K1811-0(4M)			
<a href="#">CD69273001</a>	NO		2-1899421-6, CL105-2X2X0.75-PIOCK0454			
<a href="#">CD69793001</a>	NO		2-1899423-3, CLFH-178-0(CO)			
<a href="#">CD81963001</a>	NO		"0024K1811-0(3M)", "8-1899469-5"			
<a href="#">CD90493001</a>	NO		"CL105-7X2X0.5-POCK0482", "8-1899500-4"			
<a href="#">CD93653001</a>	NO		"EPD110886A/1(CO)", "1899513-2"			
<a href="#">CD95553001</a>	NO		"7-1899520-1", "EPD102974A-OCK0400"			
<a href="#">CD96363001</a>	NO		"8-1899522-0", "EPD102966A-OCK0456"			
<a href="#">CD99383001</a>	NO		"0024K1811-0(6M)", "9-1899535-6"			
<a href="#">CQ02493001</a>	NO		"7522D5811-0(3M)"			
<a href="#">CQ04543001</a>	NO		"EPD117005ACK0355"			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">CQ04553001</a>	NO		"1-1899760-8", "EPD117006ACK0355"			
<a href="#">CQ04563001</a>	NO		"EPD117007ACK0355"			
<a href="#">CQ04573001</a>	NO		"EPD117008ACK0355"			
<a href="#">CQ04583001</a>	NO		"EPD117012ACK0355"			
<a href="#">CQ04593001</a>	NO		"EPD117013ACK0355"			
<a href="#">CQ04613001</a>	NO		"EPD117127ACK0355"			
<a href="#">CQ05053001</a>	NO		"EPD103036A-OCK0456/4"			
<a href="#">CQ07223001</a>	NO		"EPD117416ACK0355"			
<a href="#">CQ09663001</a>	NO		"EPD117380ACK4131"			
<a href="#">CQ10233001</a>	NO		"TRLI34265(GM)"			
<a href="#">CQ22133001</a>	NO		"TRLI34412(SB)"			
<a href="#">CQ23023001</a>	NO		"EPD110886ACK0046/3"			
<a href="#">CQ28263001</a>	NO		"TRLI34446(SB)"			
<a href="#">CQ28283001</a>	NO		"TRLI34447(SB)"			
<a href="#">CQ31923001</a>	NO		<b>TRLI34474(SB)</b>			
<a href="#">CQ31943001</a>	NO		<b>TRLI34475(SB)</b>			
<a href="#">CQ31993001</a>	NO		"0024K1811-0(M)"			
<a href="#">CQ35853001</a>	NO		<b>TRLI14514(GP)</b>			
<a href="#">CQ35863001</a>	NO		"TRLI14515(GP)"			
<a href="#">CQ37733001</a>	NO		<b>TRLI34552(SB)</b>			
<a href="#">CQ38213001</a>	NO		<b>0028A1811-0(M)</b>			
<a href="#">CQ40143001</a>	NO		<b>CLFH-400</b>			
<a href="#">CQ40393001</a>	NO		<b>7528A1814-0(M)</b>			
<a href="#">CQ40613001</a>	NO		<b>EPD119188A-OCK5100</b>			
<a href="#">CQ40623001</a>	NO		<b>EPD119188A-OCK5500</b>			
<a href="#">CQ40883001</a>	NO		"TRLI34595(SB)"			
<a href="#">CQ43613001</a>	NO		<b>EPD103533A-OCK0202</b>			
<a href="#">CQ45153001</a>	NO		<b>CLFH-179-0(M)</b>			
<a href="#">CQ48103001</a>	NO		<b>5012A3811-OCK0016</b>			
<a href="#">CQ49883001</a>	NO		<b>TRLI34760(SB)</b>			
<a href="#">CQ49933001</a>	NO		<b>TRLI14763(GP)</b>			
<a href="#">CQ54623001</a>	NO		<b>TRLI54830(JW)</b>			
<a href="#">CQ54633001</a>	NO		<b>TRLI54831(JW)</b>			
<a href="#">CQ55073001</a>	NO		<b>EPD102825A-OCK5100</b>			
<a href="#">CQ58013001</a>	NO		<b>5018D3811-OCK0206</b>			
<a href="#">CQ60503001</a>	NO		<b>C6A-24B134XM18A-OCK9500</b>			
<a href="#">CQ61763001</a>	NO		<b>EPD110886ACK0046/4</b>			
<a href="#">CQ61803001</a>	NO		<b>C6A-24B134XM18A-OCK9500</b>			
<a href="#">CQ62513001</a>	NO		<b>TRLI54995(JW)</b>			
<a href="#">CQ62523001</a>	NO		<b>TRLI54996(JW)</b>			
<a href="#">CQ62943001</a>	NO		<b>7528A1814-0(CO)</b>			
<a href="#">CQ63153001</a>	NO		<b>C6A-24B134XM18A-0(CO)</b>			
<a href="#">CQ63963001</a>	NO		<b>TRLI35037(SB)</b>			
<a href="#">CQ65143001</a>	NO		<b>C6A-24B134XM18A-OCK0206</b>			
<a href="#">CQ65153001</a>	NO		<b>C6A-24B134XM18A-OCK0206/1</b>			
<a href="#">CQ65273001</a>	NO		<b>TRLI35086(SB)</b>			
<a href="#">CQ65283001</a>	NO		<b>TRLI35087(SB)</b>			
<a href="#">CQ67123001</a>	NO		<b>TRLI35138(PH)</b>			
<a href="#">CQ67583001</a>	NO		<b>C6A-24B134XM18A-OCK0206/2</b>			
<a href="#">CQ68163001</a>	NO		<b>TRLI35146(JW)</b>			
<a href="#">CQ68173001</a>	NO		<b>TRLI35147(JW)</b>			
<a href="#">CQ68353001</a>	NO		<b>TRLI35149(IL)</b>			
<a href="#">CQ69743001</a>	NO		<b>100G1111-1.50-0-0ENCK0042</b>			
<a href="#">CQ69883001</a>	NO		<b>TRLI35178(SB)</b>			
<a href="#">CQ69893001</a>	NO		<b>TRLI35179(SB)</b>			
<a href="#">CQ71143001</a>	NO		<b>TRLI35210(TS)</b>			
<a href="#">CQ71153001</a>	NO		<b>TRLI35211(TS)</b>			
<a href="#">CQ71163001</a>	NO		<b>TRLI35212(TS)</b>			
<a href="#">CQ71193001</a>	NO		<b>C6A-26B134XM18A-OCK0620</b>			
<a href="#">CQ71203001</a>	NO		<b>C6A-26B134XM18A-OCK0620/5</b>			
<a href="#">CQ72053001</a>	NO		<b>C6A-24B134XM18A-OCK1100</b>			
<a href="#">CQ73183001</a>	NO		<b>C6A-24B134XM18A-OCK0206/3</b>			
<a href="#">CQ75793001</a>	NO		<b>C6A-24B134XM18A-OCK0206/4</b>			
<a href="#">CQ75803001</a>	NO		<b>C6A-24B134XM18A-OCK0206/5</b>			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">CQ76773001</a>	NO		7528F5814-0CK0193			
<a href="#">CQ79413001</a>	NO		2018A1811-0(CO)			
<a href="#">CQ79913001</a>	NO		EPD121678A			
<a href="#">CQ80573001</a>	NO		EPD105242A			
<a href="#">CQ80583001</a>	NO		EPD121679A			
<a href="#">CQ87593001</a>	NO		C6A-26B134XM18A-0CK0193			
<a href="#">CQ87793001</a>	NO		C6A-24B134XM18A-0CK0206/6			
<a href="#">CQ87803001</a>	NO		C6A-24B134XM18A-0CK0206/7			
<a href="#">CQ88923001</a>	NO		XXX-EPD122077A/1			
<a href="#">CQ88993001</a>	NO		C6A-24B134XM18A-0CK0206/8			
<a href="#">CQ89003001</a>	NO		C6A-24B134XM18A-0CK0206/9			
<a href="#">CQ89483001</a>	NO		EPD122077ACK0046/2			
<a href="#">CQ89503001</a>	NO		EPD122077A/1(CO)			
<a href="#">CQ91613001</a>	NO		0024K1811-0(M1)(FS)			
<a href="#">CQ91623001</a>	NO		0024K1811-0(M2)(FS)			
<a href="#">CQ91633001</a>	NO		0024K1811-0(M3)(FS)			
<a href="#">CQ91643001</a>	NO		0024K1811-0(M4)(FS)			
<a href="#">CQ91653001</a>	NO		0024K1811-0(M1)			
<a href="#">CQ91663001</a>	NO		0024K1811-0(M2)			
<a href="#">CQ91673001</a>	NO		0024K1811-0(M3)			
<a href="#">CQ91683001</a>	NO		0024K1811-0(M4)			
<a href="#">CQ92693001</a>	NO		C7X-24B114XK18A-0(CO)			
<a href="#">CQ95273001</a>	NO		2018A1811-0			
<a href="#">CQ96143001</a>	NO		C7X-23A914XK18A-0CK9500			
<a href="#">CQ96323001</a>	NO		C6A-26B134XM18A-0(CO)			
<a href="#">CQ97023001</a>	NO		C7X-24B114XK18A-0CK9500			
<a href="#">CQ97433001</a>	NO		C6A-24B134XM18A-0(M)			
<a href="#">CQ97453001</a>	NO		C7X-24B114XL18A-0CK9500			
<a href="#">CQ97683001</a>	NO		0022E0811-0(M)			
<a href="#">CQ97693001</a>	NO		C7X-24B114XK18A-0(M)			
<a href="#">CQ99473001</a>	NO		CLFH179CK1200			
<a href="#">CQ99903001</a>	NO		EPD115016A			
<a href="#">CT01803001</a>	NO		"7523D1831-0(CO)", "2-1899547-8"			
<a href="#">CT02393001</a>	NO		"CLFH-179-0(7M)", "1-1899549-2"			
<a href="#">CT04973001</a>	NO		"EPD103030A-0CK5500"			
<a href="#">CT09433001</a>	NO		"EPD101615A-0CK5500"			
<a href="#">CT11263001</a>	NO		"EPD102966A-0CK5500"			
<a href="#">CT11273001</a>	NO		"EPD102967A-0CK5500"			
<a href="#">CT14153001</a>	NO		"EPD102787A-0CK5500"			
<a href="#">CT15513001</a>	NO		"EPD103024A-0CK5501"			
<a href="#">CT15873001</a>	NO		"EPD102831A-0CK5501"			
<a href="#">CT18613001</a>	NO		"EPD102908A-0CK5501"			
<a href="#">CT19903001</a>	NO		"EPD102965A-0CK5501"			
<a href="#">CT19913001</a>	NO		"EPD102966A-0CK5501"			
<a href="#">CT19923001</a>	NO		"EPD102967A-0CK5501"			
<a href="#">CT19963001</a>	NO		"EPD102969A-0CK5501"			
<a href="#">CT64843001</a>	NO		"2020E0811-0-UK"			
<a href="#">CT66883001</a>	NO		"EPD110886ACK0046/2"			
<a href="#">CT69993001</a>	NO		"CLFH178(FS)"			
<a href="#">CT75873001</a>	NO		"0024K1811-0(CO)"			
<a href="#">CT81643001</a>	NO		"44M9996-20-0/6-0(CO)"			
<a href="#">CT81653001</a>	NO		"44M9996-20-0/9-0(CO)"			
<a href="#">CT92833001</a>	NO		"EPD113956DCK0550"			
<a href="#">CT98383001</a>	NO		"5018F1811-0(2M)"			
<a href="#">D362073001</a>	NO		3-1201348-7, 7524A1811-0(2M)			
<a href="#">D532133001</a>	NO		7-1201499-9, 5020A3811-06(CO)			
<a href="#">D574843001</a>	NO		1200559-9, 7526A1811-0(3M)			
<a href="#">D660153001</a>	NO		1-1201872-9, CLFH316			
<a href="#">D936633001</a>	NO		1201442-9, 5026A3814-0			
<a href="#">E146233001</a>	NO		4-1200827-1, 99T7112-22-0/6-0(10M)			
<a href="#">E521943001</a>	NO		5-1201125-1, 99T7113-22-0/6/9-0(3M)			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">E820083001</a>	NO		3-1200824-8, <b>99T7112-18-0/9-0(2M)</b>			
<a href="#">E900633001</a>	NO		8-1201288-1, <b>CLFH-179CK0135</b>			
<a href="#">E940393001</a>	NO		8-1201288-3, <b>CLFH-178CK0135</b>			
<a href="#">EM0645-000</a>	NO		<b>2022A1811-0</b>			
<a href="#">EQ00193001</a>	NO		<b>7528A1818-0(M)</b>			
<a href="#">F044573001</a>	NO		4-1201019-2, <b>CLFH-179-0(CO)</b>			
<a href="#">F518743001</a>	NO		8-1200596-4, <b>2020E0811-0(CO)</b>			
<a href="#">F615273001</a>	NO		6-1201500-8, <b>5020A3811-02(CO)</b>			
<a href="#">F670013001</a>	NO		1-1200884-7, <b>99T1121-20-0/9-0(4M)</b>			
<a href="#">F907263001</a>	NO		8-1201192-8, <b>99T1121-20-0(M)/9(M)-0(CO)</b>			