



Product Change Notification

Current Date: 30-Mar-2022

TE Connectivity

Product Change Notification: P-22-022403

PCN Date: 28-MAR-22

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

HVP800 2P HEADER ASSY

Description of Changes

1. Change part number . 2322122-1/2 -> 8-2355198-1/2 1-2322122-1/2 -> 6-2355198-1/2 2-2322122-1/2 -> 7-2355198-1/2 3-2322122-1/2 -> 5-2355198-1/2 4-2322122-1/2 -> 2355198-1/2 5-2322122-1/2 -> 1-2355198-1/2 2. Optimize the PIN hole structure of housing , move and add the ribs to make the terminal position more stable and interlocking. 3. Optimize the Terminal Pin structure of fixed-position form cylindrical shell to flat shape. 4. Change the HVIL 2.Lock color from Grey to Red

Other attachments:

[Comparison between new and old HVP800 Header 20210115 Rev02](#)

Reason for Changes:

Product improvement.1. Change part number . 2322122-1/2 -> 8-2355198-1/2 1-2322122-1/2 -> 6-2355198-1/2 2-2322122-1/2 -> 7-2355198-1/2 3-2322122-1/2 -> 5-2355198-1/2 4-2322122-1/2 -> 2355198-1/2 5-2322122-1/2 -> 1-2355198-1/2 2. Optimize the PIN hole structure of housing , move and add the ribs to make the terminal position more stable and interlocking. 3. Optimize the Terminal Pin structure of fixed-position form cylindrical shell to flat shape. 4. Change the HVIL 2.Lock color from Grey to Red

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	31-MAR-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-MAR-2022

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Note: This PCN contains only document changes, these changes do not affect the form, fit or function of the parts referenced.

Customer Drawing(s) Being Modified:

Drawing Number	Related Part Number	Customer Part Number	Current Revision	New Revision
2322122	1-2322122-1		C1	

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement Number: Agreement Unknown

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

Drawing Number	Related Part Number	Customer Part Number	Current Revision	New Revision
2322122	1-2322122-1		C1	



新老料号对照表 P/N Cross Reference

Current P/N	New P/N	Description
2322122-1	8-2355198-1	HVP800 2P HEADER ASSY, CODE A, HB
2322122-2	8-2355198-2	HVP800 2P HEADER ASSY, CODE B, HB
1-2322122-1	6-2355198-1	HVP800 2P HEADER ASSY, BUSBAR, CODE A, HB
1-2322122-2	6-2355198-2	HVP800 2P HEADER ASSY, BUSBAR, CODE B, HB
2-2322122-1	7-2355198-1	HVP800 2P HEADER ASSY, BUSBAR 180°, CODE A, HB
2-2322122-2	7-2355198-2	HVP800 2P HEADER ASSY, BUSBAR 180°, CODE B, HB
3-2322122-1	5-2355198-1	HVP800 2P HEADER ASSY, CODE A, V0
3-2322122-2	5-2355198-2	HVP800 2P HEADER ASSY, CODE B, V0
4-2322122-1	2355198-1	HVP800 2P HEADER ASSY, BUSBAR, CODE A, V0
4-2322122-2	2355198-2	HVP800 2P HEADER ASSY, BUSBAR, CODE B, V0
5-2322122-1	1-2355198-1	HVP800 2P HEADER ASSY, BUSBAR 180°, CODE A, V0
5-2322122-2	1-2355198-2	HVP800 2P HEADER ASSY, BUSBAR 180°, CODE B, V0


产品对比 Part Comparison

Before Change

P/N: 0/3-2322122-1/2





Terminal




Housing

After Change

P/N: 8/5-2355198-1/2




Optimized Terminal



Optimized Housing

端子和塑壳形状有变，成品外部尺寸没有变化，性能没有变化
Only terminal and housing changed, but no other change, no performance change.

产品对比 Part Comparison




端子和塑壳形状有变，成品外部尺寸没有变化，性能没有变化
Only terminal and housing changed, but no other change, no performance change.

产品对比 Part Comparison

Before Change


P/N: 0/1/2-2322122-1/2



HVIL (2. LOCK, IL)
GREY

After Change


P/N: 8/6/7-2355198-1/2



HVIL (2. LOCK, IL)
RED


二次锁颜色有变，尺寸没有变化，性能没有变化
Only HVIL 2. LOCK. IL color changed, but no other change, no performance change.

P/N: 3/4/5-2322122-1/2



HVIL (2. LOCK, IL)
RED

P/N: 5/0/1-2355198-1/2



HVIL (2. LOCK, IL)
RED

二次锁保持不变
HVIL 2. LOCK. IL no change.

结论 Conclusion

This change does not affect product performance
此变更不影响产品使用功能

This change does not affect customer assembly
此变更不影响客户端组装性