



15-Jun-2022

PCN #: P-22-022922

Subject : Miniseal, Duraseal, Databus

Description of Change : Markem-Imaje informed us that they will replace the INK ADDITIVE 5191 (MEK based), they will move from the current 5191 to 5199 (5191 was obsoleted).

Reason : Product improvement. Vendor Markem-Imaje phase-out of pink MEK additive due to a shortage of a pink dye raw material used in MEK additives

Key Dates :

Contact By Date:20-Jun-2022

Implementation Date:20-Jun-2022

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
5441550002	"4-1194268-8", "D-150-9133CS2279"		
D42234-000	"4-1200790-8"		
CP2914-000			
503123N002	"1-1193787-7", "DK-621-0412-SCS857"		
650129-000	"1-1195133-5"		
003507-000	"5-1190026-1", "DK-621-0439R-4P"		
CU1636-000			
530805N002	"9-1194168-5", "DK-621-0436-2PCS1104"		

638491-000	"9-1195046-7", "DK-621-0434-1P"		
390299-000	"3-1192930-5", "DK-621-0439-4P"		
947343-000	"2-1197330-4", "DK-621-0433-1SCS1873"		
F33352-000	"DK-621-0440-4P-CS1498", "9-1200867-7"		
650126N004	"1195133-1", "D-436-82CS2705"		
650110N006	"6-1195132-2", "D-436-0128CS2612"		
A75990N001	"D-150-0231-NRCS2896"		
957740N003	"2-1197414-0", "DK-621-0046-3PCS258"		
A12306-000	"3-1201725-7"		
797538-000	"5-1199500-8", "D-150-0290-NF"		
449453-000	"3-1193376-3", "D-150-0708-5"		
650150-000	"8-1195133-1", "D-436-0119"		
664099-000	"7-1195233-1"		
390299N001	"3-1192930-6", "DK-621-0439-4PCS2674"		
947687-000	"7-1197332-9", "D-150-9134"		
EH8696-000			
149317-000	"8-1191079-4"		
CN7467-000			

EG3678-000	"D-200-0233-RT"		
602549-000	"6-1194769-1"		
608967-000	"1-1194816-6", "DK-621-0411-44P"		
972394-000	"2-1197516-0"		
CJ1897N001	"D-150-0342CS2903"		
957325-000	"1-1197411-4", "D-150-0708-4"		
241251N001	"4-1191772-6", "DK-621-0440-4SCS1874"		
852437-000	"2-1196645-5", "DK-621-0440-4SCS1104"		
900771-000	"7-1197001-1", "D-436-82CS788"		
CN4612-000			
702651-000	"8-1195513-6", "D-150-0228CS2075"		
C54421-000	"5-1201725-1"		
650167-000	"1-1195134-7"		
695277-000	"3-1195454-2", "W-095-04"		
CU3030-000			
712691-000	"1-1195582-7", "D-436-85CS788"		
650110-000	"5-1195132-7"		
6501100005	"6-1195132-1", "D-436-0128CS246"		
680104N002	"6-1195347-2", "D-609-03CS435"		

CV4972-000	"D-200-0236-RT"		
CM2843-000			
744843-000	"3-1195810-9", "DK-621-0438-3SCS1874"		
CF9209-000			
650074N003	"6-1195131-7", "D-436-36CS2651"		
501939-000	"1-1193752-2"		
055672-000	"8-1199171-2"		
301528-000	"4-1199929-4", "D-150-L708-F1"		
889654-000	"7-1199500-4", "D-150-0297-NF"		
CS7507-000			
F51833-000	"DK-621-0436-2P-CS2812", "7-1200827-9"		
680326N004	"6-1195350-2", "D-609-06CS2603"		
E44686-000	"DK-621-0435-2S-CS2812", "5-1200827-1"		
544155-000	"4-1194268-6", "D-150-9133"		
680332N002	"8-1195350-4"		
633671-000	"5-1195012-6", "DK-621-0433-1S"		
CA3200N001	"D-150-0331CS2902"		
046900-000	"8-1199171-1"		
449967-000	"8-1193379-4", "DK-621-0439-4SCS1873"		

ER6729-000			
163863-000	"6-1191182-2"		
D25082-000	"D-150-0236-NR"		
459515-000	"8-1193446-4", "DK-621-0433R-1S"		
CS7502-000			
695050-000	"6-1195452-6", "W-096-01"		
EH8694-000			
544155N003	"4-1200431-6", "D-150-9133CS2863"		
650126-000	"9-1195132-6"		
169757-000	"5-1191235-4", "D-150-0236"		
139255-000	"9-1191009-1", "DK-621-0411R-S"		
116115-000	"8-1190845-8", "DK-621-1639R-4S"		
644749-000	"7-1195092-5", "DK-621-0411R-44P"		
947687N001	"4-1200878-1", "D-150-9134CS2873"		
070351-000	"2-1190529-0", "DK-621-0435-2P"		
CR9761-000			
820597-000	"4-1196398-2", "DK-621-0411R-PCS2326"		
414144-000	"3-1199172-0"		
650195-000	"6-1195134-4"		
425801-000	"9-1193204-9"		

128596-000	"8-1199150-7", "DK-621-0434-1US"		
CM6823-000			
889024-000	"6-1199172-6"		
968135-000	"2-1197485-3", "DK-621-0439-4PCS1873"		
650074-000	"6-1195131-3", "D-436-36"		
EG9778-000	"DK-621-1640-4SCS312"		
CM2839-000			
CV7712-000			
073683-000	"4-1190551-1", "DK-621-0436-2SCS1104"		
E41478-000	"D-150-0235-NR"		
CC1572-000			
942598-000	"2-1199152-0", "DK-621-0433-1US"		
A25672N001	"D-150-0228-NRCS2896"		
046626-000	"8-1199171-0"		
362675-000	"2-1192719-0", "D-150-0189"		
E24799-000	"6-1200790-5"		
EM4103-000	"D-150-0228-RT-CS4049"		
365711-000	"2-1192742-9"		
D74914-000	"3-1200827-6", "DK-621-0434-1S-CS2812"		
972394N002	"D-150-0168CS2902"		

943488-000	"7-1199172-0"		
254033-000	"8-1191859-2"		
CS7499-000			
631921-000	"1195000-7", "B-500-600-00"		
CA3200-000	"D-150-0331"		
361727N001	"7-1192712-7", "DK-621-0438-3PCS1498"		
A80503-000	"2-1201790-5", "D-150-0318-NF"		
EM4105-000	"D-150-0236-RT-CS4049"		
764930-000	"5-1198935-4", "D-436-82CS2830"		
503123-000	"1-1193787-5", "DK-621-0412-S"		
542467-000	"2-1194253-5", "DK-621-0436-2S"		
EM3171-000			
339698-000	"7-1200826-1", "DK-621-0438-3S-CS2812"		
D07508-000	"8-1200810-0", "DK-621-0436-2P-CS1498"		
CJ1897-000			
CS7506-000			
193495N003	"D-150-0179CS2902"		
014939-000	"2-1190117-7", "DK-621-0439-4S"		
734989-000	"2-1195740-3", "DK-621-0437-3S"		
CM5812-000	"D-150-9133CS2925"		

328711-000	"7-1192485-9", "D-150-0231"		
ER7370-000			
680326-000	"5-1195350-8"		
CS3164-000			
193495-000	"8-1191403-4", "D-150-0179"		
A35141-000	"6-1201422-0", "MK-0020-100"		
773633-000	"8-1196024-4", "DK-621-0439R-4S"		
766673-000	"2-1195975-2", "D-406-2004"		
724447-000	"1195663-1", "DK-621-0435-2S"		
680329-000	"7-1195350-1"		
279316-000	"6-1200142-0", "D-500-04-C23-072"		
680112-000	"8-1195347-1"		
621207N003			
516269-000	"3-1194054-4", "D-406-2005"		
EG9776-000	"DK-621-1634-1PCS312"		
972394N001	"2-1197516-1", "D-150-0168CS308"		
191239-000	"1-1191387-6", "DK-621-0438-3SCS1104"		
695054-000	"7-1195452-8", "W-095-01"		
650126N010	"D-436-82-CS2621"		
CU6227-000			

143981N001	"9-1191040-3", "DK-621-0434-1SCS1874"		
365668-000	"2-1199172-5"		
EK3595-000	"D-200-82-CS4126"		
042871-000	"9-1190328-1", "DK-621-0440-4P"		
EH6623-000	"D-150-0334CS2902"		
F14072-000	"DK-621-0433-1PCS1873", "6-1200586-5"		
902973-000	"4-1197017-5", "DK-621-0411-P"		
650074N006	"6-1195131-9", "D-436-36CS454"		
829188-000	"5-1200826-7", "DK-621-0438-3P-CS2812"		
798289-000	"3-1196175-3", "D-609-06CS2717"		
EK1201-000	"D-200-85"		
390207-000	"6-1192929-4", "D-609-06CS1004"		
D17660-000	"5-1202147-7", "D-200-82"		
019439-000	"6-1190151-7", "DK-621-0433-1P"		
634121-000	"8-1195015-3", "D-406-2006"		
915480-000	"6-1199172-7", "DK-621-0435-2UP"		
870333-000	"4-1196774-8", "DK-621-0411-SCS2738"		

CP5744-000			
4367320002	"8-1193282-6", "D-436-0148CS391"		
ER7369-000			
530805-000	"9-1194168-3", "DK-621-0436-2P"		
704201-000	"1-1195524-5"		
D36771-000	"4-1200790-7"		
D20428-000	"D-436-0110CS2851", "1-1199758-8"		
680003-000	"8-1195345-0"		
383392-000	"2-1199172-6"		
191045-000	"7-1191385-3", "DK-621-0411-S"		
574636-000	"4-1200141-8", "D-500-04-C03-072"		
F23780-000	"4-1202148-1", "D-200-0231-NF"		
118345N002	"2-1190861-1", "DK-621-0412-PCS857"		
C11277-000	"2-1200790-7"		
CW7957-000	"D-200-0236-RT-CS4049"		
186998-000	"4-1191357-4", "D-150-0708-3"		
6803260002	"6-1195350-1", "D-609-06CS391"		
CB5629N001	"D-150-0333CS2902"		
6500740004	"6-1195131-6", "D-436-36CS391"		

178365-000	"1-1191297-3", "D-150-0231CS2075"		
ER6599-000			
636060-000	"5-1199172-2"		
319590-000	"5-1200942-7", "DK-621-0435-2PCS1873"		
CJ1900N001	"D-150-0343CS2903"		
118345-000	"1-1190861-9", "DK-621-0412-P"		
CX7799-000			
602707-000	"7-1194770-3"		
CY6595-000			
813317-000	"5-1196327-3", "DK-621-0411-PCS2738"		
247116-000	"1-1199151-3", "DK-621-0433-1UP"		
705692-000	"2-1195534-9", "D-150-0178"		
393863-000	"8-1192954-1", "D-150-9708-5"		
D25082N001	"D-150-0236-NRCS2896"		
D84828-000	"3-1200827-8", "DK-621-0434-1P-CS2812"		
191045N002	"7-1191385-5", "DK-621-0411-SCS1862"		
650038-000	"7-1195130-1"		
CU1641-000			
514433-000	"1-1194041-8", "DK-621-0412CS325"		

976670-000	"7-1197546-7", "D-500-0263-017C"		
650132-000	"2-1195133-5", "D-436-88"		
907771-000	"6-1197051-5"		
CM0967-000	"D-150-0348"		
A11769-000	"9-1200570-5", "D-150-0321"		
945696-000	"7-1199172-1", "DK-621-0436-2US"		
652913-000	"3-1195153-7", "DK-621-0437-3P"		
044609-000	"7-1190342-0", "DK-621-0438-3PCS1104"		
CJ1900-000			
CM3558-000	"DK-621-0436-2SCS2812"		
680104-000	"5-1195347-9"		
019439N001	"6-1190151-8", "DK-621-0433-1PCS2674"		
650126N006	"1195133-2", "D-436-82CS352"		
A75990-000	"D-150-0231-NR"		
143981-000	"9-1191040-2", "DK-621-0434-1S"		
650126N008	"3-1201259-3", "D-436-82CS2845"		
CW2517-000			
478138-000	"7-1199499-9", "D-150-0314-NF"		
976498-000	"7-1199172-9", "DK-621-0434-1UP"		

902973N002	"4-1197017-7", "DK-621-0411-PCS1862"		
CY6591-000			
438915-000	"5-1193298-0", "DK-621-0411R-P"		
595620-000	"1-1194710-7", "D-150-0133"		
E34373-000	"7-1201725-7"		
CW7087-000	"DK-621-0939R-4P"		
604947-000	"5-1194786-6", "DK-621-0434-1SCS1104"		
650126N007	"8-1201198-8", "D-436-82CS2881"		
355773-000	"6-1192670-9", "D-150-0236CS2075"		
361727-000	"7-1192712-6", "DK-621-0438-3P"		
070351N001	"2-1190529-1", "DK-621-0435-2PCS2674"		
CL0949-000			
241251-000	"4-1191772-5", "DK-621-0440-4S"		
CW7088-000	"DK-621-0939R-4S"		
680111-000	"7-1195347-8", "D-150-21"		
E41478N001	"D-150-0235-NRCS2896"		
650129N002	"1-1195133-7", "D-436-85CS2705"		
680332-000	"8-1195350-1"		

941271-000	"1-1197288-6", "D-150-0235"		
228389N002	"5-1191680-0", "DK-621-0411CS129"		
CB5629-000	"D-150-0333"		
EM3650-000	"D-150-0236-RT"		
CN4054-000			
522161-000	"4-1194103-1", "D-150-0228"		
CY6588-000			
650132N004	"D-436-88CS2897"		
A25672-000	"D-150-0228-NR"		
CF9208-000			
680110-000	"7-1195347-5", "D-150-20"		
CY3615-000			
D76167-000	"6-1200762-6", "DK-621-0434-1PCS1498"		
D01793-000	"9-1201379-3", "D-150-0326"		
621207-000	"6-1194909-7"		
EG9777-000	"DK-621-1636-2PCS312"		
EM4444-000	"D-200-0235-HAF-CS4144"		
015187-000	"2-1190119-0", "DK-621-0434-45S"		
CM2846-000			
436732-000	"8-1193282-5"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.