















Selection Guide for PQA Accessories

Photo	Part number	Description	Target application	MI 2892	MI 2885	MI 2883	MI 2130	MI 2230
	A 1501	1-phase mini flexible current clamp 3000/300/30 A / 1V	Single phase flexible current clamp with three selectable measuring ranges (25 cm loop). Does not require external power supply as it is powered by the measuring instrument.	•	•	•		
	A 1502	1-phase mini flexible current clamp 3000/300/30 A / 1V	Single phase flexible current clamp with three selectable measuring ranges (48 cm loop). Does not require external power supply as it is powered by the measuring instrument.	•	•	•		
	A 1503	1-phase mini flexible current clamp 6000/600/60 A / 1V	Single phase flexible current clamp with three selectable measuring ranges (90 cm loop). Does not require external power supply as it is powered by the measuring instrument.	•	•	•		
	A 1391	Current clamp 40/300 A / 1V	AC + DC current clamp 40/300 A / 1V with jaw opening 25 mm for power measurements. Requires A 1039 connection cable. Battery Life, 66 hours typical (Alkaline).	•	•	•		
	A 1033	Current clamp 1000 A / 1V	High accuracy current clamp 1000 A / 1V with jaw opening 52 mm and fixed 1.5 m cable for power measurements with Metrel power quality analysers.	•	•	•		
	A 1281	Current clamp 0,5/5/100/1000 A / 1V	Four ranges current clamp for measuring alternating currents in low and medium power installations. Current clamp is automatically recognized by the instrument. Clamp does not require external power supply as it is powered by the instrument.	•	•	•		
	A 1069	Mini current clamp 100 A / 1V	Mini current clamp 100 A / 1V with jaw opening 15 mm for power measurements. Requires A 1039 connection cable.	•	•	•		
	A 1122	Mini current clamp 5 A / 1V	Mini current clamp 5 A / 1V with jaw opening 15 mm for power measurements. Requires A 1039 connection cable.	•	•	•		
	A 1039	Connection cable for current clamp	Connection cable for connecting current clamps A 1069 and A 1122, A 1391 on Metrel power quality analysers.	•	•	•		
	A 1179	3-phase flexible current clamp 2000/200/20 A / 1V	3-phase flexible current clamp with three selectable measuring ranges. Powered by alkaline or rechargeable batteries.	•	•	•		
	A 1227	1-phase flexible current clamp 3000/300/30 A / 1V	Single phase flexible current clamp with three selectable measuring ranges. Current clamp is automatically recognized by the instrument. Clamp does not require external power supply as it is powered by the measuring instrument.	•	•	•		
	A 1445	1-phase flexible current clamp 3000/300/30 A / 1V		•	•	•		
	A 1446	1-phase flexible current clamp 6000/600/60 A / 1V		•	•	•		
	A 1257	3-phase flexible current clamp 3000/300/30 A / 1V	3-phase flexible current clamp with three selectable measuring ranges. Powered by alkaline or rechargeable batteries.	•	•	•		

• Option