



Product Change Notification

Current Date: 05-Apr-2022

TE Connectivity

Product Change Notification: P-22-022462

PCN Date: 05-APR-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Self Adhesive labels for wires and cables

Description of Changes
Manufacturing location change. The following Part Numbers will be transferred from the TE plant located at Idento Roedermark Germany to a TE manufacturing plant located in Tangier, Morocco.

Reason for Changes:
Dear Customer, as a result of our continuous strive to improve our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according to the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance of the product.

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	01-AUG-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1768026-3	NO		"C81401-000", "LBG-U-01562/1"			
1-1768026-5	NO		"D82582-000", "LBG-U-01570"			
1-1768026-7	NO		"C86688-000", "LBG-U-01587"			
1-1768028-0	NO		"A34241-000", "LBG-U-02249"			
1-1768028-9	NO		"F79164-000", "LBG-U-02264"			
1-1768030-2	NO		"D55491-000", "LBG-U-02652/1"			
1-1768030-4	NO		"A48865-000", "LBG-U-02654"			
1-1768030-5	NO		"F87597-000", "LBG-U-02654/1"			
1-1768030-6	NO		"C91709-000", "LBG-U-02654/2"			
1-1768031-3	NO		"A23559-000", "LBG-U-02743"			
1-1768033-0	NO		E64921-000, LEB-0619P-8			
1-1768033-2	NO		"A99702-000", "LEB-0619P-9", "4300542-F"			
1-1768033-3	NO		D33139-000, LEB-0619PF-4			
1-1768033-6	NO		D43445-000, LEB-0636P-8A			
1-1768033-7	NO		A71877-000, LEB-0636P-9			
1-1768033-9	NO		D32081-000, LEB-0636S-8A			
1-1768402-0	NO					
1-1768402-7	NO					
1-1768409-1	NO					
1-1768409-2	NO					
1-1768410-3	NO					
1-1768419-0	NO					
1-1768419-4	NO					
1-1768420-3	NO					
1-1768420-4	NO					
1-1768420-9	NO					
1-1768423-7	NO					
1-1768423-9	NO					
1-1768426-1	NO					
1-1768426-2	NO					

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1768426-6	NO					
115180-000	NO		4-1198209-6, TTP400MP-10			
1768028-3	NO		"C41818-000", "LBG-U-02223"			
1768029-3	NO		"A19466-000", "LBG-U-02464"			
1768031-4	NO		"D11411-000", "LBG-U-02734"			
1768033-1	NO		A36232-000, LEB-0608P-8A			
1768033-2	NO		E08494-000, LEB-0608P-9			
1768033-3	NO		A45086-000, LEB-0608PF-4			
1768033-4	NO		A09833-000, LEB-0615P-4			
1768033-6	NO		E32185-000, LEB-0615P-8A			
1768033-7	NO		"D07129-000", "LEB-0615P-9", "4300501-F"			
1768033-8	NO		C82621-000, LEB-0615PF-4			
1768033-9	NO		C52018-000, LEB-0619P-4			
2-1768026-5	NO		"F35151-000", "LBG-U-01607"			
2-1768026-8	NO		"D29311-000", "LBG-U-01618"			
2-1768027-0	NO		"C06530-000", "LBG-U-01912/2"			
2-1768029-2	NO		"E80726-000", "LBG-U-02492"			
2-1768030-0	NO		"A41558-000", "LBG-U-02658"			
2-1768033-3	NO		F82737-000, LEB-0818P-4			
2-1768033-5	NO		"A26529-000", "LEB-0818P-8A", "4300623-F"			
2-1768033-6	NO		A36991-000, LEB-0818P-9			
2-1768033-7	NO		C84813-000, LEB-0818PF-4			
2-1768033-8	NO		D55847-000, LEB-0820P-4			
2-1768034-0	NO		D61052-000, LEB-2156P-4			
2-1768034-2	NO		C51739-000, LEB-2156P-8A			
2-1768034-3	NO		A24474-000, LEB-2156P-9			
2-1768034-4	NO		E89256-000, LEB-2156PF-4			
2-1768034-5	NO		E50053-000, LEB-2540P-4			
2-1768034-6	NO		D72586-000, LEB-2540P-8			
2-1768034-7	NO		C03955-000, LEB-2540P-8A			
2-1768034-8	NO		D09374-000, LEB-2540P-9			
2-1768404-1	NO					
2-1768404-6	NO					
2-1768406-7	NO					
2-1768407-6	NO					
2-1768407-8	NO					
2-1768407-9	NO					
2-1768410-9	NO					
2-1768417-3	NO					
2-1768419-4	NO					
2-1768419-5	NO					
2-1768423-0	NO					
2-1768709-3	NO					
202782-000	NO		1199143-2, TTPA200WE-10			
3-1768027-6	NO		"E98453-000", "LBG-U-01998"			
3-1768029-8	NO		"C05949-000", "LBG-U-02532"			
3-1768033-0	NO		A98668-000, LEB-0820P-8A			
3-1768033-1	NO		D93920-000, LEB-0820P-9			
3-1768033-2	NO		F18602-000, LEB-0820PF-4			
3-1768033-3	NO		D14539-000, LEB-0825P-4			
3-1768033-4	NO		F50978-000, LEB-0825P-8			
3-1768033-5	NO		D01324-000, LEB-0825P-8A			
3-1768033-6	NO		C16255-000, LEB-0825P-9			
3-1768033-8	NO		F44991-000, LEB-0851P-4			
3-1768033-9	NO		A12438-000, LEB-0851P-8			
3-1768034-0	NO		C15613-000, LEB-3460P-4			
3-1768034-2	NO		C95458-000, LEB-3460P-8A			
3-1768034-3	NO		D00272-000, LEB-3460P-9			
3-1768034-5	NO		A10451-000, LEB-3460S-8A			
3-1768034-7	NO		F38173-000, LEB-5270P-8			
3-1768034-8	NO		D84750-000, LEB-5270P-8A			
3-1768034-9	NO		E16129-000, LEB-5270P-9			
3-1768035-1	NO		"D09917-000", "LZ-50"			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3-1768035-2	NO		"F80468-000", "LZ-51"			
3-1768403-6	NO					
3-1768405-2	NO					
3-1768406-2	NO					
3-1768407-0	NO					
3-1768407-1	NO					
3-1768407-2	NO					
3-1768410-2	NO					
3-1768411-2	NO					
3-1768411-4	NO					
3-1768412-0	NO					
3-1768414-5	NO					
3-1768415-9	NO					
3-1768419-4	NO					
3-1768420-0	NO					
3-1768420-5	NO					
3-1768420-6	NO					
3-1768421-7	NO					
3-1768423-6	NO					
3-1768423-7	NO					
3-1768425-6	NO					
3-1768709-1	NO					
3-1768709-2	NO					
3-1768709-3	NO					
3-1768709-4	NO					
3-1768710-2	NO					
329190-000	NO		9-1198190-4, TTP600WE-10			
363702-000	NO		2-1199143-4, TTPA400WE-10			
367012-000	NO		6-1198189-1, TTP400CL-10			
379366-000	NO		1198186-5, TTP200MP-10			
390342-000	NO		8-1198186-7, TTP400WE-10			
4-1768026-3	NO		"D56288-000", "LBG-U-01666/1"			
4-1768026-4	NO		"E46590-000", "LBG-U-01667"			
4-1768026-5	NO		"E32559-000", "LBG-U-01675"			
4-1768027-3	NO		"F99376-000", "LBG-U-02040"			
4-1768027-4	NO		"C87303-000", "LBG-U-02047"			
4-1768031-9	NO		"D05870-000", "LBG-U-02776"			
4-1768032-3	NO		"F20316-000", "LEB/1325P-4"			
4-1768033-0	NO		C97490-000, LEB-0851P-8A			
4-1768033-1	NO		A64972-000, LEB-0851P-9			
4-1768033-2	NO		C25459-000, LEB-0851PF-4			
4-1768033-3	NO		D11040-000, LEB-0851S-8A			
4-1768033-4	NO		D05123-000, LEB-0876P-4			
4-1768033-6	NO		D25707-000, LEB-0876P-8A			
4-1768034-1	NO		E68114-000, LEB-5320P-4			
4-1768034-3	NO		A07520-000, LEB-5320P-8A			
4-1768034-4	NO		A14827-000, LEB-5320P-9			
4-1768034-6	NO		F93156-000, LEB-6090P-4			
4-1768034-7	NO		C05756-000, LEB-6090P-8			
4-1768034-8	NO		D22953-000, LEB-6090P-8A			
4-1768034-9	NO		A41230-000, LEB-6090P-9			
4-1768048-5	NO		D91193-000, TEK1119-N			
4-1768048-7	NO		E14842-000, TEK1119-W			
4-1768048-9	NO		E75689-000, TEK1138-N			
4-1768402-3	NO					
4-1768403-9	NO					
4-1768405-7	NO					
4-1768406-2	NO					
4-1768406-3	NO					
4-1768406-4	NO					
4-1768406-5	NO					
4-1768409-2	NO					
4-1768410-0	NO					
4-1768415-6	NO					
4-1768418-0	NO					

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4-1768420-6	NO					
4-1768420-7	NO					
4-1768420-9	NO					
410066-000	NO		1-1198184-4, TTP600MP-10			
433426-000	NO		7-1198181-1, TTP600CL-10			
438278-000	NO		1-1198182-2, TTP400BK-10			
458960-000	NO		6-1199154-4, TTPA400YW-10			
5-1768026-4	NO		"C40863-000", "LBG-U-01706"			
5-1768027-3	NO		"C06735-000", "LBG-U-02109"			
5-1768028-9	NO		"D29450-000", "LBG-U-02374"			
5-1768029-9	NO		"A49436-000", "LBG-U-02573"			
5-1768030-6	NO		"F66014-000", "LBG-U-02689"			
5-1768031-0	NO		"F28052-000", "LBG-U-02776/1"			
5-1768031-1	NO		"C14989-000", "LBG-U-02776/2"			
5-1768031-3	NO		"C11756-000", "LBG-U-02776/4"			
5-1768033-0	NO		D39410-000, LEB-0884P-4			
5-1768033-2	NO		D07134-000, LEB-0884P-8A			
5-1768033-3	NO		C20721-000, LEB-0884P-9			
5-1768033-4	NO		D07048-000, LEB-0884PF-4			
5-1768033-5	NO		C63500-000, LEB-0916P-4			
5-1768033-7	NO		E48894-000, LEB-0916P-8A			
5-1768033-8	NO		C87787-000, LEB-0916P-9			
5-1768033-9	NO		A53486-000, LEB-0916PF-4			
5-1768034-1	NO		D58678-000, LEB-A4P-4			
5-1768034-2	NO		C06149-000, LEB-A4P-4-W			
5-1768034-3	NO		F73013-000, LEB-A4P-8			
5-1768034-4	NO		D51080-000, LEB-A4P-8A			
5-1768034-5	NO		D91412-000, LEB-A4P-9			
5-1768034-6	NO		A57407-000, LEB-A4PF-4			
5-1768034-7	NO		D42416-000, LEB-A4PM-X			
5-1768034-8	NO		A52363-000, LEB-A4P-X			
5-1768034-9	NO		E85665-000, LEB-A4S-8A			
5-1768048-1	NO		A22520-000, TEK1138-W			
5-1768048-3	NO		D48362-000, TEK821-N			
5-1768048-6	NO		A23327-000, TEK914-N			
5-1768402-1	NO					
5-1768403-1	NO					
5-1768406-6	NO					
5-1768407-4	NO					
5-1768409-1	NO					
5-1768411-4	NO					
5-1768413-4	NO					
5-1768413-9	NO					
5-1768414-4	NO					
5-1768415-0	NO					
5-1768415-1	NO					
5-1768415-6	NO					
5-1768415-7	NO					
5-1768416-5	NO					
5-1768417-4	NO					
5-1768417-5	NO					
5-1768419-5	NO					
5-1768419-6	NO					
5-1768419-8	NO					
5-1768421-9	NO					
5-1768422-8	NO					
5-1768423-0	NO					
5-1768423-3	NO					
5-1768425-4	NO					
5-1768425-5	NO					
5-1768425-6	NO					
5-1768425-7	NO					
5-1768425-8	NO					
5-1768425-9	NO					
5-1768426-0	NO					

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5-1768426-1	NO					
5-1768426-2	NO					
5-1768426-3	NO					
5-1768703-3	NO					
5-1768709-3	NO					
546410-000	NO		8-1198173-9, TTP300CL-10			
550256-000	NO		2-1198174-3, TTP300WE-10			
6-1768027-1	NO		"C10548-000", "LBG-U-02133"			
6-1768027-2	NO		"A73007-000", "LBG-U-02139"			
6-1768032-9	NO		C67833-000, LEB/3460P-4			
6-1768033-0	NO		C12733-000, LEB-0920P-4			
6-1768033-2	NO		D69242-000, LEB-0920P-8A			
6-1768033-3	NO		E86499-000, LEB-0920P-9			
6-1768033-4	NO		E07029-000, LEB-0920PF-4			
6-1768033-5	NO		C59396-000, LEB-1040P-4			
6-1768033-6	NO		A35543-000, LEB-1040P-8			
6-1768033-7	NO		C92613-000, LEB-1040P-8A			
6-1768035-4	NO		E51690-000, PRM7546BL			
6-1768035-5	NO		F94966-000, PRM7546GE			
6-1768035-6	NO		E16422-000, PRM7546GN			
6-1768035-7	NO		D49226-000, PRM7546RT			
6-1768048-2	NO		D89078-000, TKM150-N			
6-1768048-4	NO		D75105-000, TKM150-W			
6-1768048-6	NO		C69399-000, TKM230-N			
6-1768403-2	NO					
6-1768407-2	NO					
6-1768407-6	NO					
6-1768411-4	NO					
6-1768413-0	NO					
6-1768414-4	NO					
6-1768420-4	NO					
6-1768421-7	NO					
6-1768422-4	NO					
6-1768422-5	NO					
6-1768422-9	NO					
6-1768423-9	NO					
6-1768425-3	NO					
6-1768425-5	NO					
6-1768426-4	NO					
6-1768426-5	NO					
6-1768426-6	NO					
6-1768426-7	NO					
6-1768426-8	NO					
6-1768709-1	NO					
6-1768709-2	NO					
6-1768710-1	NO					
7-1768026-0	NO		"C96609-000", "LBG-U-01773"			
7-1768032-2	NO		C86967-000, LEB/3460P-9			
7-1768033-0	NO		D16509-000, LEB-1318P-4			
7-1768033-1	NO		D82097-000, LEB-1318P-8			
7-1768033-2	NO		"A67201-000", "LEB-1318P-8A", "4300500-F"			
7-1768033-3	NO		D71000-000, LEB-1318P-9			
7-1768033-8	NO		D09526-000, LEB-1325P-4			
7-1768033-9	NO		E12617-000, LEB-1325P-8			
7-1768036-1	NO		D61912-000, SET-1227PSL			
7-1768036-3	NO		E15632-000, SET-1827PSL			
7-1768036-4	NO		D86269-000, SET-2222PSL			
7-1768036-5	NO		A93499-000, SET-2727PSL			
7-1768048-1	NO		A13284-000, TKM50GE-N			
7-1768048-3	NO		F09698-000, TKM50GN-N			
7-1768048-7	NO		E26117-000, TKM50WE-N			
7-1768048-8	NO		C41779-000, TKM75-H			
7-1768403-3	NO					
7-1768403-6	NO					

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
7-1768408-8	NO					
7-1768410-0	NO					
7-1768410-1	NO					
7-1768410-3	NO					
7-1768410-4	NO					
7-1768411-0	NO					
7-1768412-5	NO					
7-1768412-6	NO					
7-1768416-1	NO					
7-1768416-8	NO					
7-1768419-1	NO					
7-1768420-7	NO					
7-1768422-4	NO					
7-1768422-6	NO					
7-1768423-3	NO					
7-1768423-9	NO					
7-1768425-1	NO					
7-1768425-4	NO					
7-1768709-5	NO					
735200-000	NO		2-1198160-8, TTP200CL-10			
742278-000	NO		3-1199155-1, TTPA100YW-10			
8-1768026-3	NO		"C06325-000", "LBG-U-01825"			
8-1768026-7	NO		"E59332-000", "LBG-U-01833/1"			
8-1768026-8	NO		"E81770-000", "LBG-U-01833/2"			
8-1768027-5	NO		"A95734-000", "LBG-U-02180"			
8-1768029-9	NO		"C93476-000", "LBG-U-02632"			
8-1768030-4	NO		"E79217-000", "LBG-U-02717"			
8-1768033-0	NO		C56154-000, LEB-1325P-8A			
8-1768033-1	NO		D07123-000, LEB-1325P-9			
8-1768033-2	NO		D83271-000, LEB-1325PF-4			
8-1768033-3	NO		C05832-000, LEB-1325S-8A			
8-1768033-4	NO		F58844-000, LEB-1336P-4			
8-1768033-5	NO		C64683-000, LEB-1336P-8			
8-1768033-6	NO		D91813-000, LEB-1336P-8A			
8-1768033-7	NO		D10285-000, LEB-1336P-9			
8-1768033-8	NO		F22067-000, LEB-1336PF-4			
8-1768033-9	NO		D69604-000, LEB-1743P-4			
8-1768048-0	NO		A25727-000, TKM75-L			
8-1768048-1	NO		A93577-000, TKM75-N			
8-1768048-3	NO		E73681-000, TKM75-W			
8-1768402-7	NO					
8-1768405-4	NO					
8-1768412-8	NO					
8-1768413-5	NO					
8-1768414-3	NO					
8-1768415-2	NO					
8-1768416-1	NO					
8-1768417-3	NO					
8-1768420-2	NO					
8-1768420-3	NO					
8-1768420-4	NO					
8-1768424-0	NO					
8-1768424-2	NO					
8-1768424-6	NO					
880436-000	NO		4-1198149-9, TTP200WE-10			
9-1768027-0	NO		"C77997-000", "LBG-U-02190"			
9-1768028-8	NO		"A95789-000", "LBG-U-02454"			
9-1768032-1	NO		D72176-000, LEB-0415P-4			
9-1768032-2	NO		D42712-000, LEB-0415P-8			
9-1768032-3	NO		E67674-000, LEB-0415P-8A			
9-1768032-4	NO		D94216-000, LEB-0415P-9			
9-1768032-5	NO		D78648-000, LEB-0415PF-4			
9-1768032-8	NO		E15350-000, LEB-0608P-4			
9-1768032-9	NO		E92682-000, LEB-0608P-8			
9-1768033-0	NO		D34721-000, LEB-1743P-8			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
9-1768033-1	NO		E59097-000, LEB-1743P-8A			
9-1768033-2	NO		"D84868-000", "LEB-1743P-9", "4300522-F"			
9-1768402-8	NO					
9-1768402-9	NO					
9-1768409-6	NO					
9-1768409-9	NO					
9-1768411-0	NO					
9-1768411-9	NO					
9-1768414-3	NO					
9-1768415-3	NO					
9-1768415-6	NO					
9-1768415-7	NO					
9-1768415-8	NO					
9-1768416-1	NO					
9-1768418-5	NO					
9-1768419-4	NO					
9-1768419-9	NO					
9-1768421-5	NO					
9-1768421-6	NO					
9-1768421-7	NO					
9-1768422-6	NO					
9-1768422-8	NO					
9-1768423-6	NO					
9-1768424-0	NO					
9-1768424-2	NO					
9-1768424-6	NO					
9-1768425-4	NO					
9-1768709-9	NO					
916390-000	NO		2-1198144-2, TTP400YW-10			
930476-000	NO		6-1199155-5, TTPA200YW-10			
A03630-000	NO		6-1200611-4, MV-478175-5-8A			
A03659-000	NO		7-1200611-0, MP-171171-10-8A			
A07010-000	NO		9-1200611-9, WP-381381-2.5-9			
A07908-000	NO		1-1200612-5, MP-508095-5-8A			
A31177-000	NO		7-1200611-5, WV-762508-2.5-9			
A33676-000	NO		8-1200611-3, NC-508064-10-9			
A37084-000	NO		9-1200611-2, MP-381064-10-8A			
A37960-000	NO		9-1200611-6, MV-406254-1.5-8A			
A41119-000	NO		1200612-3, NC-250381-10-9			
A41179-000	NO		1-1200612-0, MP-095095-10-8A			
A43619-000	NO		4-1200612-1, MP-101508-2.5-8A			
A43626-000	NO		4-1200612-2, WP-254254-10-9			
A43672-000	NO		4-1200612-6, TN-381020-10-9			
A47929-000	NO		6-1200612-2, TN-191114-15-9			
A47982-000	NO		7-1200612-0, WP-445064-10-9			
A51165-000	NO		2-1200610-6, WP-318097-10-9			
A57019-000	NO		3-1200610-5, WP-127111-10-9			
A57045-000	NO		3-1200610-6, WP-165051-25-9			
A57984-000	NO		4-1200610-5, WV-381127-5-9			
A67027-000	NO		1200611-2, WP-508064-10-9			
A67976-000	NO		1-1200611-1, TN-381064-10-9			
A71160-000	NO		2-1200611-1, WP-101508-2.5-9			
A77028-000	NO		5-1200610-8, MV-165051-25-8A			
A77951-000	NO		6-1200610-2, WP-064064-25-9			
A77997-000	NO		6-1200610-7, WP-508318-2.5-9			
A83632-000	NO		8-1200610-3, MP-254064-10-8A			
A87022-000	NO		2-1200611-3, MV-229064-10-8A			
A87085-000	NO		2-1200611-8, MV-064064-25-8A			
A87942-000	NO		3-1200611-0, NC-381064-10-S1-9			
A87957-000	NO		3-1200611-1, NC-318064-10-9			
A87959-000	NO		3-1200611-2, MV-610419-2.5-8A			
A91141-000	NO		3-1200611-8, MV-508254-5-8A			
A91162-000	NO		4-1200611-1, MP-508318-2.5-8A			
A97023-000	NO		9-1200608-8, WP-165102-10-9			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
A97040-000	NO		9-1200608-9, MP-523841-1.5-8A			
A97079-000	NO		1200609-2, MV-445102-5-8A			
A97971-000	NO		1200609-7, MP-478175-5-8A			
C03798-000	NO		4-1200609-7, MP-229064-10-8A			
C07219-000	NO		6-1200609-1, MV-318097-10-8A			
C08172-000	NO		6-1200609-7, MP-318064-10-8A			
C11286-000	NO		3-1200550-3, MP-101635-2.5-8A			
C11336-000	NO		7-1200609-4, WP-101635-2.5-9			
C11340-000	NO		7-1200609-5, WV-381064-10-9			
C11378-000	NO		7-1200609-7, MP-445102-5-8A			
C13738-000	NO		7-1200609-9, MP-208086-5-8A			
C17219-000	NO		8-1200609-2, TN-254254-10-9			
C17288-000	NO		1200609-3, WP-762127-1-9			
C17298-000	NO		1200609-5, WP-381064-10-9			
C27213-000	NO		3-1200609-1, WP-127032-10-9			
C28108-000	NO		4-1200609-8, WP-381127-5-9			
C31369-000	NO		5-1200609-6, WP-254064-10-9			
C32547-000	NO		9-1200566-4, NC-191064-10-9			
C37202-000	NO		8-1200609-9, WV-165102-10-9			
C48138-000	NO		1200610-7, MP-165102-10-8A			
C57207-000	NO		7-1200607-9, MP-381127-5-8A			
C57290-000	NO		8-1200607-7, TN-044033-10-9			
C58158-000	NO		9-1200607-6, WP-089047-10-9			
C67278-000	NO		4-1200608-0, MV-508064-10-8A			
C72554-000	NO		3-1201078-2, WP-635889-1.5-4			
C73701-000	NO		4-1200608-6, WP-095080-25-9			
C78190-000	NO		7-1200607-8, NC-191762-5-9			
C81396-000	NO		8-1200607-6, WV-178095-10-9			
C83714-000	NO		8-1200607-9, WP-508095-5-9			
C91325-000	NO		1-1200608-2, MP-254127-10-8A			
C93757-000	NO		1-1200608-8, WV-445445-2-9			
C93791-000	NO		2-1200608-0, MP-508508-3-8A			
CF6337-000	NO		7-1899778-1, TTPA200BK-10			
CJ8532-000	NO		8-1899734-3, TTP400CL-10-CS8758			
CJ8610-000	NO		6-1899729-0, TTP400WE-10-CS8758			
CL7353-000	NO		5-1899820-8, TTPA250WE-10			
CM7055-000	NO		6-1899729-6, TTP200CL-10-CS8758			
CM7058-000	NO		3-1899731-1, TTP400YW-10-CS8758			
CP0390-000	NO		5-1899730-2, TTP100WE-10			
CS4718-000	NO		7-1899729-6, TTP200WE-10-CS9115			
CT98053001	NO		8-1899734-5, TTPA075WE-10-CS9245			
CV1944-000	NO		1899766-5, TTPA200WE-10CS9245			
D01421-000	NO		2-1200608-9, TN-381127-5-9			
D01443-000	NO		3-1200608-4, NC-254127-10-9			
D01460-000	NO		3-1200608-5, WP-254127-10-9			
D14042-000	NO		8-1200608-5, TN-699191-5-9			
D16834-000	NO		9-1201321-2, NC-127365-10-9			
D17308-000	NO		9-1200608-5, WV-762381-2.5-9			
D17361-000	NO		5-1200606-5, MP-699191-5-8A			
D17374-000	NO		5-1200606-6, MP-508127-5-8A			
D21432-000	NO		6-1200606-7, NC-381064-10-9			
D21452-000	NO		6-1200606-8, MP-101762-1.8-8A			
D21493-000	NO		7-1200606-6, WV-318064-10-9			
D24019-000	NO		8-1200606-6, WP-254097-10-9			
D24083-000	NO		9-1200606-3, WP-445102-5-9			
D27420-000	NO		8-1200804-2, TTPA200RD-10			
D28217-000	NO		1-1200607-2, WV-165051-25-9			
D28245-000	NO		1-1200607-5, MP-508064-10-8A			
D31439-000	NO		2-1200607-7, WP-508508-3-9			
D31494-000	NO		5-1200606-2, MP-064064-25-8A			
D37349-000	NO		7-1200606-9, NC-381381-2.5-9			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
D41400-000	NO		1200607-3, MV-254254-10-8A			
D41432-000	NO		1200607-4, WP-318064-10-9			
D54061-000	NO		4-1200607-9, MP-254254-10-8A			
D54063-000	NO		5-1200607-0, WP-101101-1.3-9			
D62315-000	NO		5-1201054-3, MP-368076-10-8A			
D64036-000	NO		7-1200607-2, NC-381127-5-9			
D67328-000	NO		2-1200605-3, TN-318097-10-9			
D67366-000	NO		2-1200605-7, WP-610419-2.5-9			
D68241-000	NO		4-1200605-7, TN-254064-10-9			
D68278-000	NO		5-1200605-4, WP-250381-10-9			
D71481-000	NO		6-1200605-8, WP-114040-25-9			
D74058-000	NO		8-1200605-4, WP-101165-0.85-9			
D81438-000	NO		2-1200605-6, WP-699191-5-9			
D86363-000	NO		8-1201262-5, WP-699318-2.5-9			
D87328-000	NO		4-1200605-3, TN-127111-10-9			
D87365-000	NO		4-1200605-8, WV-101508-2.5-9			
D87475-000	NO		7-1200565-2, NC-165051-25-9			
D91401-000	NO		5-1200605-9, WP-762381-2.5-9			
D91458-000	NO		6-1200605-2, MV-381191-5-8A			
D98236-000	NO		1200606-9, WP-080080-10-9			
E07470-000	NO		2-1200606-8, WP-095095-10-9			
E09398-000	NO		4-1201673-1, MP-556102-10-4			
E09933-000	NO		8-1201791-5, TTP1000CL-10			
E11530-000	NO		3-1200606-8, MV-508318-2.5-8A			
E21509-000	NO		2-1200604-4, MP-165051-25-8A			
E21530-000	NO		3-1200604-1, MP-178095-10-8A			
E21545-000	NO		3-1200604-9, MV-127127-10-8A			
E27427-000	NO		7-1200604-0, MV-254064-10-8A			
E28312-000	NO		9-1200603-5, WV-229064-10-9			
E31574-000	NO		1-1200604-3, WV-254064-10-9			
E34125-000	NO		1-1200604-8, WV-508095-5-9			
E38328-000	NO		2-1200604-9, TN-191064-10-9			
E41599-000	NO		3-1200604-8, MP-762381-2.5-8A			
E44791-000	NO		3-1200549-6, MP-762508-2.5-8A			
E45872-000	NO		5-1201293-3, WP-165051-25-9-5AC			
E47409-000	NO		6-1200604-1, MP-095080-25-8A			
E47442-000	NO		6-1200604-3, MV-699191-5-8A			
E48361-000	NO		6-1200604-7, TN-381191-5-9			
E54104-000	NO		8-1200604-2, MP-305047-10-8A			
E57283-000	NO		6-1200834-0, TTP200YW-10			
E57460-000	NO		9-1200604-1, MP-445064-10-8A			
E57467-000	NO		9-1200604-3, TN-089047-10-9			
E58363-000	NO		9-1200604-7, WP-305047-10-9			
E58375-000	NO		9-1200604-8, WP-254045-10-9			
E60715-000	NO		5-1201251-5, WP-191064-10-9-T200			
E63497-000	NO		1-1200804-4, TTPA200MP-10			
E64177-000	NO		1-1200605-5, MP-318097-10-8A			
E64189-000	NO		1-1200605-6, MP-254097-10-8A			
E66212-000	NO		2-1200837-9, WP-762254-5-9			
E67401-000	NO		1-1200605-7, MP-445445-2-8A			
E67479-000	NO		8-1200602-8, MP-127111-10-8A			
E68336-000	NO		9-1200602-6, WP-203127-10-9			
E68365-000	NO		1200603-9, WP-699254-5-9			
E68367-000	NO		1-1200603-0, WV-610419-2.5-9			
E71523-000	NO		1-1200603-9, WP-406254-1.5-9			
E74142-000	NO		4-1200603-0, WP-508254-5-9			
E77497-000	NO		4-1200603-5, WP-127127-10-9			
E81542-000	NO		8-1200602-2, WP-445445-2-9			
E87488-000	NO		1200603-1, WV-101635-2.5-9			
E88369-000	NO		1-1200603-1, TN-508254-5-9			
E91539-000	NO		2-1200603-4, WV-508254-5-9			
E91557-000	NO		3-1200603-1, WP-178095-10-9			
E94126-000	NO		3-1200603-9, MV-381127-5-8A			
E97476-000	NO		5-1200603-3, WV-089047-10-9			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
E98167-000	NO		4-1201698-0, WP-101229-6.6-9			
E98371-000	NO		6-1200603-1, WP-478175-5-9			
E99087-000	NO		9-1201563-6, WP-127064-10-9			
F01602-000	NO		6-1200603-5, WV-508127-5-9			
F01667-000	NO		6-1200603-8, WP-191064-10-9			
F07559-000	NO		7-1200603-9, MV-381064-10-8A			
F07566-000	NO		8-1200603-0, MP-089047-10-8A			
F07599-000	NO		8-1200603-2, MP-508254-5-8A			
F08409-000	NO		8-1200603-4, NC-229064-10-9			
F08497-000	NO		8-1200603-9, MP-762127-1-8A			
F14201-000	NO		9-1200603-2, MP-610419-2.5-8A			
F14221-000	NO		9-1200603-4, MP-381381-2.5-8A			
F24274-000	NO		8-1200601-4, TN-127127-10-9			
F27528-000	NO		1200602-3, MP-699254-5-8A			
F27584-000	NO		1200602-5, MP-203127-10-8A			
F27596-000	NO		1200602-6, MP-381191-5-8A			
F28482-000	NO		5-1200601-4, NC-508127-5-9			
F31612-000	NO		6-1200601-1, NC-254097-10-9			
F34217-000	NO		6-1200601-8, WP-101762-1.8-9			
F37507-000	NO		8-1200601-1, MV-762508-2.5-8A			
F38449-000	NO		1200602-1, MP-191114-15-8A			
F48442-000	NO		2-1200602-1, WP-040040-25-9			
F48449-000	NO		2-1200602-2, WP-523841-1.5-9			
F51616-000	NO		2-1200602-8, WV-381191-5-9			
F51654-000	NO		3-1200602-1, WV-699191-5-9			
F54250-000	NO		3-1200602-4, MV-254127-10-8A			
F57507-000	NO		4-1200602-1, MP-406254-1.5-8A			
F58436-000	NO		4-1200602-7, TN-165051-25-9			
F58495-000	NO		5-1200602-0, MV-762381-2.5-8A			
F64200-000	NO		5-1200602-5, TN-254127-10-9			
F65989-000	NO		7-1201220-4, WP-127CIR-10-9			
F67510-000	NO		6-1200602-7, MP-101101-1.3-8A			
F71282-000	NO		6-1201251-8, NC-127191-10-9			
F71606-000	NO		7-1200600-0, WP-229064-10-9			
F71623-000	NO		7-1200600-3, WV-699254-5-9			
F71693-000	NO		8-1200600-1, WV-254097-10-9			
F74262-000	NO		8-1200600-6, WP-508127-5-9			
F77500-000	NO		9-1200600-3, WV-445102-5-9			
F77516-000	NO		9-1200600-5, WP-191114-15-9			
F77529-000	NO		1200601-1, WP-381191-5-9			
F77590-000	NO		1-1200601-1, WP-171171-10-9			
F78456-000	NO		7-1200600-6, WV-254127-10-9			
F78472-000	NO		8-1200600-0, MP-191064-10-8A			
F97088-000	NO		3-1200548-6, WP-762508-2.5-9			
F98478-000	NO		4-1200601-0, TN-508508-3-9			