

06-Jun-2019 **PCN #:**P-19-017473

Subject: MQS 3 pos Housing

Description of Change: Dear customer, this PCN refers to PCN E-19-006334. We would also like to point out that it is urgently necessary for you to check your test adapters to see whether they meet the following criteria: We inform you about a seal change at MQS housing PNs 967642 and 1418603, which are under design responsibility of TE Connectivity. New seal design has an optimized geometry with improved mating and unmating forces of the assembly. Interface drawing 114-18063-123 Rev. A1 for test adapters and counterparts will not be changed and is still valid. Old part revision (before change) and new part revision (after change) can be checked with the same test adapters, if test adapters are according to TE interface drawing. Please check that your test adapters are according to valid interface drawing. If test adapters are not according to valid interface drawing, these have to be changed by customer. Samples for checking can be provided by TE Connectivity, if needed.

Reason: Product improvement.

Key Dates:

Contact By Date: 12-Feb-2020

Implementation Date:12-Feb-2020

Product Affected

2-967642-2

1418603-2

2-967642-1

1-967642-1

(Alias Part Numbers:

"1-0967642-1")

5-967642-1



or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the change of the cha

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.