

## PRODUCT CHANGE NOTIFICATION

Product Category ABRASION PROTECTION **20231231-1**

Product Group DUCT AND ABRASION

ISSUE DATE:  N/A  EMEA  LATAM  APDec-23

IMPACTED REGIONS:  DISCONTINUATION

REASON FOR CHANGE:  OTHER

### DESCRIPTION OF CHANGE: (Required)

Effective December 31, 2023 we will no longer include an installation tool in packages of Panduit spiral wrap products.

Photos/Drawing (where applicable)



IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2023	12	31

**CUSTOMER SERVICE CONTACTS**

<b>ASIA PACIFIC</b>	<b>AUSTRALIA: 1-800 7263848</b> <a href="mailto:AUS-CSVM@panduit.com">AUS-CSVM@panduit.com</a>	<b>CHINA: 400-820-1900</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	<b>HONG KONG: 800-965768</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>
	<b>INDIA: 000 800 6501844 (Fixed)</b> 000 800 6500369 (Mobile) <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>INDONESIA: 001 803 65 7571</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>JAPAN: +81-3-6863-6000</b> <a href="mailto:JPN-CS@panduit.com">JPN-CS@panduit.com</a>
	<b>KOREA: 02-2182-7300</b> <a href="mailto:KOR-CustomerService@panduit.com">KOR-CustomerService@panduit.com</a>	<b>MALAYSIA 1800 801435</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>SINGAPORE: 1-800-7263848</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>
	<b>TAIWAN: 0080 165 1487</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>THAILAND: 001-800-65-6385</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	
	<b>LATIN AMERICA</b> <b>BRAZIL 08000562613 (Toll Free)</b> <a href="mailto:BRA-custservice@panduit.com">BRA-custservice@panduit.com</a>	<b>MEXICO: +52-33-37776000 x80520</b> 01 800 360 86 00 (Toll Free) <a href="mailto:MEX-customerservice@panduit.com">MEX-customerservice@panduit.com</a>	<b>OTHER LA COUNTRIES:</b> Phone USA 1-708-532-1800 <a href="mailto:TP-CS-INTERNATIONAL@panduit.com">TP-CS-INTERNATIONAL@panduit.com</a>
<b>NORTH AMERICA</b> USA & CANADA: 1-800-777-3300 <a href="mailto:cs@panduit.com">cs@panduit.com</a>	<b>EMEA</b>	<b>EMEA: +44 208 6017219</b> <a href="mailto:EMEA-CustomerServices@panduit.com">EMEA-CustomerServices@panduit.com</a>	

IMPACTED PART NUMBER(s)	IMPACTED PART NUMBER(s)
T12R-CY	T50F-C4Y
T12T-C	T50F-C3Y
T12F-D	T50N-TL0
T12N-C0	T50N-TL0
T12N-C	T50R-TLY
T12N-D	T50R-CY
T12F-C0	T50F-X0
T12F-C	T50F-X
T12FR-CY	T50FR-CY
T12FR-C20Y	T50FR-TLY
T19F-M	T50F-C7
T19F-C0	T50F-C6
T19F-C	T50F-C5
T19T-C	T50F-TL
T19N-C	T50F-C8
T19N-C0	T50T-Q
T19R-CY	T50F-C
T19FR-CY	T50F-C10
T19FR-C20Y	T50F-C0
T25N-C	T50N-C
T25N-C	T50N-C
T25F-C	T50N-TL
T25T-L0	T50N-TL
T25FR-M	T50N-C0
T25N-M0	T50N-C0
T25N-M0	T50F-TL4Y
T25N-M	T50FR-C20Y
T25N-M	T50P-C0
T25N-C0	T50P-C0
T25N-C0	T50NZFR-C20

T25F-C6	T62F-TL0
T25F-M0	T62N-C
T25F-M	T62N-C
T25F-C8	T62R-CY
T25F-C10	T62N-C0
T25F-C0	T62N-C0
T25R-CY	T62F-C0
T25R-M20Y	T62F-C
T25R-MY	T62T-Q
T25R-C20Y	T62FR-CY
T25F-X0	T62FR-C20Y
T25F-C2	T75F-C
T25F-C4Y	T75F-C0
T25F-C3Y	T75F-T0
T25T-L	T75N-T
T25FR-CY	T75N-T
T25FR-MY	T75N-C0
T25FR-C20Y	T75N-C0
T25FR-M20Y	T75N-C
T25NZFR-C20	T75N-C
T25FG-C0	T75T-X
T38F-C	T75R-CY
T38N-TL	T75F-T
T38N-TL	T75FR-CY
T38R-CY	T75FR-TY
T38F-TL0	T75FR-C20Y
T38F-TL	T75NZFR-C20
T38T-L	T75P-C0/N
T38R-TLY	T75P-C0/N
T38N-C0	T100N-C0
T38N-C0	T100N-C0

T38N-C	T100N-C
T38N-C	T100N-C
T38F-C0	T100R-CY
T38FR-CY	T100T-X
T38FR-TLY	T100F-C0
T38FR-C20Y	T100F-C
T38P-C0	T100FR-CY
T38P-C0	T100FR-C20Y
T38NZFR-C20	T100P-C0
T50F-TL0	T100P-C0
T50F-C2	