



11-Jan-2023

PCN #: PCN-23-163285

Subject : Datasheet for Relay package SNR corrected by relay description.

Description of Change : Update and add new part numbers/part descriptions to capture the recommended combination of relay with the socket. Standard pin combinations for panel mounting and pcb pin combinations for pcb mounting.

Reason : Document clarification

Key Dates :

Contact By Date:16-Jan-2023

Implementation Date:16-Jan-2023

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
3-1416100-0	"D40517-000", "AMPS-3-1416100-0", "ST3P2LC4"		
3-1416100-2	"A45179-000", "AMPS-3-1416100-2", "ST3P3LC4"		
3-1416100-3	"C62820-000", "AMPS-3-1416100-3", "ST3P3SM5"		
3-1416100-4	"F60449-000", "AMPS-3-1416100-4", "ST3P3TP0"		
3-1416100-1	"E71897-000", "AMPS-3-1416100-1", "ST3P3LB2"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.