

PCN #	53171
Issued Date:	18-Jul-18
Issued By:	Louie Dichoso
Author:	Louie Dichoso



Change affects whole product family?	NO
--------------------------------------	----

Part #'s affected (See attached if entire product family is affected)

598-8610-202F, -207F, 598-8621-202F, -207F, 598-8640-202F,-207F, 598-8660-202F, -207F

Description of Change:

Corrected the polarity, color callout on schematic for all part numbers. Cathode/anode placement reversed as well as color designated to the pins. Also updated a few dominant wavelength values on the chart



Reason for Change:

Incorrect schematic and data needs to be updated

Properties of Old vs. Changed Product:

Disposition of Old Product:

Use as is, product is correct and only documentation error

Expected Implementation Date:	immediate
Customer Feedback Expected by:	n/a

Additional Comments: (Include Potential Risks if Appropriate)

documentation error

Supporting Qualification Data:

n/a

ation

vell as the