

Dear Customer,

With this INFINEON Technologies Errata Note we would like to inform you about the following

Erratum of product marking in datasheet for IPD046N08N5

Infineon Technologies AG
Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0
Chairman of the Supervisory Board: Dr. Wolfgang Eder
Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Dr. Sven Schneider
Registered Office: Neubiberg
Commercial Register: München HRB 126492

Erratum of Product Marking in datasheet for IPD046N08N5

► **Products affected:**

Sales name	SP number	OPN	Package
IPD046N08N5	SP001475652	IPD046N08N5ATMA1	PG-TO252-3

► **Detailed Change Information:**

Subject: Erratum of product marking in datasheet for IPD046N08N5

Reason: Product marking in datasheet shows nonconformance compared to the physical product marking on the device

Description:

Old

- 046N08N5

New

- 046N08N

► **Impact of Change:**

NO change of existing datasheet parameters

NO change in quality and reliability

NO change in package outline dimensions

► **Attachments:**

3_cip10198.pdf Product datasheet IPD046N08N5_2_1

► **Implementation Date:**

2020-April-01

If you have any questions, please do not hesitate to contact your local Sales office.