



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451

Monday 7th March 2022

Dear Customer,

Re: Product Change notification for Harwin product.

Please be advised that the male horizontal connectors in the M83 Series (Datamate 3-Row Jackscrew) have had the nominal dimension on the termination/tail length changed on the applicable Technical Drawings. The length has changed from (4.0mm) to (3.5 +0.6/-0.5mm).

This change has been made so that the drawings accurately accommodate the tolerance of the individual components. No changes have been made to the actual production process.

The parts affected include:

- M83-LML3M1Nxx-0000-000
- M83-LML3M5N18-0000-000
- M83-LML3M7N18-0000-000
- M83-LML3M5N13-0302-333
- M83-LML3M5N19-0101-333

Please see the following spreadsheet for a detailed list of affected items:

https://cdn.harwin.com/pdfs/PCN_spreadsheet_2022-03-07.xlsx

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team
technical@harwin.com

Product Change Notification from Harwin

Part number affected	Drawing for affected product
M83-LML3M1N18-0000-000	M83-LML3M1NXX-0000-000.pdf
M83-LML3M1N27-0000-000	M83-LML3M1NXX-0000-000.pdf
M83-LML3M1N36-0000-000	M83-LML3M1NXX-0000-000.pdf
M83-LML3M1N48-0000-000	M83-LML3M1NXX-0000-000.pdf
M83-LML3M1N54-0000-000	M83-LML3M1NXX-0000-000.pdf
M83-LML3M1N60-0000-000	M83-LML3M1NXX-0000-000.pdf
M83-LML3M1N96-0000-000	M83-LML3M1NXX-0000-000.pdf
M83-LML3M5N18-0000-000	M83-LML3M5NXX-0000-000.pdf
M83-LML3M5N27-0000-000	M83-LML3M5NXX-0000-000.pdf
M83-LML3M5N36-0000-000	M83-LML3M5NXX-0000-000.pdf
M83-LML3M5N48-0000-000	M83-LML3M5NXX-0000-000.pdf
M83-LML3M5N54-0000-000	M83-LML3M5NXX-0000-000.pdf
M83-LML3M5N60-0000-000	M83-LML3M5NXX-0000-000.pdf
M83-LML3M5N96-0000-000	M83-LML3M5NXX-0000-000.pdf
M83-LML3M5N13-0302-333	M83-LML3M5N13-0302-333.pdf
M83-LML3M5N19-0101-333	M83-LML3M5N19-0101-333.pdf
M83-LML3M7N18-0000-000	M83-LML3M7NXX-0000-000.pdf
M83-LML3M7N27-0000-000	M83-LML3M7NXX-0000-000.pdf
M83-LML3M7N36-0000-000	M83-LML3M7NXX-0000-000.pdf
M83-LML3M7N48-0000-000	M83-LML3M7NXX-0000-000.pdf
M83-LML3M7N54-0000-000	M83-LML3M7NXX-0000-000.pdf
M83-LML3M7N60-0000-000	M83-LML3M7NXX-0000-000.pdf
M83-LML3M7N96-0000-000	M83-LML3M7NXX-0000-000.pdf