

Issue Date: April 7th, 2020

Dear Valued Customer,

This notice is to inform you of changes affecting item(s) that you have purchased from Littelfuse.

Description of the Change:

- We are insourcing the production of the packaging plastics used in the attached part numbers.

Reason for The Change:

- Our current supplier, one who had been supplying these components to us since before the acquisition of Cole Hersee, no longer meets supplier requirements to continue to support these types of components.
- Our investment represents our commitment to enhance the supply chain used to support these finished goods.

Effective Date of the Change:


- We will conduct this insourcing as a running change, with existing/procured stock targeted to last through June 2020. Stock shipped after that point will begin to utilize insourced components, on a part number-by-part number basis.

What You Need to Do:

- There will be no change to fit, form, or function, of these products, and no action is required on your behalf. As we are coordinating this as a running change, your supply will not be disrupted.

If you have any questions, please feel free to contact your Littelfuse Customer Service Representative or your Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,



Zachary Naughton
Global Product Manager
Littelfuse Commercial Vehicle Products

Items Purchased by Your Company That Are Affected by The Changes:

00940133ZP
00940134ZP
00940135ZP
00940154ZP
00940189ZP
00940202ZP
00940202ZPGLO
00940202ZPGLOBK
00940301ZP
00940362ZP
00940362ZPGLO
00940362ZPGLOBK
00940363ZP
00940365ZP
00940366ZP
00940367ZP
00940368ZP
00940369ZP
00940370ZP
00940400Z
00940400ZGLO
00940402ZP
00940408ZP
00940413ZP
00940418ZP
00940419ZP
00940441ZP
00940442ZP
00940461ZP
00940462Z
00940462ZGLO
00940475Z
00940479ZP
00940506ZP
00940550Z
00940554Z
00940557ZXA
00940558ZPA

00940559ZPA
00940559ZPAS
00940561ZPA
00940562ZPA
00940563ZPA
00940564ZPA
00940565ZPA
00940566ZPA
00940566ZXA
00940567ZPA
00940569ZPA
00970019X
00970019XP
00970023XP
00970025XPA
00970026XP
00970038XPA
00970053XP
00970054XPA
0185100.XP
0185120.XP
0185150.XP
0211010.XP
0211015.XP
0211020.XP
0211025.XP
0211030.XP
02400113XP
03453LF2XP
03453LF8XP
03500417XP
03500418XP
0813020.XP
0813030.XP
0813040.XP
0813050.XP
0ACB020.XP
0ACB030.XP

0AFH0001XP
0AFH0002XP
0AGA0001ZP
0AGA0002ZP
0AGA0003ZP
0AGA001.VP
0AGA002.VP
0AGA003.VP
0AGA005.VP
0AGA010.VP
0AGA015.VP
0AGA020.VP
0AGA030.VP
0AGC0001ZP
0AGC0001ZPGLO
0AGC0002ZP
0AGC0003ZP
0AGC0004ZP
0AGC0005ZP
0AGC001.VP
0AGC002.VP
0AGC003.VP
0AGC004.VP
0AGC005.VP
0AGC006.VP
0AGC01.5VP
0AGC010.VP
0AGC015.VP
0AGC02.5VP
0AGC020.VP
0AGC025.VP
0AGC030.VP
0AGC035.VP
0AGC07.5VP
0AGU040.VPG
0AGU050.VPG
0AGU060.VPG

Items Purchased by Your Company That Are Affected by The Changes (cotd):

0AGW0001ZP
0AGW0002ZP
0AGW005.VP
0AGW015.VP
0AGW020.VP
0AGW030.VP
0AGX0002ZP
0AGX020.VP
0AGX025.VP
0AGX030.VP
0ATD0300ZBP
0ATO001.VP
0ATO002.VP
0ATO003.VP
0ATO003.VPGLO
0ATO004.VP
0ATO005.VP
0ATO005.VPGLO
0ATO005.ZXPRO
0ATO010.VP
0ATO010.VPGLO
0ATO010.VPGLOBK
0ATO010.ZXPRO
0ATO015.VP
0ATO015.VPGLO
0ATO015.VPGLOBK
0ATO015.ZXPRO
0ATO020.TPGLOBK
0ATO020.VP
0ATO020.VPGLO
0ATO020.VPGLOBK
0ATO020.ZXPRO
0ATO025.VP
0ATO025.VPGLO
0ATO025.VPGLOBK
0ATO025.ZXPRO
0ATO030.TPGLOBK
0ATO030.VP

0ATO030.VPGLO
0ATO030.VPGLOBK
0ATO030.ZXPRO
0ATO040.VP
0ATO07.5VP
0ATO07.5VPGLO
0ATO07.5ZXPRO
0BPF0001ZP
0CBF010.XP
0CBF015.XP
0CBF020.XP
0CBF025.XP
0CBF030.XP
0CBF035.XPA
0CBF040.XP
0CCB025.XP
0EFL0102XP
0FCB020.XP
0FHA0001XP
0FHA0001XPGLO
0FHA0002XP
0FHA0030XP
0FHA0200ZP
0FHM0001XP
0FHM0001XPGLO
0FHM0002XP
0FHM0200ZP
0FHM0200ZPA
0FLC014.XP
0FLC014.XPA
0FLW014.XP
0FLW016.XP
0FNY0001XP
0FNY0020XP
0FNY0030XP
0GBC005.VPA
0GBC008.VP
0GBC016.VP

0GBC025.VP
0MAB0001XP
0MAX020.XP
0MAX020.XPGLO
0MAX030.XP
0MAX030.XPGLO
0MAX030.XPGLOBK
0MAX040.XP
0MAX040.XPGLO
0MAX040.XPGLOBK
0MAX050.XP
0MAX050.XPGLO
0MAX050.XPGLOBK
0MAX060.XP
0MAX060.XPGLO
0MAX060.XPGLOBK
0MAX070.XP
0MAX070.XPGLO
0MAX080.XP
0MAX080.XPGLO
0MAX080.XPGLOBK
0MAX100.XPGLO
0MAX100.XPGLOBK
0MEG080.X
0MEG080.XPA
0MEG100.X
0MEG100.X-PAC
0MEG100.XP
0MEG125.X
0MEG125.X-PAC
0MEG125.XP
0MEG150.X
0MEG150.X-PAC
0MEG150.XP
0MEG175.X
0MEG175.X-PAC
0MEG175.XP
0MEG200.X

Items Purchased by Your Company That Are Affected by The Changes (cotd):

0MEG200.X-PAC
0MEG200.XP
0MEG225.X
0MEG225.X-PAC
0MEG225.XP
0MEG250.X
0MEG250.X-PAC
0MEG250.XP
0MEG300.X
0MEG350.X
0MEG400.X
0MEG450.X
0MEG500.X
0MID050.XP
0MID080.XP
0MID150.XP
0MIN002.VP
0MIN003.VP
0MIN003.VPGLO
0MIN004.VP
0MIN005.VP
0MIN005.VPGLO
0MIN010.VP
0MIN010.VPGLO
0MIN010.VPGLOBK
0MIN010.ZXPRO
0MIN015.VP
0MIN015.VPGLO
0MIN015.VPGLOBK
0MIN015.ZXPRO
0MIN020.TPGLOBK
0MIN020.VP
0MIN020.VPGLO
0MIN020.VPGLOBK
0MIN020.ZXPRO
0MIN025.VP
0MIN025.VPGLO
0MIN025.VPGLOBK

0MIN025.ZXPRO
0MIN030.VP
0MIN030.VPGLO
0MIN030.VPGLOBK
0MIN030.ZXPRO
0MIN07.5VP
0MIN07.5VPGLO
0OMN0002XP
0OMN0004XP
0PAL020.X
0PAL020.XP
0PAL030.X
0PAL030.XP
0PAL040.X
0PAL040.XP
0PAL050.X
0PAL050.XP
0PAL060.X
0PAL060.XP
0PAL1100X
0PAL1100XP
0PAL1120X
0PAL1120XP
0PAL130.X
0PAL130.XP
0PAL160.X
0PAL160.XP
0PAL180.X
0PAL180.XP
0PAL2100X
0PAL2100XP
0PAL2120X
0PAL2120XP
0PAL2140XP
0PAL230.X
0PAL230.XP
0PAL240.X
0PAL240.XP

0PAL250.X
0PAL250.XP
0PAL260.X
0PAL260.XP
0PAL270.X
0PAL270.XP
0PAL280.X
0PAL280.XP
0PAL330.X
0PAL330.XP
0PAL340.X
0PAL340.XP
0PAL4100X
0PAL4100XP
0PAL4120XP
0PAL4140XP
0PAL430.X
0PAL430.XP
0PAL440.X
0PAL440.XP
0PAL450.X
0PAL450.XP
0PAL480.X
0PAL480.XP
0PAL525.X
0PAL525.XP
0PAL530.X
0PAL530.XP
0SFE0001ZP
0SFE0001ZPGLO
0SFE0002ZP
0SFE0003ZP
0SFE004.VP
0SFE006.VP
0SFE009.VP
0SFE014.VP
0SFE020.VP

Items Purchased by Your Company That Are Affected by The Changes (cotd):

0SFE030.VP
0SFE07.5VP
0UCB005.XP
0UCB006.XP
0UCB010.XP
0UCB015.XP
0UCB020.XP
0UCB025.XP
0UCB030.XP
FHAC0001XP
FHAC0002XP
FHLM0200ZPA
FHM20200ZPA
JCAS020.XP
JCAS025.XPA
JCAS030.XP
JCAS040.XP
JCAS050.XP
JCAS060.XP
LJCA020.XP
LJCA025.XPA
LJCA030.XP
LJCA040.XP
LJCA050.XP
LJCA060.XP
LMIN005.VP
LMIN005.ZXPROA
LMIN010.VP
LMIN010.ZXPROA
LMIN015.VP
LMIN015.ZXPROA
LMIN020.VP
LMIN020.ZXPROA

LMIN025.VP
LMIN025.ZXPROA
LMIN030.VP
LMIN030.ZXPROA
LMIN07.5VPW
MCAS015.XP
MCAS015.XP-BK
MCAS015.XPS
MCAS020.XP
MCAS020.XP-BK
MCAS020.XPS
MCAS025.XP
MCAS025.XP-BK
MCAS025.XPS
MCAS030.XP
MCAS030.XP-BK
MCAS030.XPS
MCAS040.XP
MCAS040.XP-BK
MCAS040.XPS
MCAS050.XPS
MCAS060.XPS
MIC2005.VP
MIC2005.VP-BK
MIC2010.VP
MIC2010.VP-BK
MIC2010.ZXPRO
MIC2015.VP
MIC2015.VP-BK
MIC2015.ZXPRO
MIC2020.VP
MIC2020.VP-BK
MIC2020.ZXPRO

MIC2025.VP
MIC2025.VP-BK
MIC2030.VP
MIC2030.VP-BK
MIC2030.ZXPRO
MIC207.5VP
MIC207.5VP-BK
MIC3005.VP
MIC3005.VP-BK
MIC3005.ZXPRO
MIC3010.VP
MIC3010.VP-BK
MIC3010.ZXPRO
MIC3015.VP
MIC3015.VP-BK
MIC3015.ZXPRO
MIC307.5VP
MIC307.5VP-BK
MIC307.5ZXPRO
ZCAS080.XP
ZCAS100.XP
ZCAS125.XP
ZCAS150.XP
ZCAS175.XP
ZCAS200.XP
ZCAS225.XP
ZCAS250.XP
ZCAS300.XP
ZCAS350.XP
ZCAS400.XP
ZCAS500.XP