



04-Jul-2023

PCN #: PCN-23-179438

Subject : EP2.5 plug housing

Description of Change : Please be aware of an upcoming feature change to the listed part numbers.
Before: the slot width is 1.60mm
After: the slot width is 1.40mm

Reason : Update made to improve customer problem: Terminal incorrect insertion into housing

Key Dates :

Contact By Date:10-Jan-2024

Implementation Date:10-Jan-2024

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
1969442-5			
5-2338183-3			
3-2338183-2			
1-2338183-6			
3-2324579-8			
7-2338183-5			
6-2338183-6			
1-2324579-4			
1-2338183-2			
3-2324579-4			
1-2323743-8			
2-2324579-2			
8-2338183-2			
8-2338183-7			
4-2324579-0			
3-2323743-8			

1-1969442-6			
3-2338183-7			
5-2338183-5			
2-2338183-3			
1-2324579-0			
2-2323743-0			
1-2338183-7			
4-2338183-0			
2338183-3			
6-2338183-4			
7-2338183-6			
9-2338183-3			
1-2324579-6			
1969442-2			
2-2324579-0			
3-2338183-9			
1969442-4			
5-2338183-9			
6-2338183-5			
9-2338183-2			
1744417-4			
4-2338183-9			
2-2338183-0			
1744417-6			
2-1969442-0			
1-1744417-4			
1-2324579-2			
1-1969442-9			
1-2428310-0			
1-1969442-3			
1-2338183-0			
1-2338183-1			
5-2338183-7			
1-2338183-3			
8-2338183-9			
4-2338183-7			

1-1969442-5			
1-1969442-0			
4-2338183-8			
7-2338183-1			
2338183-7			
9-2338183-8			
2-2324579-6			
2338183-2			
3-2338183-3			
4-2323743-0			
2-2323743-8			
8-2338183-5			
3-2338183-0			
1-2338183-4			
3-2338183-6			
8-2338183-6			
2-1744417-0			
1-2323743-6			
2-2338183-8			
7-2338183-8			
1-1744417-7			
2428310-9			
3-2338183-1			
1-1969442-1			
2-2323743-2			
3-2338183-4			
7-2338183-7			
9-2338183-7			
1-1744417-9			
2338183-1			
1-1744417-8			
9-2338183-5			
1-1969442-4			
6-2338183-7			
1969442-6			
1-1744417-3			

8-2338183-0			
2338183-6			
2-2338183-7			
1744417-9			
2-2338183-4			
1969442-3			
2338183-5			
2-2324579-4			
6-2338183-9			
2-2338183-2			
3-2323743-6			
6-2338183-8			
7-2338183-0			
2301559-2			
2-2324579-8			
2-2338183-6			
9-2338183-0			
4-2338183-3			
1-1969442-7			
4-2338183-4			
5-2338183-2			
2-2323743-4			
2338183-4			
1969442-9			
1-2323743-4			
5-2338183-6			
1744417-5			
2-2323743-6			
3-2338183-8			
1-2428310-1			
1-1969442-2			
1-1744417-1			
5-2338183-8			
1-1969442-8			
4-2338183-5			
2338183-8			

7-2338183-9			
8-2338183-4			
1744417-2			
4-2338183-2			
6-2338183-2			
8-2338183-8			
9-2338183-6			
1969442-8			
1-1744417-0			
5-2338183-0			
2324579-8			
2-2338183-9			
1-2323743-0			
7-2338183-3			
6-2338183-0			
7-2338183-4			
7-2338183-2			
1-1744417-5			
3-2324579-6			
2338183-9			
3-2338183-5			
3-2324579-0			
3-2323743-2			
1-1744417-2			
2323743-8			
1-2338183-8			
3-2324579-2			
9-2338183-4			
9-2338183-9			
1-2324579-8			
2-2338183-5			
1-2338183-5			
3-2323743-0			
9-2338183-1			
6-2338183-3			
8-2338183-3			

1-2323743-2			
5-2338183-4			
3-2323743-4			
1744417-8			
1-2338183-9			
1744417-7			
1-2428310-2			
1969442-7			
1-1744417-6			
4-2338183-6			
5-2338183-1			
1744417-3			

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.