



PCN# : P631AAB
Issue Date : Mar. 24, 2016

Information Only Notification

This is to inform you that a change is being made to the following products.

This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products on or after the issue date of this notification.

Please contact your local Customer Quality Engineer if you have any questions regarding this notification.

Implementation of change:

Description of Change (From) :
Minimum Order Quantity (MOQ) as per one tube quantity.

Description of Change (To) :
Reflect new Minimum Order Quantity (MOQ) as per bag quantity. Increase minimum order quantity for tube packed devices.

| Generic Package | MOD | PackID | MOQ From | MOQ To |
|-----------------|----------|--------|----------|--------|
| TS6P | TS6P04A | P01022 | 15 | 1200 |
| DPBR7 | GBU04A | CABT02 | 20 | 800 |
| AC | AC014A | QTT025 | 25 | 550 |
| NMDIP | N16E | M20009 | 25 | 500 |
| TQ247 | TO247E03 | CATT01 | 30 | 1500 |
| NMDIP | N08E | M20004 | 40 | 1000 |
| TT220 | TO220B03 | CATT02 | 50 | 1000 |
| NMSON | M08A | M20516 | 95 | 4750 |
| NMSON | M08A | M20025 | 95 | 9500 |
| TF220 | TO220M03 | SDTFT1 | 50 | 1000 |

Reason for Change:

Consolidate and standardize tube packing method. Improve efficiency at both assembly and warehouse operation by eliminating the need to repack.

Affected Product(s):

| | | |
|----------------|-----------|---------------|
| DFB2005 | DFB2010 | DFB20100 |
| DFB2020 | DFB2040 | DFB2060 |
| DFB2080 | DFB2505 | DFB2510 |
| DFB25100 | DFB2520 | DFB2540 |
| DFB2560 | DFB2580 | FAN7190M_F085 |
| FDPF15N65_F150 | FIN1027M | FIN1028M |
| GBU4A | GBU4B | GBU4D |
| GBU4G | GBU4J | GBU4K |
| GBU4M | GBU6A | GBU6B |
| GBU6D | GBU6G | GBU6J |
| GBU6K | GBU6M | GBU8A |
| GBU8B | GBU8D | GBU8G |
| GBU8J | GBU8K | GBU8M |
| KAT00124A | MBR1035 | MBR1045 |
| MBR1050 | MBR1060 | MBR1535CT |
| MBR1545CT | MBR1560CT | MBR1645 |
| MBR1660 | MBR2035CT | MBR2045CT |
| MBR2050CT | MBR2060CT | MBR2535CT |
| MBR2545CT | MBR2550CT | MBR2560CT |
| MBR4035PT | MBR4045PT | MBR4050PT |
| MBR4060PT | MBR735 | MBR745 |
| MBR750 | MBR760 | ML4800CP |
| ML4824CP1 | RA9100_32 | RV4141AN |
| RV4145AN | | |