

### 1 Products affected


Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.	
SBU PG PUG Type					
01 002 002 0000000501	See list below	Fuseholder complete	FPG2	n.a.	
*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)					

List of part numbers affected						
FPG2 complete						
3101.0020	3101.0120	3101.0025	3101.0125	3101.0220		
3101.0320 3101.0225 310		3101.0325				
FPG2 socket		<u>'</u>	·			
3101.2511.1	01.2511.1 3101.2513.1					
FPG2 carrier						
3101.7011	3101.7021	3101.7511	3101.7521			

# 2 Type of change

Change of markings

## 3 Detailed description of change



## 4 Reason of change

Newly approved nominal voltage according to IEC 60127-6

### 5 Release date

The change will be rolled-out starting ww 09/2017 (Date code 1709 or higher on label) and lasts approx. 6 months depending on the variant.

### 6 Impact of change and recommended action

Form	Yes	Modified marking on product		
Fit	No	No change for dimension		
Function	No	No change in function		
Manufacturing	NI.	No abanca for manufacturina a		

Manufacturing No No change for manufacturing site

Label No No change on label Packaging No No change in packaging

## 7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	

Product Change Notification			FPG2 change of the marks				
owner	creation date	release date	released by	change order no	rev	page	D40 040 045
zbindeja	2016-11-16	2017-01-30	nowakfr	2011481	Α	1 of 1	D10-010-915