




# PRODUCT CHANGE NOTIFICATION



## SINGL FUSE™ SMD FUSES



### Bourns® Model SF-xxxxxx, and SF-xxxxxxA-R SinglFuse™ SMD Fuses *Label Content Modification*

Riverside, California – October 17, 2023 – Effective immediately, Bourns will be removing the term “SINGLE FUSE” from the labels on the taping reels and packaging bags of the [Model SF-xxxxxx](#) and [SF-xxxxxxA-R](#) Series SinglFuse™ SMD Fuses. This adjustment will create consistent label content and a consistent label format across the SinglFuse™ SMD Fuse product line.

There have been no alterations to the actual SinglFuse™ SMD Fuse products within the Model [SF-xxxxxx](#) and [SF-xxxxxxA-R](#) Series. As a result, this change has no impact on the fit, form, function, quality, or reliability of these products. Bourns will initiate the label modification process starting from date code 2340 onwards and will progressively implement the change over the upcoming months. A list of affected part numbers is provided on the following page.

Affected Series	Original	New
<p>SF-xxxxxx SF-xxxxxxA-R</p>		

Users should verify that the described changes will not impact the performance of the product in their specific applications.

SF2313

Affected Part Numbers - SF-xxxxxx Series					
SF-0402F		SF-0402FP		SF-0402S	
SF-0402F0315-2	SF-0402F160-2	SF-0402FP050-2	SF-0402FP250-2	SF-0402S050-2	SF-0402S250-2
SF-0402F050-2	SF-0402F200-2	SF-0402FP080-2	SF-0402FP300-2	SF-0402S080-2	SF-0402S300-2
SF-0402F075-2	SF-0402F250-2	SF-0402FP100-2	SF-0402FP315-2	SF-0402S100-2	SF-0402S315-2
SF-0402F080-2	SF-0402F300-2	SF-0402FP125-2	SF-0402FP400-2	SF-0402S125-2	SF-0402S400-2
SF-0402F100-2	SF-0402F315-2	SF-0402FP150-2		SF-0402S150-2	
SF-0402F125-2	SF-0402F400-2	SF-0402FP160-2		SF-0402S160-2	
SF-0402F150-2		SF-0402FP200-2		SF-0402S200-2	
SF-0603F		SF-0603FP		SF-0603S	
SF-0603F040-2	SF-0603F200-2	SF-0603FP050-2	SF-0603FP250-2	SF-0603S040-2	SF-0603S160-2
SF-0603F050-2	SF-0603F250-2	SF-0603FP063-2	SF-0603FP300-2	SF-0603S050-2	SF-0603S200-2
SF-0603F063-2	SF-0603F300-2	SF-0603FP080-2	SF-0603FP315-2	SF-0603S063-2	SF-0603S250-2
SF-0603F080-2	SF-0603F315-2	SF-0603FP100-2	SF-0603FP400-2	SF-0603S070-2	SF-0603S300-2
SF-0603F100-2	SF-0603F400-2	SF-0603FP125-2	SF-0603FP500-2	SF-0603S080-2	SF-0603S315-2
SF-0603F125-2	SF-0603F500-2	SF-0603FP150-2		SF-0603S100-2	SF-0603S400-2
SF-0603F150-2		SF-0603FP160-2		SF-0603S125-2	SF-0603S500-2
SF-0603F160-2		SF-0603FP200-2		SF-0603S150-2	SF-0603S600-2
SF-0603SP		SF-1206F		SF-1206FP	
SF-0603SP050-2	SF-0603SP200-2	SF-1206F050-2	SF-1206F300-2	SF-1206FP050-2	SF-1206FP300-2
SF-0603SP063-2	SF-0603SP250-2	SF-1206F080-2	SF-1206F400-2	SF-1206FP080-2	SF-1206FP400-2
SF-0603SP080-2	SF-0603SP300-2	SF-1206F100-2	SF-1206F500-2	SF-1206FP100-2	SF-1206FP500-2
SF-0603SP100-2	SF-0603SP315-2	SF-1206F125-2	SF-1206F700-2	SF-1206FP125-2	SF-1206FP700-2
SF-0603SP125-2	SF-0603SP400-2	SF-1206F150-2		SF-1206FP150-2	
SF-0603SP150-2	SF-0603SP500-2	SF-1206F200-2		SF-1206FP200-2	
SF-0603SP160-2	SF-0603SP600-2	SF-1206F250-2		SF-1206FP250-2	
SF-1206S		SF-1206SP			
SF-1206S050-2	SF-1206S250-2	SF-1206SP050-2	SF-1206SP250-2		
SF-1206S080-2	SF-1206S300-2	SF-1206SP080-2	SF-1206SP300-2		
SF-1206S100-2	SF-1206S400-2	SF-1206SP100-2	SF-1206SP400-2		
SF-1206S125-2	SF-1206S500-2	SF-1206SP125-2	SF-1206SP500-2		
SF-1206S150-2	SF-1206S700-2	SF-1206SP150-2	SF-1206SP700-2		
SF-1206S200-2		SF-1206SP200-2			

Affected Part Numbers - SF-xxxxxxA-R Series	
SF-0603SPA-R	SF-1206SA-R
SF-0603SPA100R-2	SF-1206SA1000R-2
SF-0603SPA150R-2	SF-1206SA1200R-2
SF-0603SPA200R-2	SF-1206SA1500R-2
SF-0603SPA300R-2	SF-1206SA2000R-2
SF-0603SPA400R-2	
SF-0603SPA500R-2	
SF-0603SPA600R-2	
SF-0603SPA700R-2	
SF-0603SPA800R-2	

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).