



21-Sep-2022

PCN #: PCN-22-152831

Subject : RYII series relay - Cover material change

Description of Change : Dear customer, to ensure a consistently high quality and to ensure the delivery capability we intend to change the current plastic material of the Cover.

While both materials have the same characteristics, passed the same tests and are UL, VDE, CQC and HazLoc certified, the new material color appears slightly lighter. The Relay form (dimensions), features and ratings keep unchanged.

Reason :

Key Dates :

Contact By Date:01-Apr-2023

Implementation Date:01-Apr-2023

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
4-1393225-6	"RY900042"		
8-1393224-5	"RY532024"		
9-1393225-0			
1415399-1	"RY900109"		
1393224-9	"RYA31012"		
1-1393225-8	"RY611006"		
9-1393224-9	"RY551012"		
9-1415398-1	"RY900108"		
1415033-1	"RY6120124"		
1-1393225-9	"RY611012"		
4-1393225-3	"RY900017"		
5-1419136-2	"RY613005"		
1393225-5	"RY553012"		
8-1393225-7			
2-1416010-9	"RY212060"		

4-1393225-7	"RY900043"		
1956190-8			
4-1415400-2			
1415047-1	"RY900095"		
4-1393225-5	"RY900021"		
1-1956164-2			
5-1393224-4	"RY212009"		
5-1393224-9	"RY212048"		
4-1393224-5	"RY211009"		
5-1393224-5	"RY212012"		
7-1393224-9	"RY531012"		
6-1393225-7	"RY900069"		
7-1393224-6	"RY531005"		
1-1956164-4			
3-1393224-0	"RYA52012"		
6-1393225-1	"RY900063"		
1956190-4			
8-1393224-1	"RY531018"		
8-1393225-4			
1956180-1			
6-1393225-2	"RY900064"		
1956190-7			
5-1393224-8	"RY212024"		
2-1415033-1	"RY6120484"		
9-1393224-0	"RY533048"		
7-1956150-7			
1-1393224-4	"RYA32005"		
2-1956154-5			
3-1956170-6			
1-1416010-8	"RY231048"		
4-1393224-7	"RY211018"		
8-1393224-7	"RY533009"		
1-1393224-8	"RYA32024"		
8-1415032-1	"RY6120054"		
5-1393225-3	"RY900053"		
1-1415525-1	"RY900116"		

4-1393224-8	"RY211021"		
1393225-1	"RY551018"		
7-1393225-4	"RY900080"		
1-1393224-5	"RYA32009"		
8-1415507-1	"RY900113"		
1956190-2			
2-1393225-5	"RY612009"		
2-1416010-2	"RY900403"		
5-1393225-0	"RY900046"		
4-1393225-8	"RY900044"		
8-1415046-1	"RY900093"		
1956137-7			
8-1393224-4	"RY532012"		
1-1393224-3	"RYA31048"		
9-1415064-1	"RY900098"		
8-1393225-9			
2-1393225-4	"RY612006"		
5-1415530-1	"RY213032"		
3-1393225-4	"RY613048"		
1393224-7	"RYA31005"		
3-1393225-2	"RY613018"		
1-1956130-2			
9-1393225-9			
1-1393225-7	"RY611005"		
5-1393224-0	"RY211036"		
4-1393224-2	"RY211005"		
2-1393224-6	"RYA51005"		
4-1393224-9	"RY211024", "E75193- 000", "AMPS- 4-1393224-9"		
6-1393224-0	"RY213005"		
1393225-2	"RY551024"		
1393224-8	"RYA31006"		
8-1415022-1	"RY612060"		
3-1393225-0	"RY612048"		
5-1393225-1	"RY900048"		

2-1393225-9	"RY612024"		
8-1393224-6	"RY533006"		
1-1393224-9	"RYA33005"		
9-1393225-2			
9-1393225-6			
2-1416010-1	"RY900402"		
9-1393224-8	"RY551005"		
1393225-6	"RY553024"		
6-1393224-1	"RY213012"		
2-1393226-5			
8-1393224-2	"RY531024"		
7-1956150-9			
7-1393224-7	"RY531006"		
5-1393224-1	"RY211048"		
1956190-3			
5-1393224-2	"RY212005"		
8-1415044-1	"RY900096"		
6-1393225-9	"RY900071"		
1-1415029-1	"RY900091"		
8-1415509-1	"RY900115"		
4-1393224-4	"RY211008"		
4-1393225-4	"RY900018"		
1956190-5			
6-1393225-8	"RY900070"		
2-1393225-0	"RY611019"		
7-1956150-5			
8-1415500-1	"RY900112"		
8-1415064-1	"RY900097"		
2-1393224-0	"RYA33021"		
2-1393225-7	"RY612018"		
6-1393225-5	"RY900067"		
5-1393224-7	"RY212018"		
4-1393224-6	"RY211012"		
1956190-1			
9-1415032-1	"RY6120064"		
5-1393225-9	"RY900061"		

7-1393225-1	"RY900073"		
1-1393224-1	"RYA31019"		
6-1393225-4	"RY900066"		
9-1393225-8			
4-1415078-1	"RY631005-A"		
7-1393225-2	"RY900074"		
6-1393224-2	"RY213024"		
1-1393224-6	"RYA32012"		
9-1393225-4			
7-1393224-8	"RY531009"		
4-1393224-3	"RY211006"		
2-1393225-1	"RY611024"		
6-1393225-6	"RY900068"		
6-1393224-3	"RY213048"		
2-1393226-7			
2-1415355-1	"RY900102"		
6-1956150-8			
8-1393225-8			
7-1393225-0	"RY900072"		
4-1393225-2	"RY900016"		
1-1393224-0	"RYA31018"		
5-1393224-3	"RY212006"		
1-1416010-9	"RY900400"		
2-1416010-0	"RY900401"		
8-1393224-0	"RY531015"		
1-1415033-1	"RY6120244"		
3-1393226-2			
8-1393224-9	"RY533024"		
1393225-4	"RY553009"		
2-1393225-6	"RY612012", "1SNE008000 T1400"		
1956179-1			
5-1393224-6	"RY212015"		
2-1393224-8	"RYA51024"		
1-1393224-7	"RYA32021"		

3-1393225-5	"RY613060"		
7-1415500-1	"RY900111"		
9-1393225-7			
2-1393225-8	"RY612021"		
2-1393225-2	"RY611048"		
5-1419136-3	"RY632005"		
2-1393224-7	"RYA51012"		
6-1393225-3	"RY900065"		
1-1415399-1	"RY900110"		
2-1393224-2	"RYA33060"		
2-1393225-3	"RY612005"		
4-1415400-1	"RY631024"		
1-1393224-2	"RYA31024"		
1956145-7			
5-1393225-4	"RY900054"		
2-1393224-1	"RYA33024"		
2-1415004-1	"RY533036"		
8-1393224-3	"RY531048"		
8-1393225-6			
4-1393225-9	"RY900045"		
3-1393225-3	"RY613024"		
2-1393224-9	"RYA52009"		
3-1393225-1	"RY613012"		
8-1393224-8	"RY533012"		
5-1393225-2	"RY900049"		
1393225-3	"RY552012"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.