



Part no.: 426127
AC-MLC-HR-END
Host receiver termination



Figure can vary

Contents

- Technical data
- Electrical connection
- Notes

Technical data

Basic data

Application	Alignment and setup aid for MLC 520 Host versions
Suitable for	MLC 520 host receiver safety light curtains

Connection

Connection 1

Type of connection	Connector
Thread size	M12
Type	Male
No. of pins	8 -pin
Encoding	A-coded
Design	Axial

Certifications

Degree of protection	IP 67
----------------------	-------

Classification

Customs tariff number	85366990
eCl@ss 8.0	27069190
eCl@ss 9.0	27069190
ETIM 5.0	EC001578
ETIM 6.0	EC001578

Electrical connection

Connection 1	
Type of connection	Connector
Thread size	M12
Type	Male
No. of pins	8 -pin
Encoding	A-coded
Design	Axial

Notes

WARNING!

Risk of injury due to insufficient safety distance

- Integration of a Guest device results in an increase in reaction time. For this reason, a large safety distance must be allowed for.
- For further information, refer to calculation of the safety distance in the connecting and operating instructions.

Part no.: 426127 – AC-MLC-HR-END – Host receiver termination

WARNING!

Risk of injury due to missing stepping behind protection

- If the terminating plugs are used, take appropriate measures to ensure that it is not possible to step behind the safety light curtain.

WARNING!

Risk of injury due to unforeseeable machine behavior

- Changes made to the protective device can lead to unforeseeable machine behavior.
- After making changes, have the protective device checked by a qualified person.

NOTE

- Refer to the MLC 520 Host connecting and operating instructions.