INFORMATION NOTE



Introduction of several changes for LQ100 & TQ100-5 packages leading to a change in the visual appearance.

Subject of Change: Introduction of several changes for LQ100 & TQ100-5 packages leading to a change in the visual appearance.

- Products affected: Please refer to 1_cip15101 attached.
- **Reason of Change:** Harmonization of Infineon's QFP100 package platform.

Description of Change: Old New Package outline : Chamfer and radius corner 4 chamfer corner Top ejector pin: Without top ejector pin mark With & without top ejector pin mark ם 🗁 רביומת ההתהתההההההההההההההה ron with without Pin 1 indicator: Without inner ring design With inner ring design

infineon

INFORMATION NOTE

N° 101/15



Assessment:	No impact expected on the quality, reliability, function and manufacturability of the products affected due to this change.
TIME SCHEDULE:	
Final qualification report:	Not applicable
First samples available:	No samples planned
Intended start of delivery:	January 2016
Documentation:	1_cip15101: affected product list

If you have any questions, please do not hesitate to contact your local Sales office.