

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.	
SBU PG	PGU	Туре					
02 006	016	0000001515	See list below	Power Entry Module with Filter	CD		
02 006	016	0000001517	See list below	Power Entry Module with Filter	CD Bowdenzug		
*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)							


		List of part numbe	ers affected			
CD04.1101.151.01	CD21.4501.151	CD24.4199.151	CD41.1501.151	CD64.1101.151	CDD4.3101.151	CDL4.4133.151
CD11.1501.151	CD21.4599.151	CD31.1501.151	CD41.1599.151	CD64.4101.151	CDD4.4101.151	CDM4.1101.151
CD11.3501.151	CD23.4101.151	CD31.3501.151	CD41.4501.151	CDA1.4501.151	CDE4.1101.151	CDM4.4101.151
CD11.4501.151	CD23.4101.198	CD31.4501.151	CD41.4599.151	CDA4.1101.151	CDE4.1101.151.01	4320.0001
CD11.4599.151	CD24.1101.151	CD31.4599.151	CD43.1101.151	CDA4.3101.151	CDE4.4101.151	4320.0002
CD14.1101.151	CD24.1101.151X1	CD34.1101.151	CD44.1101.151	CDA4.4101.151	CDE4.4133.151	4320.0003
CD14.1101.151X1	CD24.1132.151	CD34.1101.151.01	CD44.1101.151.01	CDA4.4199.151	CDE4.4199.151	4320.0004
CD14.1132.151	CD24.1133.151	CD34.1101.A	CD44.1105.151	CDB4.3101.151	CDG4.4101.151	4320.0008
CD14.1133.151	CD24.3101.151	CD34.1133.151	CD44.1132.151	CDB4.4101.151	CDG4.4132.151	4320.0024
CD14.3101.151	CD24.4101.151	CD34.1199.151	CD44.3101.151	CDC4.1101.151	CDG4.4133.151	4320.0027
CD14.4101.151	CD24.4101.151.01	CD34.4101.151	CD44.4101.151	CDC4.4101.151	CDG4.4199.151	
CD14.4198.151	CD24.4101.151X1	CD34.4101.151.01	CD44.4198.151	CDC4.4101.151.01	CDH4.1101.151	
CD14.4199.151	CD24.4133.151	CD34.4132.151	CD44.4199.151	CDC4.4132.151	CDL1.4501.151	
CD21.1501.151	CD24.4198.151	CD34.4133.151	CD61.1501.151	CDC4.4133.151	CDL4.1101.151	
CD21.3501.151	CD24.4198.151.01	CD34.4199.151	CD61.4501.151	CDC4.4199.151	CDL4.4101.151	

2 Type of change

V-Lock cord retaining feature as standard.

3 Detailed description of change

V-Lock feature integrated as standard (not an option anymore)



	0118.2258					
creation date	created by	release date	released by	notification no.	revision	page
2015-01-14	hollenpe	2015-06-08	hollenpe	26910	_	1 of 2



As the V-Lock is now a standard feature, the material numbers with index .21 are obsolete and will be replaced by the standard number:

CD61.1501.151.21	\rightarrow	CD61.1501.151
CD64.1101.151.21	\rightarrow	CD64.1101.151
CDC4.4101.151.21	\rightarrow	CDC4.4101.151
CDE4.4101.151.21	\rightarrow	CDE4.4101.151
CDM4.4101.151.21	\rightarrow	CDM4.4101.151

4 Reason of change

V-Lock cord retaining implemented as a standard feature.

5 Release date

The change will be rolled-out starting ww 25/2015 and lasts approx. 8 months depending on the variant.

6 Impact of change and recommended action

Form:	Yes	C14 inlet with V-Lock notch as standard
Fit:	No	There are no dimensional changes
Function:	Yes	V-Lock feature is standard (not an option anymore)
Production Site:	No	There are no change of the production site
Product Label:	No	No change of the product label

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Data Sheet CD		
Data Sheet CD Bowdencable		

	0118.2258					
creation date	created by	release date	released by	notification no.	revision	page
2015-01-14	hollenpe	2015-06-08	hollenpe	26910	-	2 of 2