



Expertise Applied | Answers Delivered

8755 W. Higgins Road  
Suite 500  
Chicago, IL 60631

[www.littelfuse.com](http://www.littelfuse.com)

---

Subject: Plating of Class T: JLLN & JLLS Series Fuses

Document# LFPCN\_PG0041 - **REV 1**

Date: 1/13/2014

This letter is to inform Littelfuse Sales, Sales Support & Customers of a process change in the manufacturing of the end caps for our JLLN & JLLS series fuses. Going forward the fuse end caps (and blades where applicable) will no longer be plated on standard fuses. They will remain in their natural state. This will be a running change that will start in production during April 2014. Please see the table on page two for the SKUs that will be affected.

There is no change to product numbers and no updates are required for ordering systems. There is no performance impact as a result of the change and the fuses will continue to be UL Listed. This change will significantly reduce overall product lead times to help ensure product availability for our customers and will prevent appearance issues that can be encountered with silver plating over time.

Littelfuse recognizes there are some customers who view plating as a highly desirable trait. In order to satisfy these customers' expectations, Littelfuse will be implementing a new line of premium plated fuses. These plated fuses will have a "XP" suffix added to the part number for ordering purposes. Other than plating there will be no difference in the two versions of the product. Please see the chart on page two for a complete list of new part numbers. Customers may begin to order the plated version of the product in April 2014.



Expertise Applied | Answers Delivered

8755 W. Higgins Road  
Suite 500  
Chicago, IL 60631

[www.littelfuse.com](http://www.littelfuse.com)

### Affected SKUs (Future Non-plated)

JLLN001.T	JLLN110.X	JLLS003.T	JLLS1200X
JLLN002.T	JLLN1100X	JLLS006.T	JLLS125.X
JLLN003.T	JLLN1200X	JLLS010.T	JLLS150.X
JLLN006.T	JLLN125.X	JLLS015.T	JLLS175.X
JLLN010.T	JLLN150.X	JLLS020.T	JLLS175.Z
JLLN015.T	JLLN175.X	JLLS025.T	JLLS200.X
JLLN020.T	JLLN200.X	JLLS030.T	JLLS225.X
JLLN025.T	JLLN225.X	JLLS035.T	JLLS250.X
JLLN030.T	JLLN250.X	JLLS040.T	JLLS300.X
JLLN035.T	JLLN300.X	JLLS045.T	JLLS350.X
JLLN040.T	JLLN350.X	JLLS050.T	JLLS400.X
JLLN045.T	JLLN400.X	JLLS060.T	JLLS450.X
JLLN050.T	JLLN450.X	JLLS070.V	JLLS500.X
JLLN060.T	JLLN500.X	JLLS080.V	JLLS600.X
JLLN070.V	JLLN600.X	JLLS090.V	JLLS700.X
JLLN080.V	JLLN700.X	JLLS100.V	JLLS800.X
JLLN090.V	JLLN800.X	JLLS1000X	JLLS900.X
JLLN100.V	JLLS001.T	JLLS110.X	
JLLN1000X	JLLS002.T	JLLS1100X	

### New SKUs (Plated)

JLLN001.TXP	JLLN110.XXP	JLLS003.TXP	JLLS1200XXP
JLLN002.TXP	JLLN1100XXP	JLLS006.TXP	JLLS125.XXP
JLLN003.TXP	JLLN1200XXP	JLLS010.TXP	JLLS150.XXP
JLLN006.TXP	JLLN125.XXP	JLLS015.TXP	JLLS175.XXP
JLLN010.TXP	JLLN150.XXP	JLLS020.TXP	JLLS175.ZXP
JLLN015.TXP	JLLN175.XXP	JLLS025.TXP	JLLS200.XXP
JLLN020.TXP	JLLN200.XXP	JLLS030.TXP	JLLS225.XXP
JLLN025.TXP	JLLN225.XXP	JLLS035.TXP	JLLS250.XXP
JLLN030.TXP	JLLN250.XXP	JLLS040.TXP	JLLS300.XXP
JLLN035.TXP	JLLN300.XXP	JLLS045.TXP	JLLS350.XXP
JLLN040.TXP	JLLN350.XXP	JLLS050.TXP	JLLS400.XXP
JLLN045.TXP	JLLN400.XXP	JLLS060.TXP	JLLS450.XXP
JLLN050.TXP	JLLN450.XXP	JLLS070.VXP	JLLS500.XXP
JLLN060.TXP	JLLN500.XXP	JLLS080.VXP	JLLS600.XXP
JLLN070.VXP	JLLN600.XXP	JLLS090.VXP	JLLS700.XXP
JLLN080.VXP	JLLN700.XXP	JLLS100.VXP	JLLS800.XXP
JLLN090.VXP	JLLN800.XXP	JLLS1000XXP	JLLS900.XXP
JLLN100.VXP	JLLS001.TXP	JLLS110.XXP	
JLLN1000XXP	JLLS002.TXP	JLLS1100XXP	

Thank you for your continued business.

Sincerely,



Expertise Applied | Answers Delivered

**Jim McGuire**  
Assistant Product Manager, North America  
8755 West Higgins Road /Suite 500  
Chicago, IL, 60631

[jmcguire@littelfuse.com](mailto:jmcguire@littelfuse.com) Phone: 773-628-0708

[www.littelfuse.com](http://www.littelfuse.com)