

## **PRODUCT CHANGE NOTICE**

<b>PCN NUMBER</b>	: 310
<b>Product Category</b>	: Soldering Tip
<b>Issue Date</b>	: 09 - May - 2023
<b>Effective Date</b>	: 09 - May - 2023
<b>REASON FOR CHANGE</b>	: The soldering iron protection ring has been shorted by 8mm, the stainless-steel tube has been shortened 15mm, and the whole unit has been shorted by 23mm in total. These alterations have no impact on quality or usage, and the items remain fully compatible with the respective soldering irons and stations.
<b>FORM FIT AND FUNCTION</b>	: Difference in dimension and the function remains the same.
<b>Part Effected</b>	: Below are the list of part(s) are affected.

FARNELL SKU	NEWARK SKU	Part Number
3265152	52AH6285	MP740238
3265153	52AH6286	MP740239
3265154	52AH6287	MP740240
3265155	52AH6288	MP740241
3265156	52AH6289	MP740242
3265157	52AH6290	MP740243
3265159	52AH6291	MP740244
3265161	52AH6292	MP740245

**Important Notice** : This PCN and its contents (the "Information") belong to the members of the AVNET group of companies (the "Group") or are licensed to it. No license is granted for the use of it other than for information purposes in connection with the products to which it relates. No license of any intellectual property rights is granted. The Information is subject to change without notice and replaces all data sheets previously supplied. The Information supplied is believed to be accurate but the Group assumes no responsibility for its accuracy or completeness, any error in or omission from it or for any use made of it. Users of this data sheet should check for themselves the Information and the suitability of the products for their purpose and not make any assumptions based on information included or omitted. Liability for loss or damage resulting from any reliance on the Information or use of it (including liability resulting from negligence or where the Group was aware of the possibility of such loss or damage arising) is excluded. This will not operate to limit or restrict the Group's liability for death or personal injury resulting from its negligence. Multicomp Pro is the registered trademark of Premier Farnell Limited 2019.