



02-Aug-2022

**PCN #:** PCN-22-144095

**Subject :** 2.5mm SIGNAL DBL-LOCK CAP AND PLUG HSG

**Description of Change :** As a valuable TE customer, please be aware of an alternative material is added on the listed part numbers to avoid global material shortage and interruptions in supply and ensuring lead time and delivery timely. New added material has been fully qualified which follows a strict procedure, which guarantees quality, ability to supply, and no changes to product performance. Product color could have slight difference between current and new added material, there is no impact on product performance.

**Reason :**

**Key Dates :**

**Contact By Date:**21-Nov-2022

**Implementation Date:**21-Nov-2022

<b>Product Affected</b>	<b>Alias Part Number</b>	<b>Substitute Part Number</b>	<b>AliasSub Part Number</b>
917694-1			
316091-1			
917690-1			
917692-1			
2333402-1			
316087-1			
917693-1			
316094-1			
1-353557-1			
917697-1			
316086-1			
353440-4			
917688-1			
917689-1			

1746063-1			
316088-1			
316089-1			
917696-1			
316092-1			
917695-1			
917691-1	"0-0917691-1"		
353440-6			
917687-1			
917686-1			
316090-1			

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.