




Product Change Notification


Date Issued :	October 25, 2022	PCN Number :	512647
Reason for Change :	Change to Product		
Description of Change :	The outer sleeve of the UltraLock head did not rotate freely. to ensure free rotation, the rear step of the inner sleeve was adjusted accordingly. The diameter was reduced and the step made longer.		
Reason for Short Notice :	Corrective Actions		
Assessment of Change :	First Article Inspection		
Planned Implementation Date :	November 25, 2022		
Sample Availability Date:	September 30, 2022		
Internal Molex Qualification Date :	September 30, 2022		
Last date to request Samples by Customer :	October 14, 2022		
Traceability Code Markings / Date :	No special marking on the product or packaging		

Before Picture

old



new



After Picture

Overview

- The outer sleeve of the UltraLock head did not rotate freely. To ensure free rotation, the rear shoulder of the inner sleeve was adjusted accordingly. The diameter was reduced and the step made longer.

- Product Impact
 - No impact for function

- Part Number Impact
 - 1203070246

RELEASED

You may address inquiries regarding this PCN by clicking on the below link
mailto:pcn_coordinator@molex.com?subject=PCN_Notification:512647
or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 512647** " in the e-mail Subject line for faster response.

[Molex, LLC](#)
2222 Wellington Court
Lisle, IL 60532
TEL (800) 786-6539
www.molex.com