



17-Oct-2023

**PCN #:** PCN-23-189274

**Subject :** RPII relays (1 & 2 pole) - product marking process change

**Description of Change :** Dear customer, please be aware of an upcoming cosmetic change to the listed part numbers (not affecting the function of the product). As part of our continuous improvement of manufacturing processes regarding our environmental impact and sustainability, we will change our process of product marking from white-color pad printing to a more state-of-the-art laser marking process, much like TE is already doing on other clear-cover relays such as SR4, SR6 or RT. The content and arrangement of the information on the relay cover will not change.

**Reason :** Laser marking is a consistent and reliable state-of-the-art process, which generates no waste during marking changes and works without additional substances such as colors or cleaning chemicals, making it an overall more sustainable way of marking our product.

**Key Dates :**

**Contact By Date:**18-Dec-2023

**Implementation Date:**18-Dec-2023

<b>Product Affected</b>	<b>Alias Part Number</b>	<b>Substitute Part Number</b>	<b>AliasSub Part Number</b>
8-1415071-1	RP31L024		
7-1415546-4	RP444012		
7-1393234-3	RP421F12		
1393845-5	RP821024		
1-1393845-0	RP821F12		
8-1393235-9	RP920109		
9-1393230-7	RP411060		
7-1393235-7	RP920086		
6-1393234-8	RP421024, D55829-000, AMPS-6-1393234- 8		
7-1415546-5	RP444024		
2-1393235-5	RP421080		

9-1393230-6	RP411048		
9-1415546-4	RP334048		
8-1415546-2	RP314F24		
8-1415546-8	RP314024		
1393845-6	RP821048		
3-1393235-9	RP82A012		
9-1393230-4	RP411012		
6-1415546-3	RP424006		
6-1415546-4	RP424012		
8-1393234-0	RP441024		
1-1393231-1	RP412012		
6-1415546-7	RP424060		
7-1415546-0	RP424A24		
1415547-1	RP714024		
1393230-1	RP3SLA05		
1-1393230-1	RP3SL024		
1393230-9	RP3SL012, CA6513-000, AMPS-0-1393230- 9		
1393232-9	RP812024		
8-1415546-5	RP314006		
7-1393235-2	RP920079		
1415547-7	RP734020		
3-1415547-0	RP8CS024		
1393233-5	RP910228		
1415540-6	RP910265		
2-1393235-3	RP421W19		
1-1393235-9	RP421A12		
3-1415547-9	RP920147		
7-1415543-3	RP910266		
1-1393233-8	RP910246		
6-1415546-1	RP844024		
1415547-4	RP414012		
1393235-2	RP42A024		
3-1393235-3	RP441012		
1393230-5	RP3SLF12		

6-1393231-6	RP7SL024		
7-1393234-7	RP42A012		
7-1415546-2	RP424F12		
9-1415546-1	RP334012		
1-1393230-2	RP3SL048		
7-1415546-7	RP824012		
8-1393231-8	RP81A024		
8-1415546-4	RP314005		
8-1415546-7	RP314012		
8-1415546-9	RP314048		
8-1415546-1	RP314F12		
1-1415547-2	RP814048		
1415540-7	RP910267		
7-1415527-1	RP910262		
1-1415538-4	RP920145		
1-1393233-2	RP910238		
9-1393235-2	RP920124		
6-1393230-5	RP41A110		
8-1415546-3	RP314W20		
9-1415546-2	RP334024		
7-1415546-8	RP824024		
7-1415546-6	RP824006		
9-1393231-8	RP811012		
9-1415546-6	RP414A24		
1393231-6	RP412F12		
4-1393231-5	RP431012		
9-1415546-9	RP714012		
1415547-8	RP734024		
1393230-7	RP3SL005		
7-1415546-9	RP824048		
8-1415546-0	RP824060		
1393845-4	RP821012		
1393230-2	RP3SLA06		
6-1393230-7	RP41B009		
9-1393230-5	RP411024		
1-1393231-2	RP412024		

6-1415546-5	RP424024		
6-1393230-3	RP41A024		
6-1415546-9	RP424A12		
1415547-9	RP734036		
6-1415546-6	RP424048		
6-1415546-8	RP424110		
6-1393231-5	RP7SL012		
9-1415546-8	RP714006		
1415547-6	RP734012		
7-1415546-3	RP424F24		
2-1415044-1	RP31L048		
1393230-8	RP3SL006		
1393232-8	RP812012		
9-1415546-5	RP354012		
1415547-3	RP734A12		
5-1393235-3	RP841024		
3-1393235-5	RP441090		
1415547-5	RP414024		
1-1393845-1	RP821F246		
6-1393234-9	RP421048		
9-1393231-9	RP811024		
1-1415547-0	RP814012		
1-1415547-1	RP814024		
1393230-6	RP3SLF24		
6-1415546-2	RP424005		
7-1393234-1	RP421110		
1393235-3	RP42A048		
7-1415547-0	RP43N024		
1393230-3	RP3SLA12		
2-1393233-1	RP910249		
4-1393235-7	RP821F606		
8-1415546-6	RP314010		
9-1393230-1	RP411F24		
1393235-6	RP42A110		
1-1393233-3	RP910240		
7-1415547-1	RP45N024		

7-1393234-4	RP421F24		
3-1415510-1	RP910261		
3-1393235-8	RP82AF48		
1-1393231-0	RP412010		
1393230-4	RP3SLA24		
6-1393234-5	RP421006		
1415547-2	RP714048		
7-1415546-1	RP424A48		
1-1393230-0	RP3SL018		
1393845-3	RP821006		
9-1415546-0	RP314110		
2-1393233-3	RP910251		
8-1393232-5	RP910193		
8-1393231-9	RP81B024		
1-1393845-4	RP82A024		
6-1393234-4	RP421005		
9-1415546-7	RP414F24		
9-1415546-3	RP434024		
7-1415071-1	RP31L012		
8-1415535-5	RP910263		
1-1393230-3	RP3SL060		
9-1393235-1	RP920123		
1-1393233-5	RP910242		
7-1393235-5	RP920083		
6-1393234-7	RP421012		
1393232-4	RP812F05		
9-1393230-8	RP411110		
1-1415547-7	RP41N024		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.