

**1 Products affected**

Product hierarchy no. *				Part no.	SBU	Type / Description
SBU	PG	PUG	Type			
03	009	010	0000003000	See list attached	Switches	MTG/MTP
03	009	011	0000003100	See list attached	Switches	LDT/LDS
03	009	010	0000003008	See list attached	Switches	LSG/LSH/LPH/LPS/LPV
03	009	010	0000003006	See list attached	Switches	MCS18 Printmount
03	009	011	0000003102	See list attached	Switches	MCS18 Frontpanel
03	009	010	0000003005	See list attached	Switches	SDK
03	009	010	0000003001	See list attached	Switches	SMS/PMS

\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

**2 Type of change**



- Modified label
- Improved identification product configuration code on the label

**3 Detailed description of change**


All product types listed in section 1 receive a new label layout.

To better visualize the changes, we have used colors and numbers to cluster information into the following sections (The colors and white numbers are not part of the new label layout):

<b>Product identification section:</b> To improve readability, we clustered all the information concerning product identification in this group. To increase clarity, we introduce our product configuration code into this area.	1
<b>Product conformity section:</b> Identical information was slightly rearranged.	2
<b>Product logistics section:</b> Label names changed. Information was slightly rearranged.	3
<b>Product approval section:</b> Identical information was slightly rearranged.	4
<b>Interruption ratings section:</b> Identical information was slightly rearranged.	5
<b>Origin information section:</b> Label for Factory Code was added. Information was slightly rearranged.	6

Old label	New label
 <p>The old label layout includes: P/N 1241.1100.7037 (1), SCHURTER AG CH-6002 Luzern (2), QTY 100 (3), Lot 3216547 (3), Date 2137 (3), MCS18 (1), ST (5), CoO CZ (6), and a barcode (4).</p>	 <p>The new label layout includes: P/N 1241.1100.7037 (1), Type MCS 18/MCS 18 Soft Touch (2), Product Type (2), MCS 18 FP. QD. SW. +  Part Description (1), Configuration Code (1), Qty 100 (3), Lot 3216547 (3), Date Code 2137 (3), FC ST (6), CoO CZ (6), and a barcode (4).</p>

Product Change Notification					PG09 Global Labeling Change		
owner	creation date	release date	released by	change order no	rev	page	D10-058-536
helblijo	22.09.2021	23.09.2021	barthro	2022706	B	1 of 2	



#### 4 Reason of change

SCHURTER improves and modernizes the label printing process to increase standardization and harmonize processes throughout all SCHURTER factory locations.

#### 5 Release date

Packaging labels will be changed earliest in week 42/2021 (Date code 2142 or higher on the label).

#### 6 Impact of change and recommended action

Form	No	
Fit	No	
Function	No	
Manufacturing	No	
Label	Yes	No actions required since barcode & 2D-code are not affected by the change.
Packaging	No	

#### 7 Reference Documents / Attachments

Kind of document	Remarks
List of affected articles	List contains a comparison of text / content between old and new labels in reference to chapter 3. "Product identification section"

Product Change Notification					PG09 Global Labeling Change		
owner	creation date	release date	released by	change order no	rev	page	D10-058-536
helblij	22.09.2021	23.09.2021	barthro	2022706	B	2 of 2	