

Product Bulletin

Document # : PB22658X Issue Date: 20 March 2019

Title of Change:	Product Bulletin of Adding UL Logo on Part Marking for Bridge Rectifiers in GBU Package.	
Effective date:	20 March 2019	
Contact information:	Contact your local ON Semiconductor Sales Office or < Benjo.Rulona@onsemi.com >	
Type of notification:	This Product Bulletin is for notification purposes only. ON Semiconductor will proceed with implementation of this change upon publication of this Product Bulletin.	
Change Category:	Wafer Fab Assembly Change	☐ Test Change
Change Sub-Category(s): Manufacturing Site Addition Manufacturing Site Transfer Manufacturing Process Change	☐ Material Change ☐ Product specific change	☐ Datasheet/Product Doc change ✓ Shipping/Packaging/Marking ☐ Other:
Sites Affected:	ON Semiconductor Sites: None	External Foundry/Subcon Sites: China Subcon
Description and Purpose:		

Change From: No UL Logo on Marking

Change To: With UL Logo on Marking

Change From:







Affected Devices Are Bridge Rectifiers in GBU Package Only.

Devices are UL Certified with Certificate # E258596 as indicated in the datasheets. The marking change provides proper identification through top mark that parts are UL certified. This change also aligns ON Semiconductor with the current industry standard for UL marking on GBU Bridge Rectifiers.

TEM001796 Rev. B Page 1 of 2



Product Bulletin

Document # : PB22658X Issue Date: 20 March 2019

List of Affected Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

GBU4A	GBU6J
GBU4B	GBU6K
GBU4D	GBU6M
GBU4G	GBU8A
GBU4J	GBU8B
GBU4K	GBU8D
GBU4M	GBU8G
GBU6A	GBU8J
GBU6B	GBU8K
GBU6D	GBU8KS
GBU6G	GBU8M

TEM001796 Rev. B Page 2 of 2