

PRODUCT CHANGE NOTIFICATION

Ref Nr: PCN-20220105002

Date: Jan. 5th , 2022

TO: ALL CUSTOMERS (with appendix)**FROM:** SBU Global Field Marketing**HEREWITH YOU ARE INFORMED OF OUR INTENTION TO CHANGE YAGEO BRANDING TO PULSE****DESCRIPTION:**

YAGEO Corp. hereby announce that Inductor Branding will change from YAGEO to PULSE.

- 3 months phase in is defined. The PCN effective date is 2022/01/05 and all affected part numbers will be remained. No change.
- In the interim, customers can place order either via YAGEO or PULSE channel.
- From 2022/04/01, all the inductor order will be taken by PULSE channel only.
- There is no change to the manufacturing location, processes, materials, equipment and personnel (anything that could affect fit, form and function of the product).

For detail, please contact local YAGEO/PULSE Sales representative.

REASONS:

Global branding name of Inductor is utilized with the intention of managing product lines more consistent.

EXPECTED INFLUENCE ON PERFORMANCE: No change**EXPECTED INFLUENCE ON QUALITY AND RELIABILITY:** No change**FOR MORE INFORMATION, CONTACT:** Algo.lin@yageo.com**RETURN YOUR COMMENTS BEFORE:** Feb. 15 ,2022**Remarks:** If you have no comment before Feb 15, 2022, we will trust as you can accept this brand change.**Comments:****Date:****Function:****Signature:**

Appendix: The YAGEO/PULSE inductor series list (see page 2)

YAGEO = PULSE			
Inductor Series	Inductor Series	Inductor Series	Inductor Series
ABPY001608xxxxxxxxxx	BMRA000606xxxxxxxxxx	NLC3225xxxxxxxxxxxxx	SL1012xxxxxxxxxxxxx
AWCU002012xxxxxxxxxx	BMRF001010xxxxxxxxxx	NLC4532xxxxxxxxxxxxx	SL1016Txxxxxxxxxxxxx
AWCU004532xxxxxxxxxx	BPSD000807xxxxxxxxxx	NLC5650xxxxxxxxxxxxx	SLF1045xxxxxxxxxxxxx
AWVS005050xxxxxxxxxx	BSCH000603xxxxxxxxxx	PBJ2012xxxxxxxxxxxxx	SLF1275xxxxxxxxxxxxx
AWVS006060xxxxxxxxxx	BSCH001005xxxxxxxxxx	PBY1005xxxxxxxxxxxxx	SQC4532xxxxxxxxxxxxx
AWVT003030xxxxxxxxxx	BSCH001608xxxxxxxxxx	PBY1608xxxxxxxxxxxxx	SQC5750xxxxxxxxxxxxx
BBBK001608xxxxxxxxxx	BSCQ000603xxxxxxxxxx	PBY2012xxxxxxxxxxxxx	SQV4532xxxxxxxxxxxxx
BBBK002012xxxxxxxxxx	BWCS001610xxxxxxxxxx	PBY3216xxxxxxxxxxxxx	SSL0402xxxxxxxxxxxxx
BBGK001608xxxxxxxxxx	BWCS002317xxxxxxxxxx	RH03506xxxxxxxxxxxxx	SSL0503xxxxxxxxxxxxx
BBGK002012xxxxxxxxxx	BWVF002520xxxxxxxxxx	SBK1608xxxxxxxxxxxxx	SSL0802xxxxxxxxxxxxx
BBHV001608xxxxxxxxxx	BWVF003030xxxxxxxxxx	SBK2012xxxxxxxxxxxxx	SSL0804xxxxxxxxxxxxx
BBNQ001608xxxxxxxxxx	BWVS004040xxxxxxxxxx	SBK3216xxxxxxxxxxxxx	SSL0810xxxxxxxxxxxxx
BBPY001005xxxxxxxxxx	BWVS005050xxxxxxxxxx	SBY1005xxxxxxxxxxxxx	TC3220xxxxxxxxxxxxx
BBPY001608xxxxxxxxxx	BWVS006060xxxxxxxxxx	SBY2012xxxxxxxxxxxxx	UPB2012xxxxxxxxxxxxx
BBPY002012xxxxxxxxxx	BWVS008080xxxxxxxxxx	SCD0302xxxxxxxxxxxxx	UPB3216xxxxxxxxxxxxx
BBPY003216xxxxxxxxxx	CL1608xxxxxxxxxxxxx	SCD0403xxxxxxxxxxxxx	
BBSY001005xxxxxxxxxx	CL2012xxxxxxxxxxxxx	SCD0503xxxxxxxxxxxxx	
BBUP001608xxxxxxxxxx	CLH0603xxxxxxxxxxxxx	SCD0504xxxxxxxxxxxxx	
BBUP002012xxxxxxxxxx	CLH1608xxxxxxxxxxxxx	SCD0705xxxxxxxxxxxxx	
BBUP003216xxxxxxxxxx	GBK1608xxxxxxxxxxxxx	SCD1005xxxxxxxxxxxxx	
BDGD002016xxxxxxxxxx	GBK2012xxxxxxxxxxxxx	SCDS125xxxxxxxxxxxxx	
BDHE002016xxxxxxxxxx	HFJ1005xxxxxxxxxxxxx	SCDS127xxxxxxxxxxxxx	
BDHE002520xxxxxxxxxx	LVF3030xxxxxxxxxxxxx	SCDS74Txxxxxxxxxxxxx	
BKP002012xxxxxxxxxx	MHCC06xxxxxxxxxxxxx	SDS0402xxxxxxxxxxxxx	
BMQA000606xxxxxxxxxx	NL2520xxxxxxxxxxxxx	SdT0804xxxxxxxxxxxxx	
BMRA000404xxxxxxxxxx	NL3225xxxxxxxxxxxxx	SL0608Txxxxxxxxxxxxx	
BMRA000505xxxxxxxxxx	NL4532xxxxxxxxxxxxx	SL0810Txxxxxxxxxxxxx	