

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

Change of Production Strategy for Gen5 HVIC wafer manufacturing site from formerly Newport Wafer Fab to NXP Semiconductors USA, Inc., back to solely Newport Wafer Fab

Infineon Technologies AG
Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0
Chairman of the Supervisory Board: Dr. Wolfgang Eder
Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Dr. Sven Schneider
Registered Office: Neubiberg
Commercial Register: München HRB 126492

TITLE

► Products affected:

Please refer to attached affected product list:

1_cip_AffectedProducts_INFORMATION_NOTE 031_20.xlsx 

► Detailed Change Information:

Subject: Change of production strategy back to Newport Wafer Fab Ltd. as sole vendor for HVIC Gen5 wafers

Reason: Discontinuation Letter from NXP Semiconductors USA, Inc. for the affected products

Description:

Old

New

- Newport Wafer Fab Ltd. as Infineon owned site
- Former Production strategy to move from Newport Wafer Fab Ltd. to NXP Semiconductors USA, Inc. Reference PCN : 1155 - 1161 from 2017

- Newport Wafer Fab Ltd. as a Neptune 6 Ltd. Company, used by Infineon as Silicon Foundry
- Keep Newport Wafer Fab Ltd. as sole production site

► Product Identification:

Wafer fab origin will not be distinguished through the external part marking or shipping labels, however, based on the assembly lot code and marked on the device. IFX internal systems will be able to trace the site of the wafer lots used to produce the final product.

N° 031/20

► **Impact of Change:**

No changes to form, fit or function. Datasheet specifications will not be changed. No physical change on released wafers.

Deliveries of products either with NXP or Newport chips possible until NXP stocks are depleted.

► **Attachments:**

Affected product list: 1_cip_AffectedProducts_INFORMATION_NOTE 031_20.xlsx

► **Intended start of delivery:**

01-05-2020

If you have any questions, please do not hesitate to contact your local Sales office.