



30-Apr-2020

PCN #:E-20-006265

**Subject:**PE & RE/L relay series

**Description of Change:** Correction of the product environmental compliance coding in the corresponding statement of compliance (SoC) regarding REACH SVHC BPA and establishment of a relationship to a BPA RSCD on [TE.com](http://TE.com).

**Reason:** Document Clarification. Document clarification. Dear customer! In our PE & RE/L relay series, we use an adhesive, which contains SVHC BPA above REACH threshold of 0.1%. Our Statement of Compliance for the relays did not consider this fact, as it is based on a material declaration from our supplier, which turned out to be wrong. After detecting this error, since March 2020 we corrected the product compliance declaration accordingly and these are linked to the affected products on our homepages. We are working to find potential alternative adhesives, which might enable us to declare containing REACH SVHC below threshold again, but for the time being, the SoC similar to the enclosed is valid for the PE & RE/L relay series. Apologies for any inconveniences caused.

**Key Dates:**

**Contact By Date:**01-May-2020

**Implementation Date:**01-May-2020

**Product Affected**

1-1416010-1

(Alias Part Numbers:  
"REL90010")

3-1415390-1

(Alias Part Numbers:  
"PE014F12")

8-1415060-1

## **Product Affected**

(Alias Part Numbers:  
"PE900001")

1393219-6

(Alias Part Numbers:  
"PE014012")

2-1393217-2

(Alias Part Numbers:  
"RE032012")

2-1416010-3

(Alias Part Numbers:  
"RE034005")

2-1393217-4

(Alias Part Numbers:  
"RE032024")

2-1393219-0

(Alias Part Numbers:  
"PE514012")

5-1415390-1

(Alias Part Numbers:  
"PE014F24")

1393219-2

(Alias Part Numbers:  
"PEL90001")

1-1416010-0

(Alias Part Numbers:  
"REL90009")

1-1393217-6

(Alias Part Numbers:  
"RE031018")

1-1393219-0

(Alias Part Numbers:  
"PE014024")

2-1419142-2

(Alias Part Numbers:  
"PE014003")

9-1415389-1

(Alias Part Numbers:  
"PE014F02")

3-1415540-8

(Alias Part Numbers:

## **Product Affected**

"PE514F12")

1393219-4

(Alias Part Numbers:

"PE014006")

1415390-1

(Alias Part Numbers:

"PE014F03")

1-1393219-3

(Alias Part Numbers:

"PE014048")

2-1393219-2

(Alias Part Numbers:

"PE514024")

1-1393219-4

(Alias Part Numbers:

"PE015012")

1393219-3

(Alias Part Numbers:

"PE014005")

1-1393217-5

(Alias Part Numbers:

"RE031012")

1-1416010-7

(Alias Part Numbers:

"REL90011")

8-1415063-1

(Alias Part Numbers:

"PE014A12")

1-1415390-1

(Alias Part Numbers:

"PE014F05")

1393219-5

(Alias Part Numbers:

"PE014009")

2-1416010-7

(Alias Part Numbers:

"RE034024")

2-1415402-1

(Alias Part Numbers:

"RE031005")

**Product Affected**

2-1416010-6

(Alias Part Numbers:

"RE034012")

1-1393217-8

(Alias Part Numbers:

"RE031024")

1415544-4

1-1393219-7

(Alias Part Numbers:

"PE514005")

7-1415063-1

(Alias Part Numbers:

"PE014A05")

1-1393217-9

(Alias Part Numbers:

"RE032005")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.