

Product Change Notice

PCN#: EE-PCN23019

7/25/2023

CLASSIFICATION OF CHANGE:

VDE certification change

DESCRIPTION OF CHANGE:

Fuse holder H15 series has no VDE certification. Suggested alternates, where applicable, have been suggested.

REASON FOR CHANGE:

Fuse holder H15 does not comply with VDE requirements, H15 is only available with UL certification.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

Fuse holder H15 has no change on the quality, reliability, and performance.

PARTS FAMILIES AFFECTED:

PN's affected and suggested replacements with VDE certification are listed below.

| Product Series | FG P/N | Replacement PN |
|----------------|--------------|----------------|
| H15 | BK-H15-V-1 | BK1-HTC-45M |
| H15 | BK1-H15-V-1 | BK1-HTC-45M |
| H15 | BK-H15-H-1 | BK1-HTC-50M |
| H15 | BK1-H15-H-1 | BK1-HTC-50M |
| H15 | BK-H15-V-1-K | BK1-HTC-45M |
| H15 | BK-H15-H-1-B | BK1-HTC-50M |

TIME SCHEDULE:

Immediately

SAMPLE AVAILABILITY:

Available upon request

ISSUED BY:

Roald Bai
Product Manager – Circuit Protection

CONTACT INFORMATION:

For questions or comments, please [Contact us](#)