



Product / Process Change Notification (PCN)

PCN ID#: 38

Title: Supplier Change

Change: Permanent

Honeywell Contact

Name: Dzul, Jorge

E-mail: Jorge.Dzul@Honeywell.com

Title: Sr Quality Engineer

Product Information

Affected parts and revisions:

BAF1-2RN-LH BAF1-2RN-RH BAF1-2RN2-LH 2LS111 DTF2-2RN-RH BAF1-2RN2-RH BZF1-2RN-RH DTF2-2RN-LH
BAF1-2RQ9-LH BAF1-2RQ9-RH BZF1-2RN-LH BAF1-3RNX1 BAF1-3CN18X1 BAF1-3CNX1 GKBA1L7 GKBA14L7
OP-AR30 EX-AR30 OPD-AR30 GKBC1L7 EXD-AR30-6 GKBA10L7 GKCA14M6-FW GKBA3L7 EXD-AR30-3
GKBA16L6 GKBA2LX GKBA16L7 GKBA14L6 GKBB14L6 EXH-AR33 GKBA1LX GSXA42C CLSXB9T-E GSXA42A1E
GSXA42A GSXA42B GSXC42A1E 301LS2 301LS8 5LS1 2LS1 5LS1-L 2LS1-L 205LS1 202LS1 9PA33 LSA1A LSJ1A-7A
LSA1A-2B LSXYAB3K LSXN3K LSV1A LS2D4K LSJ1A-7N LSB3K LSW1A LSH1A LSN3K LSXA3K LS2A4K BXA3K
BXA3K-1A LSZ3K LSA3K LSZ7R1A LSK3K-8C LSYAC3KQ-FP LSQYAB1A1T353 LSA3K4 LSYPB1A LSXJ3K-7A LSZ7A1A
LSF1A LSYAC3KP-FP LSYAB1A LSC1A BX2A3K LS4A3K-1B LS-85633 LSJ3K-7M LSXD3K LSXC3K LSK1A-8C LSXD4K
LSXA3K-1A LSP1A LSYCC3KP-FP LSZ3A LSB1A LSA1A-1A LSYAB3K LSYPB3K LSG1A BXD3K LSA1A-4M LSA1A1
LS2H3K LS2H4K LSE1A LSJ1A-7M LSJ5A-7N LSQYFC3K223 LSU1E LSU5A LSXB3K LSYRC3KP-FP LSYJC1A-7N
LSA1A-1B LS2A4KC LS4K1A-8A LSYWB1A LSYUB1A LS2YAB4K LSZ7J1A-7A LSYAC1E LSYFB1A LSP3K LSA1A-2A
BXC4K LSYAC1A LSQUC5K272 LSYDB3K BX4C3K LS2N3K LSD3K LSXA3K-2J BXQA3K358 LSYEC3KP-FP LSR1A
LSZ7D1A LSZ21A LSD1A LSQ053 LSQ054 LSQYUB3K339 LSN1A LSQAB3K173-1B LSXYPB3K LSYUB3K LSA5A
LSU1A LSXP3K3 LSZ7K1A-8A LSXYAB3K-1A LSP1E LSV3K LSZ7P5A LSP5A LSYCC3K LSA1A-1D LSJ3K-7A
LSXYBB3K LSYPC1A LSYJB3K-7M LSXP3K LSA3K-2C LSXA3K-2C LSH3K LSYAB3KQ-FP LSP3K3 LSXZ3K LSYHC3K
LS2E4K LS4A3K-2B BX4A3K-1A LSW3K LSF3K LSA9A LSA1A-2D LS4A1A LSYCB1A LSYJB1A-7M LSYJB1A-7A LSH1E
LSA1E LSC5A LSZ7B1A LSA1A3 LSYVB1A LSXH3K LSXF3K BX4A3K LSA1A2 LSYKC1A-8C LSZ7A5A LSYCC3K
LS3A3K-7AA LSYDC5AC LSYKB1A-8C LSXA4K LSYAC5A BX24A3K-1A LSQ037 LSA3K-1B BX4J3K-7A LS-85637
LSYBB3K BX4D3K BXC3K LSXA3K5-1A LSA1F LSYRC5KP-FP LSYAC5KP-FP LSYEC1A LSXE3K LSYJB3K-7A LS2A4KPC
LS4K1A-8C LSK1A-8A LSYAC3KPB-FP BXA3E LSYFC1A LSYUB1A13-2D LSA3K-1A LSYUC1A LSYPB3KP-FP
LSYKC1ADD-8C-C LSH9A7 LSYNC3KP-FP LSA8A LSG3K LS3A1A LSF3K5 BX24A3K LS4D1A LSXA3K5 LSH1A-2D
LSK3K-8A LSZ7H1A BXN3K LSYDC3KP-FP LSXV3K LSYDB1A LSA9A-2L BXA4K LSYUB1A3 LSYUB1A3-2D LSC3K
LSV1E LSQUC3K170 LSYAC5KQ-FP LS4A3K-7AA LSYUB1A13 LS4J1A-7M LSA1A2-2J LSYKB3K-8C BXA3K-2C
LSYJC1A-7A LSZ7C1A LSXR3K LSYCC3KQ-FP LSYCC1A LS4YAC1A LS2YEB4K LSQYUB3K319 LS4D3K LSA1E-1B
LSK1A LSQYAB3K340 LSXYNB3K LSYNB3K LSZ7J1A-7M CLSB4B CLSB4B-1 CLSXB4A-1 CLSXB4A CLSXB4T CLSB7A-
1 CLSXE4A-1 51ML94 51ML10-E1 151ML10 51ML10

Does the part number change? False

Type of Change:

Supplier- Manufacturer

Change Description:

Freeport awarded PJ Spring to supply the springs.

Reason for change:

Honeywell Freeport production site declares no more capacity to produce Springs

Justification for change:

Honeywell Freeport production site declares no more capacity to produce Springs

Product Identification to distinguish the change:

date code

Samples (If required): Not applicable

Change Implementation Date: 2022-05-27

Honeywell is committed to providing you with a superior level of customer service. Please e- mail to contact listed above for additional information regarding this communication.

G-AST-FRM-QA.2

EFFECTIVE DATE: 3-29-22

REVISION: 0